UNCLASSIFIED


AD NUMBER AD916695 **NEW LIMITATION CHANGE** TO Approved for public release, distribution unlimited **FROM** Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; Aug 1973. Other requests shall be referred to AFFDL[FBA], Wright-Patterson AFB, OH 45433. **AUTHORITY** AFFDL, 1tr, 28 May 1974

CORROSION FATIGUE CRACK GROWTH IN AIRCRAFT STRUCTURAL MATERIALS

L. R. Hall, R. W. Finger and W. F. Spurr

BOEING AEROSPACE COMPANY Seattle, Washington 98124

SEPTEMBER, 1973
FINAL TECHNICAL REPORT AFML-TR-73-204



DISTRIBUTION LIMITED TO U. S. GOVERNMENT AGENCIES AND DESIGNATED RECIPIENTS ONLY SINCE THIS REPORT CONCERNS THE TEST AND EVALUATION OF TECHNOLOGY DIRECTLY APPLICABLE TO MILITARY HARDWARE (AUGUST 1973). BESTON FOR AGENT TO THE CONTROL OF THIS DOCUMENT MUST BE REFERRED TO AFFOL (FBA), WPAFB, OH 46433.

AIR FORCE MATERIALS LABORATORY
AIR FORCE FLIGHT DYNAMICS LABORATORY
Air Force Systems Command
Wright-Patterson Air Force Base, Ohio

NOTICE

When Government drawings, specifications, or other data are used for any purpose other than in conection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

Copies of this report should not be returned unless return is required by security considurations, contractual obligations, or notice on a specific document.

AIR FORCE/56780/4 February 1974 - 200

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE	
	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER 2. GOVT ACCESSION AFML-TR-73-204	NO. 3. RECIPIENT'S CATALOG NUMBER
I. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVERED
CORROSION FATIGUE CRACK GROWTH	FINAL TECHNICAL REPORT
IN AIRCRAFT STRUCTURAL MATERIALS	JUNE 1971 THRU JUNE 1973
- AUTHOR(n)	B. CONTRACT OR GRANT NUMBER(#)
L. R. HALL, R. W. FINGER & W. F. SPURR	AF33615-71-C-1687
PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, Y.,SK AREA & WORK UNIT NUMBERS
BOEING AEROSPACE COMPANY	AREA & WORK DATE HOMBERS
SEATTLE, WASHINGTON 98124	
1. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
AIR FORCE MATERIALS LABORATORY	SEPTEMBER 1973
AIR FORCE FLIGHT DYNAMICS LABORATORY AIR FORCE SYSTEMS COMMAND	13. NUMBER OF PAGES
WRIGHT-PATTERSON AIR FORCE BASE, OHIO	re) 15. SECURITY CLASS, (of this report)
MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office)	
4. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office	LINCL ASSISTED
4. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office SAME	UNCLASSIFIED
SAME 5. DISTRIBUTION STATEMENT (of this Report) "DISTRIBUTION LIMITED TO U.S. GOVERNMENT AGENCIES AN SINCE THIS REPORT CONCERNS THE TEST AND EVALUATION	ID DESIGNATED RECIPIENTS ONLY OF TECHNOLOGY DIRECTLY APPLI-
SAME 6. DISTRIBUTION STATEMENT (of this Report) "DISTRIBUTION LIMITED TO U.S. GOVERNMENT AGENCIES AN	TSM. DECLASSIFICATION/DOWNGRADING SCHEDULE ND DESIGNATED RECIPIENTS ONLY OF TECHNOLOGY DIRECTLY APPLI-
SAME 5. DISTRIBUTION STATEMENT (of this Report) "DISTRIBUTION LIMITED TO U.S. GOVERNMENT AGENCIES AN SINCE THIS REPORT CONCERNS THE TEST AND EVALUATION CABLE TO MILITARY HARDWARE (AUGUST 1973). REQUESTED DISTRIBUTION OF THIS DOCUMENT MUST BE REFERRED TO A	TSM. DECLASSIFICATION/DOWNGRADING SCHEDULE ND DESIGNATED RECIPIENTS ONLY OF TECHNOLOGY DIRECTLY APPLI-

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

INVOLVED FIVE ALLOYS AND SEVEN TEST MEDIA.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

(CONTINUED ON NEXT PAGE)

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

BLOCK 20 - ABSTRACT (CONTINUED)

THE FOUR PRINCIPAL ALLOYS WERE: 7075-T651 ALUMINUM, 6A1-4V(ELI) BETA ANNEALED (&A) TITANIUM, 6AI-4V RECRYSTALLIZE ANNEALED (RA) TITANIUM, AND 9Ni-4Co-0.3C STEEL (220-240 ksi); IN ADDITION THE 7475-T651 ALLOY WAS SUB-JECTED TO A LIMITED NUMBER OF TESTS. ALL ALLOYS WERE TESTED IN THE FORM OF HOT ROLLED PLATE. TEST MEDIA INCLUDED: DESICCATED AIR, WATER SATURATED JP-4 FUEL, DISTILLED WATER, 3.5% NaCI SOLUTION, SUMP TANK WATER, ALTERNATING JP-4 FUEL AND DISTILLED WATER, AND DYE PENETRANT (TYPE ZL-2A). MOST TESTS WERE CONDUCTED AT 72F WITH A FEW TESTS BEING PERFORMED AT +175F AND -65F. DOUBLE CANTILEVER BEAM SPECIMENS WERE USED FOR ALL TESTS WITH THE EXCEP-TION OF A LIMITED NUMBER OF SURFACE-FLAWED SPECIMEN TESTS. CORROSION FATIGUE TESTS WERE CONDUCTED USING TWO CYCLIC FREQUENCIES (6 AND 60 cpm) AND THREE RATIOS OF MINIMUM TO MAXIMUM STRESS (0.1, 0.5 AND 0.8). OVERLOAD EFFECTS WERE INVESTIGATED BY TESTING 7075-T651 ALUMINUM, TI-6AI-4V AND TI-6AI-4V RA TAPERED DOUBLE CANTILEVER BEAM SPECIMENS IN BOTH DESICCATED AIR AND 3.6% NaCI SOLUTION. FINALLY, A SERIES OF TESTS WAS UNDERTAKEN TO EVALUATE THE EFFECTS ON SCC AND CORROSION FATIGUE CRACKING OF VARIATIONS IN METALLURGICAL CHARACTERISTICS IMPARTED TO TI-6AI-4V RA ALLOY PLATE BY VARIOUS THERMAL CYCLES.

FOREWORD

This report describes an investigation of corrosion fatigue crack growth in airframe structural materials performed by the Boeing Aerospace Company from 1 June 1971 through 30 June 1973 under Air Force Contract F33615-71-C-1687.

From 1 June 1971 through October 1972 the work was sponsored by the Air Force Materials Laboratory (AFML) with Mr. K. D. Shimmin as project engineer. Subsequent to October 1972, the effort was sponsored by the Advanced Metallic Structures - Advanced Development Program Office (AMS-ADPO), Air Force Flight Dynamics Laboratory (AFFDL), under the joint management and technical direction of AFFDL and AFML with Mr. N. G. Tupper as project engineer.

This program was conducted by the Research and Engineering Division of the Boeing Aerospace Company, Seattle, Washington under the supervision of H. W. Klopfenstein, Structures Research and Development Manager. The Program Leader was J. N. Masters, Supervisor, Failure Mechanisms Group. Technical Leader was L. R. Hall and program support was provided by R. W. Finger, test design and coordination, W. F. Spurr, metallurgical investigations, A. A. Ottlyk, test engineering, and D. G. Good, technical illustrations and art work.

This report was submitted by the authors on June 25, 1973.

This technical report has been reviewed and is approved.

Vincent J. Russo

Chief, NDT and Mechanics Branch Metals and Ceramics Division

Air Force Materials Laboratory

John C. Frishett, Major, USAF

John Frank &

Program Manager, AMS Program Office

Structures Division

Air Force Flight Dynamics Laboratory

TABLE OF CONTENTS

				Page
SUM	IARY			1
1.0	INTE	ODUCTIO	ON	5
2.0	MATE	RIALS A	AND PROCEDURES	9
	2.1	Materi	als	9
		2.1.1	Aluminum 7075-T651	9
		2.1.2	Aluminum 7475-T651	1.5
		2.1.3	Titanium 6A1-4V Beta Annealed	. 18
		2.1.4	Titanium 6A1-4V Recrystallize Annealed	25
	•	2.1.5	Steel Alloy 9Ni-4Co-0.3C	32
	2.2	Select	ion of Environments	38
	2.3	Proced	lures	43
		2.3.1	Specimen Preparation	43
		2.3.2	Testing	45
		2.3.3	Evaluation of Results	49
		2.3.4	Comments on Procedures	53
3.0	RESU	LTS AND	DISCUSSION	57
	3.1	Alumin	um Alloy Test Results	57
		3.1.1	Stress Corrosion Cracking Tests	57
		3.1.2	Corrosion Fatigue Tests	65
			3.1.2.1 Effect of Test Environment	65
•			3.1.2.2 Effect of Cyclic Frequency	72
			3.1.2.3 Effect of Specimen Type	83
		3.1.3	Aluminum Alloy 7475-T651 Results	85
			3.1.3.1 Stress Corrosion Cracking Tests	85
			3.1.3.2 Corrosion Fatigue Tests	85
	3.2	Titani	um Alloy 6A1-4V Beta Annealed Results	88
		3.2.1	Stress Corrosion Cracking Tests	88
		3.2.2	Corrosion Fatigue Tests	90
			3.2.2.1 Effect of Test Environment	92
			3.2.2.2 Effect of Cyclic Frequency	104
			3.2.2.3 Effect of Specimen Type	104
			3.2.2.4 Tests of Low 0, (Super ELI) Material	110

TABLE OF CONTENTS (Cont.)

		lage
3.3 Titanium Allo	y 6Al-4V Recrystallize Annealed	112
3.3.1 Stress	Corrosion Cracking Tests	112
3.3.2 Corros	ion Fatigue Tests	112
3,3,2.	1 Effect of Test Environment	115
3.3.2.	2 Effect of Cyclic Frequency	126
3.3.2.	3 Specimen Configuration Effect	126
3.3.2.	4 Crack Closure Measurements	132
3.3.2	5 Thermal Processing Effects	142
3.4 Steel Alloy T	est Results	1.58
3.4.1 Stress	Corresion Cracking Tests	158
3.4.2 Corros	ion Fatigue Tests	162
3.4.2.	.1 Effect of Test Media and	162
	Cyclic Frequency	
3.5 Overload Effe	ect Tests	166
3.5.1 Test I	rocedures	166
3.5.2 Method	is for Evaluating Results	168
3.5.3 Result	ts and Discussion	170
3.5.4 Summa:	ry	178
3.6 Stress Ratio	Effects	179
4.0 OBSERVATIONS AND C	ONCLUSIONS	187
4.1 Observations		187
4.2 Conclusions		191
REFERENCES		193
APPENDIX A - Test Data		1.95
APPENDIX B - Test Spec	imens	241
	e Measurements For Double Cantilever	251
Beam Spec		
·	graphic Texture Measured By X-Rey	257
Pole Figu	res	

LIST OF TABLES

No.	<u>Title</u>	Page
1	Test Program	6
2	Chemical Composition of Aluminum Alloy	11
3	Summary of Fracture Toughness Data for Plate Allovs	16
4	Mechanical Property Data for 7475-T651 Aluminum	19
	Alloy One Inch Thick Plate	
5	Fracture Toughness (K _{Ic}) Data for 7475-T651	19
	Aluminum Alloy One Inch Thick Plate	
6	Chemical Composition of Titanium Alloys	20
7	Quantitative Texture Factors for Titanium Alloys	23
8	Chemical Composition of 9Ni-4Co-0.3C Steel (220-	36
	240 Ksi)	
9	Chemical Content of Simulated Sump Tank Residue	39
	Water	
10	Test Program for 7075-T651 Aluminum	58
11	Test Program for Ti-6Al-4V Beta Annealed	89
12	SCC Test Results for Ti-6A1-4V Beta Annealed	91
	Plate (WR Direction)	
13	Test Program for Ti-6Al-4V Recrystallize	113
	Annealed	
14	SCC Test Results for Ti-6A1-4V Recrystallize	114
	Annealed Plate (WR Direction)	
15	Quantitative Texture Factors and Moduli for	151
	Ti-6A1-4V Alloy Subjected to Various Thermal	
	Cycles	
16	Mechanical Property Test Results at 72F for	151
	Ti-6Al-4V Plate Subjected to Various Thermal	
	Cycles	
17	Fracture Toughness Test Results for Ti-6A1-4V	153
	Subjected to Various Thermal Cycles (WR Orienta-	
	tion and CT specimens)	
18	SCC Test Results in 72F/3.5% NaCl Solution for	153
	Ti-6A1-4V Subjected to Various Thermal Cycles	

LIST OF TABLES (CONT'D)

No.	<u>Title</u>	Page
19	Test Program for 9Ni-4Co-0.3C (240 ksi) Steel	٠
-	Alloy Plate	
20	Overload Effects Test Program	
21	Results of Overload Effect Tests on 6Al-4V ELI	
	Beta Annealed Titanium Alloy Plate	
22	Results of Overload Effect Tests on 6A1-4V	
	Recrystallize Annealed Titanium Alloy Plate	
23	Results of Overload Effect Test on 7075-T651	
	Aluminum Alloy Plate	
24	Summary of Stress Ratio Effects Resulting from	
	6 CPM Tests	

LIST OF FIGURES

No.	<u>Title</u>	Page
1	7075-T651 Aluminum Alloy Microstructure Composite	12
	(200X, Kellers Etch)	
2	Mechanical Properties for 7075-T651 Aluminum Alloy	13
	Plate (0.625-Inch Thick)	
3	Fracture Toughness Data for All Test Alloys (CT	14
	Specimens)	
4	7475-T651 Aluminum Alloy Microstructure Composite	17
	(200X, Kellers Etch)	
5	6A1-4V Standard ELI Beta Annealed Titanium Alloy	21
	Microstructure Composite (500X)	
6 .	Pole Figure for 6A1-4V Standard ELI Beta Annealed	22
	Titanium Alloy - Basal Plane $(0002)_{\alpha}$	
7	Mechanical Properties for 6A1-4# Standard ELI Beta	24
	Annealed Titanium Alloy Plate (1.0-Inch Thick)	
8	6A1-4V "Super ELI" (02 Content 0.06) Beta Annealed	26
	Titanium Alloy Microstructure Composite (500X)	
9	Pole Figure for 6A1-4V "Super ELI" (02 Content	27
	0.06) Beta Annealed Titanium Alloy - Basal Plane	
	(0002) _a	
10	6A1-4V Recrystallize Annealed Titanium Alloy	29
	Microstructure (500X)	
1.1	Pole Figure for 6A1-4V Recrystallize Annealed	30
	Titanium Alloy - Basal Planes $(0002)_{\alpha}$	
12	Mechanical Properties for 6A1-4V Recrystallize	31
	Annealed Titanium Alloy Plate (1.0-Inch Thick)	
13	9Ni-4Co-0.3C Steel Alloy Microstructure Composite	33
	(500X)	
14	Banding in 9Ni-4Co-0.3C Steel Alloy (200X)	34
15	Banding in 9Ni-4Co-0.3C Steel Alloy at High Magn-	34
	ification (1200X)	
16	Mechanical Properties for 9Ni-4Co-0.3C Steel Alloy	37
	Place (0.625-Inch Thick)	

No.	<u>Title</u>	Page
17	Schematic Representation of Possible Effects of	41
	Mixing Environments A and B on Stress Corrosion	
	Properties of an Alloy	
18 .	Velocity of Stress Corrosion Cracks in a High Strength	42
	Aluminum Alloy as a Function of Water Content in	
	Methanol	
19	SCC Test Specimens for 7075-T651 Aluminum and 9Ni-4Co-	47
•	0.3C Steel Alloys	
20	SCC Test Specimen and Loading Method for 6A1-4V	48
	Titanium Alloys	
2.1	Shape Parameter Curves for Surface and Internal Flaws	51
22	Estimated Elastic Stress Intensity Magnification	52
	Factors at Maximum Crack Depth for Surface Cracks in	
	Tension (Reference 4)	
23	Stress Corrosion Cracking Velocity Data for 7075-T651	60
	Aluminum Alloy	
24	SCC Test Results for 7075-T651 Aluminum Alloy, Crack	62
	Surface Sprayed with LPS-3 Prior to Immersion in Test	
	Media	
25	SCC Test Results for 7075-T651 Aluminum Alloy Crack	63
	Surface Sprayed with LPS-3 and Dried for 3.0 Hours	
	Prior to Immersion in Test Media	
26	Illustration of Fracture Face from 7075-T651 Aluminum	64
	Alloy Surface Flaw Specimen SCC Test in 3.5% NaCl	
	Solution	
27	Effect of Environment on Fatigue Crack Growth Rates	66
	at R=0.1 in 7075-T651 Aluminum Alloy (60 CPM)	
28	Effect of Environment on Fatigue Crack Growth Rates	67
	at R=0.5 in 7075-T651 Aluminum Alloy (60 CPM)	
29	Effect of Environment on Fatigue Crack Growth Rates	68
	at 6 CDM to 7075_T651 Aluminum Allow	

No.	<u>Title</u>	Page
30	Fatigue Crack Growth Rates for 7075-T651 Aluminum	7 0
	Alloy in Alternating JP-4 Fuel and Distilled Water	
	(60 CPM)	
31	Fatigue Crack Growth Rates for 7075-T651 Aluminum	71
	Alloy in Alternating JP-4 Fuel and Distilled Water	
	(6 and 60 CPM)	
32	Fatigue Crack Growth Rates for 7075-T651 Aluminum	73
	Alloy in Distilled Water, Crack Surface Sprayed with	
	LPS-3 and Dried for 3.0 Hours Prior to Immersion in	
	Test Media (60 CPM)	
33	Fatigue Crack Growth Rates for 7075-T651 Aluminum	74
	Alloy in Dye Penetrant (60 CPM)	
34	Fatigue Crack Growth Rates for 7075-T651 Aluminum	7 5
	Alloy in Dye Penetrant' (6 CPM)	
35	Fatigue Crack Growth Rates for 7075-T651 Aluminum	76
	Alloy at $-65F$ and $+175F$ in Desiccated Air and 3.5%	
	NaCl Solution (6C CPM)	
36	Fatigue Crack Growth Rates for 7075-T651 Aluminum	77
	Alloy at 175F in JP-4 Fuel and Distilled Water	
	(60 CPM)	
37	Fatigue Crack Growth Rates for 7075-T651 Aluminum	78
	Alloy in Desiccated Air (6 CPM)	
38	Fatigue Crack Growth Rates for 7075-T651 Aluminum	79
	Alloy in Distilled Water (6 CPM)	
39	Fatigue Crack Growth Rates for 7075-T651 Aluminum	80
	Alloy in 3.5% NaCl Solution (6 CPM)	
40	Fatigue Crack Growth Rates for 7075-T651 Aluminum	81
	Alloy in Water Saturated JP-4 Fuel (6 CPM)	
41	Fatigue Crack Growth Rates for 7075-T651 Aluminum	82
	Alloy in Sump Tank Water (6 CPM)	
42	Fatigue Crack Growth Rate Data for 7075-T651 Aluminum	84
	Alloy Surface Flawed Specimen (60 CPM)	

No.	<u>Title</u>	Page
43	Stress Corrosion Cracking Velocity Data for 7475-T651	86
	Aluminum Alloy	
44	Fatigue Crack Growth Rates for 7475-T651 Aluminum Alloy	87
	in Desiccated Air and 3.5% NaCl Solution (60 CPM)	
45	Effect of Environment on Fatigue Crack Growth Rates at	93
	R=0.1 for 6A1-4V Standard ELI Beta Annealed Titanium	
	Alloy (60 CPM)	
46	Effect of Environment on Fatigue Crack Growth Rates at	94
	R=0.50 in 6A1-4V Standard ELI Beta Annealed Titanium	
	Alloy (60 CPM)	
47	Effect of Environment on Fatigue Crack Growth Rates at	95
	R=0.80 in 6A1-4V Titanium Alloy (60 CPM)	
48	Effect of Environment on Fatigue Crack Growth Rates at	96
	R=0.10 in 6A1-4V Standard ELI Beta Annealed Titanium	
	Alloy (6 CPM)	
49	Effect of Environment on Fatigue Crack Growth Rates at	97
	R=0.50 in 6A1-4V Standard ELI Beta Annealed Titanium	
	Alloy (6 CPM)	
50	Fatigue Crack Growth Rates for 6Al-4V Standard ELI	98
	Beta Annealed Titanium Alloy at R=0.5 in Alternating	
	JP-4 Fuel and Distilled Water (60 CPM)	
51	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	99
	Beta Annealed Titanium Alloy at R=0.1 in Alternating	
	JP-4 Fuel and Distilled Water (60 CPM)	
52	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	101
	Beta Annealed Titanium Alloy in Dye Penetrant (6 CPM)	
53	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	102
	Beta Annealed Titanium in Distilled Water, Crack	
	Surface Sprayed with LPS-3 and Dried 3.0 Hours Prior	
	to Immersion in Test Media (60 CPM)	
54	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	103
	Beta Annealed Titanium Alloy at -65F and 175F (60 CPM)	

No.	<u>Title</u>	Page
55	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	105
	Beta Annealed Titanium Alloy in Desiccated Air (6 CPM)	
56	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	106
	Beta Annealed Titanium Alloy in Distilled Water (6 CPM)	
57	Fatigue Crack Growth Rates for 6A1-4V Standard ELI	107
	Beta Annealed Titanium Alloy in Water Saturated JP-4	
	Fuel (6 CPM)	
58	Fatigue Crack Growth Rates for 6A1-4V Standard ELI Beta	108
	Annealed Titanium Alloy in 3.5% NaCl Solution (6 CPM)	
59	Fatigue Crack Growth Rates for "Super Eli" 6A1-4V Beta	109
	Annealed Titanium Alloy in 3.5% NaCl Solution (60 CPM)	
60	Fatigue Crack Growth Rates for 6A1-4V Standard ELI Beta	111
	Annealed Titanium Alloy Surface Flawed Specimen (60 CPM)	
61	Effect of Environment on Fatigue Crack Growth Rates at	116
	R=0.1 for 6A1-4V Recrystallize Annealed Titanium Alloy	
	(60 CPM)	
62	Effect of Environment on Fatigue Crack Growth Rates at	117
	R=0.5 for 6A1-4V Recrystallize Annealed Titanium Alloy	
	(60 CPM)	
63	Effect of Environment on Fatigue Crack Growth Rates at	118
	R=0.80 for 6Al-4V Recrystallize Annealed Titanium	
	Alloy (60 CPM)	
64	Effect of Environment on Fatigue Crack Growth Rates at	119
	R=0.10 for 6A1-4V Recrystallize Annealed Titanium	
	Alloy (6 CPM)	
65	Effect of Environment on Fatigue Crack Growth Rates at	120
	R=0.50 for 6A1-4V Recrystallize Annealed Titanium Alloy	
	(6 CPM)	
66	Fatigue Crack Growth Rates for Recrystallize 6A1-4V	121
	Annealed Titanium Alloy in Alternating JP-4 Fuel and	
	Distilled Water (60 CPM)	

No.	<u>Title</u>	Page
67	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	123
	Annealed Titanium Alloy in Dye Penetrant (60 CFM)	
68	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	124
	Annealed Titanium Alloy in Distilled Water, Crack	
	Sufaces Sprayed with LPS-3 and Dried 3.0 Hours Prior	
	to Immersion in Test Media (60 CPM)	
69	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	125
	Annealed Titanium Alloy at -65F and 175F (60 CPM)	
70	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	127
	Annealed Titanium Alloy in Desiccated Air (6 CPM)	
71	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	128
	Annealed Titanium Alloy in Water Saturated JP-4 Fuel	
	(6 CPM)	
72	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	129
	Annealed Titanium Alloy in Distilled Water (6 CPM)	
73	Fatigue Crack Growth Rates for 6Al-4V Recrystallize	130
	Annealed Titanium Alloy in 3.5% NaCl Solution (6 CPM)	
74	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	131
	Annealed Titanium Alloy in Sump Tank Water (6 CPM)	
75	Fatigue Crack Growth Rates for 6A1-4V Recrystallize	133
	Annealed Titanium Allov (obtained using NAR Specimen	
	Design) (60 CPM)	
76	Fatigue Crack Growth Rate Date for 6A1-4V Recrystallize	134
	Annealed Titanium Alloy Surface Flawed Specimen (60 CPM)	
77	Clip Gage Location for Crack Closure Measurements	135
78	Loading Program Used for Crack Closure Measurements	137
79	Effect of Measurement Location on Apparent Stress	137
	Intensity Factor at Onset of Crack Closure	
80	Examples of Crack Displacement vs Load Recording	138
	Obtained During Crack Closure Measurements	
81	Effect of Peak Cyclic Stress Intensity Factor on Stress	140
	Intensity Factor at the Onset Crack Closure	

No.	<u>Title</u>	Page
82	Effect of Crack Length and Load Increase on Stress	141
	Intensity Factor at Which Crack Closure Occurs	
83	Cutting Diagram and Microstructural Variation for	145
	Thermally Cycled 6A%-4V Recrystallize Annealed	
	Titanium Alloy Plates	
84	Equiaxed Alpha-Beta Microstructure of Ti-6A1-4V	147
	Specimen 55K+1	
85	Basketweave Microstructure of Ti-6Al-4V Specimen	147
	44K-1	
86	Microstructure of Fracture Toughness Specimen 66K-1	148
).	Showing Both the Equiaxed Alpha and Basketweave Grain	
	Morphologies.	
87	Basal Plane Pole Figure for Equiaxed Alpha-Beta	149
	Microstructure Resulting from Cyclic Heat Treatment	
	of Plate 44	
88	Basal Plane Pole Figure for Basketweave Microstructure	150
	Resulting from Cyclic Heat Treatment of Plate 44	
89	Fracture Surface of Stress Corrosion Specimen from	154
	Plate 33	
90	Corrosion Fatigue Crack Growth Rates for Thermal	156
	Processing Effects Tests	
91	Stress Corrosion Cracking Velocity Data for 9Ni-	160
	4Co-0.3C Steel Alloy	
92	Envelopes of Average Crack Growth Rate Data for 9Ni-	163
	4Co-0.3C Steel Alloy Plate in Six Environments	
93	Effect of Environment on Fatigue Crack Growth Rates	164
	at R=0.10 for 9Ni-4Co-0.3C Steel Alloy Plate (6 CPM)	
94	Effect of Environment on Fatigue Crack Growth Rates	165
	at R=0.5 for 9Ni-4Co-0.3C Steel Alloy Plate (6 CPM)	
95	Example of Test Records Obtained from Overload Tests	169
96	Effect of Overload Ratio on Delay Cycles for Titanium	174
	Alloy Overload Tests	

No.	<u>Title</u>	Page
97	Effect of Peak Overload Stress Intensity Factor on	177
	Change in Cyclic Life	
98	Effect of Stress Ratio on Corrosion Fatigue Crack	180
	Growth Rate Behavior of Aluminum and Steel Alloy at	
	at 60 CPM	
99	Effect of Stress Ratio on Corrosion Fatigue Crack	181
	Growth Rate Behavior of Titanium Alloys at 60 CPM	
100	Effect of Stress Ratio on Fatigue Crack Growth Rates	182
	for Steel and Titanium Alloys in Desiccated Air	
101	Effect of Cyclic Frequency on Stress Ratio Effects in	184
	Titanium and Steel Alloys.	•

SUMMARY

This program was directed to a study of some of the factors affecting the growth of crack-like defects in aircraft structural materials. The objective was to study the characteristics of and the influence of metallurgical factors on corrosion fatigue crack growth in high strength metal alloys. Mechanical property, fracture toughness, stress corrosion cracking, and corrosion fatigue tests were conducted for five alloys in seven different environments. The four principal alloys included: 7075-T651 aluminum, 6A1-4V (ELI) beta annealed titanium, 6A1-4V recrystallize annealed (RA) titanium, and 9Ni-4Co-0.3C (220-240 ksi) steel, all in plate form. A limited number of tests were conducted on 7475-T651 aluminum alloy plate. Test environments included: desiccated air, distilled water, 3.5% NaCl solution, water saturated JP-4 fuel, sump tank water, alternating JP-4 fuel/distilled water, and dye penetrant. Most tests were conducted at 72F with a few tests being performed at +175F and -65F to evaluate the effects of temperature on material behavior. Double cantilever beam specimens were used for most stress corrosion cracking and corrosion fatigue tests; specimen thickness was sufficient to generate plane strain crack tip deformations. A limited number of surface-flawed specimens were tested for comparison. The majority of tests were undertaken to evaluate basic crack growth rates using cyclic frequencies of 6 and 60 cpm and ratios of minimum/maximum cyclic stress (R) of 0.1, 0.5, and 0.8. The effect of overloads on subsequent fatigue crack growth behavior was investigated by testing 7075-T651 aluminum, 6A1-4V (ELI) beta-annealed titanium and 6A1-4V RA titanium alloy tapered double cantilever beam specimens in both desiccated air and 3.5% NaCl solution. Finally, a series of tests was undertaken to evaluate the effect of both grain size and cooling rate on the crack growth resistance properties of Ti-6A1-4V RA plate.

A large body of crack growth rate data was generated in this program. These data are included in Appendix A to this report. The testing of double cantilever beam (DCB) specimens proved to be a very good method of generating large amounts of data. However, the DCB specimen is not suitable for testing the thickness direction of plate materials and hence, DCB specimen data are not always applicable to many practical cracking situations in airframe components

such as surface flaws and fastener hole flaws. The applicability of the DCB data to these problems must be checked by testing surface flawed or fastener hole flaw specimens.

A number of observations were made with respect to variations in resistance to stress corrosion and corrosion fatigue cracking among the alloys tested. For the Ti-6Al-4V alloy, beta annealing led to superior stress corrosion cracking and corrosion fatigue crack growth resistance than did recrystallize annealing. The 9Ni-4Co-0.3C steel alloy plate heat treated to the 240 ksi strength level was found to be very susceptible to stress corrosion cracking in aqueous environment. The 7475-T651 aluminum alloy plate had superior fracture toughness to the 7075-T651 aluminum alloy plate for the WR direction that was tested. Fatigue crack growth rates for the two aluminum alloys in 3.5% NaCl solution did not differ greatly.

A summary of some of the observations made during this program follows:

- The relative effects of potential models of the "worst" normal operating environment for airframe components, namely, 3.5% NaCl solution and sump tank water, was dependent on alloy.
- Changes in temperature from -65F to +175F had little or no effect on corrosion fatigue crack growth rates for the alloy/environment couples tested in this program.
- Spraying the crack surfaces of test specimens with the corrosion inhibitive compound LPS-3 prior to test had no significant effect on stress corrosion cracking and corrosion fatigue crack growth resistance.
- The effect of change in frequency from 60 to 6 cpm on corrosion fatigue crack growth rates was dependent on alloy/environment couple.
- The rate of increase of fatigue crack growth rates with increase in stress ratio varied considerably from one material/environment couple to another. In general, stress ratio effects were largest in material/environment combinations that were susceptible to SCC.

• Overloads increased cyclic life up to overload to fracture stress ratios of 0.9. For ratios greater than 0.9, the beneficial effect of crack growth rate retardation was more than offset by crack growth that occurred during the overload.

1.0 INTRODUCTION

Recent failures in first line military aircraft have demonstrated the need for additional and new design methods for airframe components. Some of the failures have been of the catastrophic variety and originated at crack-like defects that were previously undetected during production or in-service inspections. Since all aircraft structures contain defects that are either inherent in the materials or are introduced during production or service, it became evident that new design methods and criteria were required to minimize the detrimental effects of such defects.

In recent years, methods (1)* based on fracture mechanics have been successfully applied to the design of fracture resistant spacecraft and booster tanks. Hence, attempts were initiated to extend existing design methods to make them applicable to the complex geometries, environments, and loadings encountered during the operation of military aircraft. Specifically, design procedures are required to insure that the largest crack-like defect that would reasonably be expected to exist at the outset of service will not grow sufficiently to initiate a failure that could result in loss of aircraft. The design procedures require methods of: establishing the maximum possible initial defect size that could be expected to exist throughout the life of the structure; determining the critical defect sizes, i.e., sizes that would result in component failures; and calculating the number of aircraft missions that could grow the initial crack-like defect to critical sizes.

This program was directed to a study of some of the factors affecting the growth of crack-like defects in aircraft structural materials. The objective was to obtain information on load history and environmental effects and their interaction with metallurgical factors, on subcritical crack growth in high strength metal alloys. A summary of the overall test program is included in Table 1. Mechanical property, fracture toughness, stress corrosion cracking, and corrosion fatigue tests were conducted for five alloys in seven different environments. The four principal alloys (all in plate form) included: 7075-T651 aluminum, 6A1-4V (ELI) beta annealed titanium, 6A1-4V recrystallize

^{*} Number in parenthese refer to references at end of report.

Table 1: Test Program

		٨:									Time I	Ž	ENVIRONMENT	MEN	1_	1						
3	E SIWEN	ONENC IC		₹	AIR	\$ □	DISTILI	DISTILLED 3.5% NaCI	8 8	3.5% NaCi SOLUTION	Ω ON ON		₽		S F	SUMP		F 4	JP-4+H20	9.	DYE PEN	PE
TEST	SPEC	CACI	aara ITAR	499-	72F	135F 139-	72F	136F	199-	725	196F	∃99-	725	136F	199-	72F	135F	199-	72F	1921	499-	12F
MECHANICAL PROPERTY	TENS.	-	ı	- ^	×	×	ļ.	<u>L</u>		_	_		<u> </u>		T	T		T .	 -	<u> </u>	+	-
FRACTURE TOUGHNESS	כד SF	ı	ı	××	××	××																
STRESS CORROSION CRACKING	DCB SF	ı	-		××		××		ļ	××			×			××			×			
	820	09	0.1 0.5 0.8	×	××	×	×××	×		×××	×		××	×		××			×		-	. ×
CORROSION FATIGUE	DCB	9	0.1	~ ^	××		××			××			××			××					×	
	SF	99	0.5	^	×					×												
OVERLOAD	тосв	09	0.5		×		`			×			•		 							

X INDICATES CONDITIONS FOR WHICH TEST'S WERE CONDUCTED

amnealed (RA) titanium, and 9Ni-4Co-0.3C (220-240 ksi) steel. A limited number of tests were conducted on 7475-T651 aluminum alloy plate. Test environments included: desiccated air, distilled water, 3.5% NaCl solution, water saturated JP-4 fuel, sump tank water, alternating JF-4 fuel/distilled water, and dye penetrant (type Z1-2A). Most tests were conducted at 72F with a few tests being performed at +175F and -65F to evaluate the effects of temperature on material behavior. Double cantilever beam specimens were used for most stress corrosion cracking and corrosion fatigue tests; specimen thickness was sufficient to generate plane strain crack tip deformations. A limited number of surfaceflawed specimens were tested for comparison. The majority of tests were undertaken to evaluate basic crack growth rates using cyclic frequencies of 6 and 60 cpm and ratios of minimum/maximum cyclic stress (R) of 0.1, 05., and 0.8. The effect of overloads on subsequent fatigue crack growth behavior was investigated by testing 7075-T651 aluminum, 6A1-4V (ELI) beta-annealed titanium and 6A1-4V RA titanium alloy tapered double cantilever beam specimens in both desiccated air and 3.5% NaCl solution. Finally, a series of tests was undertaken to evaluate the effect of both grain size and cooling rate on the crack growth resistance properties of Ti-6A1-4V RA plate.

2.0 MATERIALS AND PROCEDURES

Test materials and procedures are described in detail in this section. Results of mechanical property and metallurgical characterization tests of all test materials are described in Section 3.1. Bases for selection of test environments are discussed in Section 3.2, and procedures used for specimen preparation, testing and evaluation of results are included in Section 3.3.

2.1 Materials

Six different alloys were tested in this program. The four primary allows were aluminum 7075-T651, steel 9Ni-4Co-0.3C, Ti-6Al-4V beta annealed, and Ti-6Al-4V recrystallize annealed (alpha-beta processed). The aluminum alloy 7475-T651 and "super ELI" Ti-6Al-4V were also tested to evaluate the effects of improved purity of composition. Various thermal cycles were applied to the Ti-6Al-4V recrystallize annealed (RA) material to assess the effects of microstructural changes on corrosion fatigue properties.

Each test material was characterized for mechanical properties, composition, microstructure and macrostructure. In addition, conductivity, hardness, and exfoliation corrosion testing were conducted for the aluminum alloys. The steel alloy, 9Ni-4Co-3.0C, was evaluated for inclusion content and alloy segregation. Crystallographic texture was determined for each titanium plate evaluated.

The material characterization data generated for the test materials of this program were evaluated and compared to other data for each alloy so that each test material could be rated against other material of the same alloy designation

2.1.1 Aluminum 7075-T651

The aluminum alloy, 7075 was procured from ALCOA in plate form, $0.625 \times 48 \times 72$ inches per specification QQ-A-250/12d in the T651 condition. The alloy was selected for study since it is commonly used in existing aircraft structure

and no systematic study had been conducted on its corrosion fatigue characteristics, particularly for plane strain conditions.

The composition of the 7075-T651 plate as determined by Boeing is included in Table 2. "Wet" analytical techniques were utilized for each element. The test results indicate that the heat chemistry is representative of a typical 7075 composition.

The microstructure (Figure 1) and macrostructure were typical of 0.625 inch thick 7075-T651 plate. Plate hardness of 90.6 (Rockwell B) and conductivity of 31.6 (% IACS) also represented typical values.

The plate was characterized for exfoliation corrosion by the "Total Immersion Exfoliation Corrosion Test" (ASTM Task Group GO1.05.02-T.6.8). The exfoliation characteristics were normal.

Mechanical properties were measured by The Boeing Company at temperatures of -65F, 72F and 175F. Detailed results are listed in Table A2 in Appendix A and are plotted against test temperature in Figure 2. The scatter bands in the upper part of Figure 2 enclose the ultimate strength and yield strength data. All mechanical properties are typical of 7075 alloy plate in the T651 condition.

Fracture toughness values were measured by The Boeing Company at temperatures of -65F, 72F, and 175F. Results are tabulated in Tables A3 and A4 in Appendix A and are plotted against test temperature in Figure 3. Fracture toughness values for the WR direction were measured using both compact tension and double cantilever beam specimens. Specimen configurations are detailed in Figures B2 and B10 in Appendix B. The compact tension data plotted in Figure 3 are typical of the 7075 aluminum alloy with the average value of $K_{\rm IC}$ at 72F being 22.7 ksi $\sqrt{\rm in}$. Double cantilever beam specimens were tested only at 72F and yielded average $K_{\rm IC}$ values of 22.2 ksi $\sqrt{\rm in}$ for the WR direction and 31.7 ksi $\sqrt{\rm in}$ for the RW direction.

Six surface-flawed specimens were tested to measure fracture toughness at +175, +72, and -65F. The crack plan was parallel to the rolling direction in all

Table 2: Chemical Composition of Aluminum Alloys

The second of th

MATERIAL	HEAT LOT	TEST LAB	ίλ	F.	Cu	Min	₩	ర	υZ	ï
7075-1651	T713-143 SPEC 1	.143 SPEC LIMITS	0.46 MAX	0.50 MAX	1.2-2.0	0.30 MAX	2.1-2.9 0.18	0.18- 0.35	5.1-6.1	0.20 MAX
		BOEING	0.07	0.23	1.55	90.0	2.15	0.20	5.52	0.03
7475.T651	\$295610 SPEC1	SPEC LIMITS	0.10 MAX	0.12 MAX	1.2-1.9	0.06 MAX	1.9-2.6	0.18	5.2-6.2	0.06
		ALCOA	0.05	0.06	1.51	0.01	2.36	0.19	5.57	0.03
		BOEING	0.05	0.10	1.60	0.06	2.15	0.20	5.48	0.03




Figure 1: 7075-T651 Aluminum Alloy Microstructure Composite (200X, Kellers Etch)




Figure 2: Mechanical Properties for 7075-T651 Aluminum Alloy Plate (0.625-Inch-Thick)




Figure 3: Fracture Toughness Data for All Test Alloys (CT Specimens)

specimens and two tests were conducted at each temperature. Results are summarized in Table 3. Detailed test data are included in Table A4 in Appendix A. For all specimens, records of crack displacement versus load showed that marked pop-ins occurred at loads less than the failure load. Previous testing has shown that pop-ins in 7075-T651 surface flawed specimens are common and result from bursts of crack growth in the laterial direction. Little or no growth occurs in the depthwise direction. This behavior is indicative of a higher resistance to crack propagation in the depthwise (WT) direction than in the laterial (WR) direction for the 7075-T651 plate material. Such behavior makes it difficult to calculate a value of stress intensity factor that equals the fracture toughness for a given direction of crack propagation. It is believed that stress intensity factors calculated using peak load and initial flaw dimensions are good approximations of the depthwise (WT) fracture tough ness. The fracture toughness values for the WT direction listed in Table 3 are considerably greater than comparable values measured for the WR direction.

2.1.2 Aluminum 7475-T651

The 7475 alloy was tested so that the relative crack growth resistance of the 7075 and 7475 alloys could be compared. The 7475 alloy is a high purity 7075 alloy with lower specification limits on magnesium content. The 7475 alloy tested in this program was obtained from Alcoa in the form of a $1.0 \times 18 \times 12$ inches plate in the T651 condition. The compositions as determined by both Boeing and Alcoa are listed in Table 2. The only significant difference in chemical composition between the 7475 and 7075 alloys was iron content which was significantly lower in the 7475 plate.

The microstructure (Figure 4) and macrostructure were typical of 1.0 inch thick 7475-T651 plate. Typical values were obtained for hardness (90.9 Rockwell B) and conductivity (32.9-% IACS).

The plate was characterized for exfoliation corrosion by the "Total Immersion Exfoliation Corrosion Test" (ASTM Task Group G01.05.02-T.6.8). Normal exfoliation characteristics were observed and negligible differences were noted compared to the corrosion characteristics of the 7075 plate.

Table 3: Summary of Fracture Toughness Data for Plate Alloys

	T	FRACTURE TOUGHNESS (KSI VIN.)					
ALLOY	TEMP		i				
	<u> </u>	WR DIRECTION*	WT DIRECTION**				
ALUMINUM	-65	21.4	30.7				
7075-T651	+72	22.7	32.6				
7070-1001	+175	24.2	34.7				
STEEL	-65	87.0	94.0				
9Ni-4Co-0.3C	+72	107.0	106.5				
(F _{tu} = 240)	+175	105.0	108.3				
TITANIUM	-85	92,5	104.8				
6AI-4V BETA	+72	93.2	95.2 (a)				
ANNEALED	+175	98.6	88.4 (a)				
T1T A A111 144	-65	84,0	103				
TITANIUM	+72	92,5	93				
6AI-4V RA	+175	102.5	90 (a)				

^{*} FROM COMPACT TENSION SPECIMENS ** FROM SURFACE FLAWED SPECIMENS (a) FAILURE STRESSES >90% $\sigma_{\rm YS}$




Figure 4: 7475-T651 Aluminum Alloy Microstructure Composite (200X, Kellers Etch)

Mechanical property and fracture toughness values were measured at 72F by The Boeing Company. Results are included in Tables 4 and 5. The ultimate and yield strength values were slightly lower than for the 7075 alloy. The plane strain fracture toughness for the WR direction of the 7475-T651 alloy (31 ks1 $\sqrt{\text{in}}$) was considerably greater than that for the 7075-T651 plate.

2.1.3 Titanium 6A1-4V Beta Annealed

The Ti-6Al-4V beta annealed alloy was purchased from RMI in the form of 1.0 \times 48 \times 84 inches plates per Boeing Material Specification XBMS7-174B. The B revision of the applicable specification requires an extra low interstitial grade and annealing above the beta transus to provide high toughness and resistance to stress corrosion cracking.

The plate composition as determined by the producer as verified by Boeing chemical analyses is shown in Table 6. The Boeing analysis yielded somewhat lower values for oxygen content. The microstructure, shown in Figure 5, is typical for beta annealed Ti-6Al-4V. Examination of the macrostructure revealed a uniform structure with only minor banding. The average prior beta grain size was approximately 10^{-4} square inches. Crystallographic average texture as determined by a computerized X-ray pole figure analysis (Figure 6 and Table 7) showed the material to have a generally random orientation of basal planes. The pole figure analysis method is described in Appendix D. A high intensity of basal planes normal to the maximum stress direction has been shown to degrade stress corrosion and corrosion fatigue characteristics. No significant effect of texture was expected in this material.

Mechanical properties were measured by The Boeing Company at temperatures of ~65F, 72F and 175F. Mechanical property data are tabulated in Table A5 in Appendix A and plotted in Figure 7. The 72 F yield and ultimate strengths of 124 and 134 ksi exceed the corresponding minimum specification values of 115 and 127 ksi. The 72F elongation and reduction in area also meet specification values of ten and fifteen percent, respectively.

Fracture toughness values were measured using both compact tension and surface flawed specimens. The compact tension specimens were tested per ASTM E399-70T

Table 4: Mechanical Property Data for 7475-T651 Aluminum Alloy One Inch Thick Plate

GRAIN DIRECTION	TEMP (^O F)	ULTIMATE TENSILE STRENGTH (KSI)	0.2% OFFSET YIELD STRENGTH (KSI)	ELONGATION IN 2.0 INCHES (%)	REDUCTION IN AREA (%)
LONGITUDINAL	72	88.7 88.6	80.0 79.5	10 10	21 23
LONG TRANSVERSE	72	84.9 86.0	75.9 75.5	. 11	29 23

Table 5 : Fracture Toughness (K_{lc}) Data for 7475-T651 Aluminum Alloy One Inch Thick Plate

PROPAGATION DIRECTION	TEMP (°F)	AVERAGE CRACK LENGTH (IN.)	MAXIMUM LOAD (K)	PQ (K)	K _Q (KSI √∏N.)
WR	72	0.74	2.74	2.49	30.0
	72	0.73	2.74	2.74	32.1

Table 6: Chemical Composition of Titanium Alloys

MATERIAL	HEAT	TEST LAB	υ ₂	Al	· V	Fe	N ₂	С	H ₂
Ti6Al-4V BETA-ANNEALED	304623 SPEC	LIMITS	.0613	5.5-6,3	3. 5 -4.5	0.25 MAX	.03 MAX	0.08 XAM	.0125 MAX
		RMI	.125	6.1	3.9	.17	.010	0.02	.0044
		BOEING	.103	6.07	3.8	.16		0.04	.0053
TI6AI-4V BETA-ANNEALED SUPER ELI	G8200 (NO SPECII	FICATION) TIMET	.06	6.0	4.1	.05	.008	.023	.005
TI-6AI-4V RECRYSTALLIZE ANNEALED	SPEC I	LIMITS	.0913	5.5-6.2	3.5-4.5	0.26 MAX	.03 XAM	80.0 XAM	.0125 MAX
		TIMET	.13	6.0	4.1	.11	.018	.026	.0050
		BOEING	.084	6.01	4.1	.15		.02	.0052





Figure 5: 6AI-4V Standard ELI Beta Annexied Titanium Alloy Microstructure Composite (500X)



CONTOUR LINES	1	2	3_	4	5	6	7	8	9	0
TIMES RANDOM INTENSITY	0.5	1.0	1,5	2.0	4.0	8.0	14.0	20.0	25.0	30.0

Figure 6: Pole Figure for 6Al-4V Standard ELI Beta Annealed Titanium Alloy - Basal Plana (0002)

Table 7: Quantitative Texture Factors* for Titanium Alloys

4447777141	HEAT	TEXTURE FACTORS				
MATERIAL	TREATMENT	% I _L	% I _T	% I _{ST}		
Ti-6AI-4V SUPER ELI BETA ANNEALED	AS-RECEIVED	32.2	36.1	31.7		
Ti-6AI-4V RECRYSTALLIZE ANNEALED	1900F/40 MIN/AC 1350F/2 HRS/AC	33.5	35.1	31.3		
Ti-6AI-4V STANDARD ELI BETA ANNEALED	AS-RECEIVED	34.0	41.2	24.8		

QUANTITATIVE TEXTURE FACTOR DESCRIBES NUMERICALLY THE PERCENTAGE OF BASAL PLANES ORIENTED NORMAL TO A SPECIFIC GRAIN DIRECTION, I.E., LONGITUDINAL (L), TRANSVERSE (T), AND SHORT TRANSVERSE (ST). THE TEXTURE FACTOR IS CALCULATED FROM X-RAY POLE FIGURE INTENSITIES (SEE APPENDIX D) AS FOLLOWS:

% IL =
$$\frac{90^{\circ}}{\Sigma}$$
 IL SIN & SIN \propto / TOTAL INTENSITY




Figure 7: Mechanical Properties For 6Al-4V Beta Annealed Titanium Alloy Plate (1.0-Inch Thick)

except for specimen thickness requirements; detailed results are tabulated in Table A6 in Appendix A and fracture toughness are plotted as a function of test temperature in Figure 3. The average 72F fracture toughness value of 93 ksivin is believed to be a close approximation of the plane strain fracture toughness of the material since the specimen thickness of one inch was a high percentage of the minimum specimen thickness required for plane strain fracture toughness testing by E399-70T, namely, 2.5 $(K_{IC}/\sigma_{vs})^2$ or about 1.4 inches. Six surface flawed specimens with crack planes perpendicular to the long transverse plate direction were tested to evaluate fracture toughness for the WT direction at -65F, 72F and 175F. Test details and results are tabulated in Table A7 in Appendix A and fracture toughness values are reported in Table 3 where they are compared to fracture toughness values obtained from the compact tension specimen tests. The trend of increasing toughness with increasing temperature for the WR direction is apparently reversed for the WT direction. However, the failure stresses for the surface-flawed specimens tested at 72F and 175F were greater than 90% of the corresponding uniaxial yield strengths and it is believed that the high failure stresses resulted in apparent fracture toughness values that are less than the actual values.

The Ti-6Al-4V beta annealed titanium plate having an oxygen content of 0.06% was obtained as a 1.0 x 8 x 11 inches plate from the Boeing Commercial Airplane Company. The plate was produced by TMCA per Boeing Material Specification BMS7-174B. The microstructure shown in Figure 8 was typical for beta annealed Ti-6Al-4V. Crystallographic average texture as determined by X-ray pole figure analysis (Figure 9 and Table 7) showed the material to have a nearly random orientation of basal planes. Chemical composition as determined by the vendor is included in Table 6 and mechanical properties measured by The Boeing Aerospace Company are shown in Figure 7. The K_{ISCC} for the WR direction of the plate was previously measured using a single edge notch tension specimen and found to be 87 ksi√in.

2.1.4 Ti-6Al-4V Recrystallized Annealed (RA)

Ti-6Al-4V RA plate, 1.0 inch thick, was fabricated to meet the requirements of the North American Rockwell Specification ST0170LB0032, Rev. B. The material was developed for use on the B-1 Bomber and was selected to meet high fracture




Figure 8 : 6AI-4V "Super ELI" (02 Cantent = 0.06) Beta Annealed Titanium Microstructure Composite (500X)




Figure 9: Pole Figures For 6Al-4V "Super EL1" (θ_2 Content = 0.06) Beta Annealed Titanium Alloy-Basal Plane (0002) α

toughness criteria. The plate material was supplied to Boeing by North America Rockwell. The specification requirements include an ELI composition grade (0.13 wt. percent oxygen) and thermal processing near, but below the heta transus temperature to achieve a fully recrystallized alpha-beta microstructure. Both of these specification requirements provide improvements in the fracture characteristics compared to the conventional MIL-SPEC Ti-6Al-4V material. Following the RA processing, the material is annealed at 1400F and cooled relatively fast to 900F.

The plate composition as determined by the supplier and by Boeing is shown in Table 6. The Boeing analysis indicated a markedly lower oxygen content than that obtained by the supplier, TIMET. The plate microstructure, shown in Figure 10, was uniform and showed a high degree of alpha-beta recrystallization with equiaxed primary alpha grains in a retained beta matrix. The macrostructure revealed some variation in alpha grain size across the plate thickness. Basal plane pole figure (Figure 11) as determined by a computerized X-ray analysis technique indicated only moderate texturing with relatively balanced high intensity basal plane regions for both the transverse and longitudinal grain directions. The transverse direction, however, had a slightly higher intensity of basal planes (Table 7).


Mechanical properties were measured by The Boeing Company at temperatures of -65F, 72F and 175F. The resulting data are tabulated in Table A8 in Appendix A and are plotted against temperature in Figure 12. The 72F yield and ultimate strengths of 125 and 137 ksi exceed the specification minima of 120 and 130 ksi. The 72F elongation of 12 percent exceeds the specification requirement of 10 percent.

Fracture toughness values were measured using both compact tension and surface flawed specimens. The compact tension specimens were tested per ASTM E399-70T except for specimen thickness requirements; detailed results are tabulated in Table A9 in Appendix A and fracture toughness values are plotted against test temperature in Figure 3. The average 72F fracture toughness of 93 ksi\in. is identical to that of the beta processed alloy and is well in excess of the specified minimum value of 75 ksi\in. Six surface flawed specimens with crack



LONGITUDINAL VIEW

Figure 10: 6AI-4V Recrystallize Annealed Titanium Alloy Microstructure (500X)



CONTOUR LINES	1	2	3	4	5	8	7	8	9	0
TIMES RANDOM INTENSITY	0.5	1.0	1.5	2.0	4,0	8,0	14.0	20.0	25.0	30.0

Figure 11: Pole Figure For 6Al-4V Recrystellize Anneeled Titenium Alloy — Basel Planes (0002)a.




Figure 12: Mechanical Properties For 6AI-4V Recrystallize Annealed Titanium Alloy Plate (1.0-Inch Thick)

planes perpendicular to the long transverse plate direction were tested to evaluate fracture toughness for the WT direction at -65%, 72% and 175%. Yest details and results are tabulated in Table A10 in Appendix A and fracture toughness values are summarized in Table 3 where they are compared to fracture toughness values obtained from the compact tension tests. Results are nearly identical to those for the Ti-6Al-4V beta annealed plate and again, the apparent trend of decreasing WT direction toughness with increasing temperature may have been influenced by the high failure stresses for the 175% tests.


2.1.5 Steel Alloy 9Ni-4Co-0.3C

The alloy steel, 9Ni-4Co-0.30C, was selected for evaluation since it is considered the leading candidate for aircraft applications in the 220-240 ksi strength range. The alloy is currently used in various primary structure applications as are similar alloys including D6AC and 4330V. The 9Ni-4Co alloy however has superior fraction toughness. The material for this study was purchased as annealed hot rolled plate per the Boeing specification BMS 7-182A. The plate size was 0.625 x 48 x 72 inches. The material was heat treated at Boeing to a strength range of 220-240 ksi using the following procedures:

- Normalize at 1650F, one hours, air cool
- Solution treat at 1550F, one hours, oil quench
- Refrigerate at -100F, two hours
- Double temper at 950F (2 + 2) hours, air cool.

The microstructure (Figure 13) is typical for the 9Ni-4Co-0.30 alloy. The macrostructure indicated evidence of banding (Figure 14). Microprobe analysis across the bands for Co, Ni and C showed no significant variation. Typical band thickness were approximately 0.0005 inch.

Delaminations were also observed on the fracture face of corrosion fatigue specimens used to test the WR direction. The average spacing of the delaminations was approximately 0.010 inch with the thicknesses ranging from 0.005 to 0.050 inch. Differences in microstructural features were not readily observable between the bands and adjacent regions even at magnifications of 1200X (Figure 15). The martensitic structure appeared to be slightly less predominant in the centers of the dark etching areas.



10 mm

Figure 13: 9NI-4Co-0.3C Steel Alloy Microstructure Composite (500X)



Figure 15: Banding in 9Ni-4Co-0.3C Steel Alloy at High Magnification, (1200X)

The alloy composition and specification limits are listed in Table 8. Except for the carbon content which was 0.34 wt %, the specification maximum, the plate composition was typical for the alloy. The inclusion content as determined per ASTM E-45 resulted in a D-2 rating which is considered relatively clean and typical of vacuum arc remelt steel.

The banding observed in the 9Ni-4Co-0.30C is not considered typical by the plate producer (Republic Steel) and was considered by Republic to be a hot working process problem. They considered the material to represent the "low end" with respect to other previous heats of the alloy. In previous limited experience at Boeing, deleterious banding in 9Ni-4Co alloys has not been observed.

Mechanical properties of the heat treated steel were measured at -65F, 72F and 175 by The Boeing Company. The resulting data are tabulated in Table All in Appendix A and mechanical properties are plotted against temperature in Figure 16. The 72F yield strengths of 204 to 209 ksi were within the desired yield strength range of 200-210 ksi. The corresponding ultimate strength values ranged from 240 to 245 ksi and exceeded the minimum specification value of 230 ksi.

Fracture toughness values were measured at -65F, 72F and 175F using compact tension, double cantilever beam, and surface flawed specimens. Compact tension specimens (Figure B2) were tested at -65F and 175F per ASTM E399-70T requirements. Double cantilever beam specimens (Figure B10) were tested at 72F per the ASTM requirements except for specimen length. The resulting data are tabulated in Table A12 in Appendix A and fracture toughness values are plotted against temperature in Figure 3. The 72F fracture toughness was 106 ksi\sqrt{in}. Six surface flawed specimens with crack planes perpendicular to the long transverse plate direction were tested to evaluate fracture toughness for the WT direction at -65F, 72F and 175F. Test details and results are tabulated in Table A13 in Appendix A, and fracture toughness values are summarized in Table 3 along with values obtained from the compact tension tests. The good agreement between all of the fracture toughness data is indicative of the homogeneity of the 9Ni-4Co-0.3C steel alloy plate.

Table 8: Chemical Composition of 9Ni-4Co-0.3C Steel (220-240 ksi)

F.	BAL	BAL	
>	0.06	0.09	0.10
9€	0.90	2	1.0
පී	4,00 -5.00	4 .	7.4
ž	7.00	7.50	7.6
්	0.90	1.06	0.1
·s	0.10 MAX	.007	
a	0.10 MAX	8 .	
ম	0.10 MAX	0.01	0.05
Min	0.10 -0.35	0.27	0.28
၁	0.29	0.34	•
TEST LAB	MITS	REPUBLIC	BOEING
HEAT LOT	SPECLIMITS	3830071	




Figure 16: Mechanical Properties for 9Ni-4Co-0.3C Steel Alloy Plate (0.625-Inch Thick)

2.2 Selection of Environments

Stress corrosion cracking and corrosion fatigue tests were conducted in seven different environments as shown in Table 1. Five primary environments included desiccated air having a relative humidity of about 10 percent, distilled water, 3.5% NaCl solution, water saturated JP-4 fuel, and sump tank water. Two secondary environments included alternating JP-4 fuel and distilled water, and dye penetrant (type ZL-2A). The desiccated air was selected as a realistic reference environment. There was no intention of selecting a completely inert reference environment for the program since one of the primary objectives was to develop useable data. Distilled water was selected to determine the results of moisture and water on crack growth behavior in the absence of salts. The 3.5% NaCl solution was thought to be representative of the worst environments to which airframe components could be frequently exposed. Other investigators have concluded that 3.5% NaCl solution is an overly severe representative of the "worst" environment and have recommended sump tank water as an alternative test environment. Sump tank water is representative of solutions that are found in sump areas of aircraft and has the chemical content shown in Table 9. Since sump tank water has a smaller chloride ion content than does 3.5% NaCl solution, it should be less aggressive in promoting crack growth in titanium alloys. Since all of the materials tested could come in contact with JP-4 fuel, the fuel environment was selected as a primary test environment. Distilled water was added to the JP-4 fuel to saturate the fuel to the limit of approximately 50 ppm of water, Tests conducted in alternating JP-4 fuel and distilled water were representative of the environmental mix encountered in a "wet" wing. Finally, tests were conducted in dye penetrant after it was observed in previous work (2) that type ZL-2A dye penetrant promoted considerable stress corrosion cracking in Ti-4Al-2.5Sn (ELI) base metal and weld metal. Hence, the question arose as to whether poor inspection practice could have detrimental effects on aircraft components. Type ZL-2A dye penetrant was tested because of its applicability to the three alloy systems tested in this program.

An attempt was made to identify environmental spectra that could be particularly detrimental to crack growth characteristics of airframe metal alloys. In particular, consideration was given to potential synergestic effects resulting from the concurrent action of two or more environments. There are a multitude of

Table 9: Chemical Content of Simulated Sump Tank Residue Water

CONSTITUENT	CONCENTRATION (PPM)			
CaCl ₂	50			
CdCl ₂	1000			
MgCl ₂	50			
NeCl	100			
ZnCl ₂	10			
PbCI ₂	1			
CuCl ₃ · 2H ₂ O	1			
CrCl3 · 6H2O	1			
FeCl3	5			
MnCl ₂ · 4H ₂ O	5			
NiCi ₂ · BH ₂ O	1			
DISTILLED WATER	BAL			

different operational fluids and manufacturing aids with which aircraft components can come in contact. However, no success was met in identifying particular combinations that would be expected to have a synergestic effect. Synergestic effects are not particularly common in subcritical crack growth tests and, in many cases, are difficult to define. For example, three cases observed in stress corrosion cracking tests are shown in Figure 17.

- 1. Alloy suseptible to SCC in both environments A and B; when the two environments are mixed, there are three possibilities.
 - a. Mixture produces more rapid crack propagation and possibly reduces K_{Iscc} ; for example, $H_2O CH_3OH-CI$ on some titanium alloys.
 - b. Mixture produces intermediate crack growth rates and possibly increases $K_{\mbox{Iscc}}$; for example, $H_2\mbox{O-glycerine-CI}$ on some titanium alloys.
 - c. Mixture reduces crack growth rates and possibly varies $K_{\rm Iscc}$; for example, H_2^0 -methylene chloride mixtures on some titanium alloys.
- 2. Alloy susceptible in only environment A: when B is added, there are two possibilities:
 - a. Mixture produces more rapid crack growth and possibly lowers K_{Iscc}; for example, H₂O-methanol mixtures on the aluminum alloy 7075-T651. (see Figure 18)
 - b. Mixture produces lower crack growth rates; for example, H₂0-methanol mixtures in the aluminum alloy 7075-T651 (see Figure 18) and H₂0-hydrogen mixtures on titanium alloys.
- 3. Alloy not susceptible in either component A or B but susceptible in mixture, possible examples:
 - a. Chemical reaction of components to produce damaging environment, e.g., hydrogen and oxygen to produce water inducing susceptibility of aluming alloys.




Figure 17: Schematic Representation of Possible Effect of Mixing Environments A & B on Stress Corrosion Properties of an Alloy




Figure 18: Velocity of Stress Corrosion Cracks in a High-Strength Aluminum Alloy as a Function of Water Content in Methanol

When the additional variable of composition, i.e., amount of A and B is introduced such as in the case of MeOH-H₂O mixture on 7075, one could conclude that both synergistic and retardation effects occur. For 7079 aluminum alloy, no synergistic effect is observed and thus, the extension of a result for one alloy to all alloys is also doubtful.

Rather than search for synergestic phenomena, it was decided to look at the effect of a corrosion inhibitive compound on crack growth behavior for several material/environment couples. The intent was to investigate whether or not corrosion inhibitive compounds had any beneficial effects on crack growth resistance at existing cracks. If such were the case, then such compounds could be useful in protecting inaccessible areas of airframe structure and as a temporary corrective action. The specific corrosion inhibitive compound used in these tests was LPS-3.

2.3 Procedures

rrocedures used for specimen preparation, handling, testing, and evaluation of results are described in this section.

2.3.1 Specimen Preparation

Thirteen different specimen configurations were used to accomplish the tests reported herein. Specimen configurations are detailed in Figures Bl through Bl3 in Appendix B. A summary of specimen configurations used for each type of test is included in Table Bl in Appendix B.

Mechanical property tests were conducted using one smooth tensile specimen configuration as shown in Figure Bl.

Static fracture toughness tests were conducted using compact tension (CT) and surface-flawed (SF) specimens. Specimen configurations for all CT specimens are included in Figure B2. Specimen configuration for aluminum alloy SF specimens is detailed in Figure B3; similar titanium and steel alloy specimens are shown in Figure B4.

Stress corrosion cracking tests were performed using double cantilever beam (DCB) and SF specimens. DCB specimen configurations are included in Figures B5 through B7. Specimens detailed in Figure B5 were used for testing the short transverse direction of the plate materials. Specimens in Figures B6 and B7 were used for testing either the WR or RW crack propagation directions. SF specimen configurations are detailed in Figures B3, B4, B8 and B9.

Corrosion fatigue tests were conducted using both DCB and SF specimens. Most tests were conducted using the DCB specimens. Grooves were vee shaped with a 60° included angle, 0.01 inch root radius, and depth equal to ten percent of the specimen thickness. SF specimen configurations are shown in Figures B3 and B4.

Overload tests were performed using tapered double cantilever beam specimens having the configurations shown in Figures B12 and B13. Specimens were linearly tapered to approximate the contour defined by the equation.

$$3 a^2/h^3 + 1/h = 4.0$$

where: a is crack length

h is one-half specimen height at the cross section through the crack tip.

The above equation defines the approximate contour required to make stress intensity factors independent of crack length for constant load (3). Since the equation is approximate and deviates only slightly from a straight line, a linear taper was used to fabricate the tapered double cantilever beam specimens. Compliance measurements on the linearly tapered specimens verified that stress intensity factor was independent of crack length within experimental accuracy. Results of compliance measurements for the tapered double cantilever beam specimens are summarized in Appendix C.

Crack starters in all CT and DCB specimens consisted of a 0.125 inch wide milled slot terminating in a chevron Vee notch. Pracracking was accomplished using fatigue loadings having a stress ratio of 0.06 and a cyclic frequency of 1800

cpm. The 0.10 inch of precrack was grown using peak cyclic stress intensity to Young's modulus ratios less than 0.0012 /inch. Crack starters in SF specimens were produced using an electrical discharge machine and 0.06 inch thick circular electrodes; electrode tips were machined to a radius of 0.003 inch and an included angle of less than 20 degrees. Fatigue cracks were grown from the starter slots using a stress ratio of 0.06, cyclic frequency of 1800 cpm, and peak cyclic stress of 10 ksi for the aluminum alloy specimens, and 25-30 ksi for the steel and titanium alloy specimens.

All specimens were cleaned by brushing with commercial grade naptha. Each specimen was then sealed in a plastic bag until tested.

2.3.2 Testing

Test procedures used for fracture toughness, stress corrosion cracking, corrosion fatigue, and overload tests are described in the following.

Fracture Toughness

All compact tensions tests were conducted per the ASTM method of tests for plane strain fracture toughness of metallic materials (E399-70T). Surface-flawed specimens were loaded to failure in standard tensile test machines at a rate required to precipitate failure in about one minute. All specimens were instrumented with clip gages spring loaded against knife edges integrally machined at the mounth of the flaw. The clip gage and load cell of the test machine were connected to an X-Y recorder to obtain records of load versus crack opening displacement for each specimen.

Temperature control was accomplished as follows. Tests at 72F were conducted within an enclosed environmentally controlled laboratory. Tests at -65F were conducted in a mixture of cold nitrogen gas and air, the temperature of which was controlled by a servo valve actuated by a thermocouple attached to the specimen. Tests at +175F were conducted with the specimen surrounded by a metallic jacket with heaters attached. Heaters and temperature were controlled by thermocouples attached to the specimen. All temperatures were controlled to within +2F of the nominal values.

Stress Corrosion Cracking

Stress corrosion cracking tests were conducted by subjecting DCB specimens to constant opening mode deflections at the mouth of the crack. All aluminum and steel alloy specimens, and titanium alloy short transverse specimens were loaded by driving a wedge into the end of the crack starter slot as illustrated in Figure 19. The crack tip was submerged in the test medium during the loading operations and the wedge was inserted until a small amount of crack extension occurred. Specimens were then placed in sealed glass containers filled with the test media. Periodic recording of crack length were taken by observing the specimens under a 30X microscope. Titanium alloy specimens used to test the WR crack propagation direction were loaded in a slightly different manner. With reference to Figure 20, specimens were pin loaded in a test machine with the crack tip submerged in the test medium. A clip gage was used to monitor crack opening displacement during the loading process. After the desired displacement was attained, a pair of circular wedges were inserted into the central hole to wedge open the crack. The load was then reduced by 1000 pounds and the wedges were driven in further to recover the crack displacement lost due to elastic deformations in the viscinity of the wedges. This incremental unloading procedure was repeated two or three times after which the applied load was reduced to zero and a final crack surface displacement reading was taken. The specimens were then transferred to enclosed test chambers filled with the test media. Periodic readings of crack length were made throughout each test.

Corrosion Fatigue

Corrosion fatigue tests were conducted by subjecting specimens to either constant load or constant deflection cycling. Tests designed to yield crack growth rates for intermediate and high AK values were conducted by subjecting specimens to constant peak cyclic loadings to grow the cracks over a series of predetermined increments of crack length in the required test media. The first increment of crack growth was induced using a constant peak cyclic load slightly greater than the load used to precrack the specimen. The peak cyclic load was then increased by 100 lb for the aluminum alloys and 500 lb for the steel and titanium alloys, and a second increment of crack growth was induced. This procedure was repeated until the stress intensity factor was at or near the critical value. Crack growth increments required to grow the cracks from initial to critical conditions




Figure 19: SCC Test Specimens for 7075-T651 Aluminum and 9Ni-4Co-0.3C Steel Alloys




Figure 20: SCC Test Specimen and Loading Method for 6AI-4V Titanium Alloys

ranged from five to seven. The increments of crack growth could generally be identified on the fracture surface of the specimen and the known locations of the crack front after each crack growth increment provided a check of the instrumentation output used to evaluate crack growth rates.

Corrosion fatigue tests for the lower ΔK values were conducted by subjecting specimens to constant deflection loadings. The initial load was set equal to the load used to precrack the specimens. The load cell and clip gage were parts of a servo system that kept the peak cyclic crack displacement constant during the remainder of the test. Consequently, the cracks grew under gradually decreasing ΔK values until the test was terminated. The load decreased smoothly throughout each test and incremental load adjustments were not used. For alloy/environment couples where crack growth rate data obtained from both constant load and constant deflection tests overlapped, agreement between the data was good. For example, see Figure A19 in Appendix A.

All corrosion fatigue and fracture toughness specimens were instrumented with clip gages to obtain recordings of opening mode crack displacement versus cycles. Clip gages were spring loaded against integrally machined knife edges at the mouth of the crack starter. Knife edge details and locations are shown in Figure BlO An appendix B. Gage output was recorded periodically to obtain relationships between specimen compliance and loading cycles.

2.3.3 Evaluation of Results

医克勒氏线 医甲基氏 医二氏虫虫 经营产的 医克里氏试验检尿病

Static fracture toughness values were calculated from CT specimen results using ASTM recommended procedures (E399-70T). Fracture toughness values were calculated from DCB specimen results using ASTM recommended procedures for CT specimens with the exception that stress intensity factors were calculated using the following equation:

$$K_{I} = \frac{2P}{b} \left[\frac{b}{b_{n}} \right]^{1/2} \left[\frac{3(a+0.6h)^{2} + h^{2}}{(1-\mu^{2}) h^{3}} \right]^{1/2}$$
(1)

where P is 5 percent secant offset load

b is specimen width

b is crack width

h is one-half the specimen height

E is Young's modulus

a is crack length

u is Poisson's ratio

Fracture toughness values for SF specimen tests were calculated using the equation

$$K_{T} = \sigma \sqrt{\pi a/Q} M_{K}$$
 (2)

where o is gross section failure stress

a is the crack depth

Q is the modified shape factor shown in Figure 21

 M_v is shown in Figure 22 (Reference 4).

Stress corrosion cracking results were evaluated by plotting increase in crack length versus test duration using intermittent readings of crack length versus time. The slopes of the resultant curves were taken as the SCC velocities. Corresponding stress intensity factors were determined using the measured crack opening displacements at the end of the specimen. For specimens loaded as shown in Figure 19, deflections were measured between the outer corners of the test specimen designated by the letter A in Figure 19. For specimens loaded as shown in Figure 20, deflections measured with the clip gage were multiplied by the ratio of a/(a+1) to determine the displacement at the load line. Stress intensity factors were calculated by substituting measured displacements (δ) into the equation

$$K_{I} = \frac{\delta E h \left[3 h (a + 0.6 H)^{2} + h^{3}\right]^{1/2}}{\sqrt{1 - u^{2}} 4 \left[(a + 0.6 h)^{3} h^{2} a\right]} \left[\frac{b}{b_{n}}\right]^{1/2}$$
(3)

where the symbols represent the same measurements as in Equation 1.

Crack growth rates for corrosion fatigue tests were determined using crack displacement versus cycles records. Crack displacements were measured at




Figure 21: Shape Parameter Curves for Surface and Internal Flaws




Figure 22: Estimated Elastic Stress Intensity Magnification Factors at Maximum Crack Depth for Surface Cracks in Tansion (Reference 4)

predetermined cyclic intervals and corresponding compliance values were determined by dividing the measured displacements by the applied load. Crack lengths corresponding to the individual compliance values were determined from previously measured compliance/crack length calibrations. Increments of crack length were divided by the corresponding number of loading cycles to determine average crack growth rates over the cyclic intervals. Stress intensity factors at the beginning and end of each cyclic interval were averaged to determine the stress intensity factor against which average crack growth rates were plotted. Stress intensity factors for uniform height DCB specimens were calculated using either Equations 1 or 3. Stress intensity factors for tapered double cantilever beam specimens were calculated using the equation

$$K_{I} = \frac{P}{\sqrt{2b_{D}}} \cdot \left[\frac{E}{(1 - \mu^{2})} \right]^{1/2} \cdot \sqrt{\partial c/\partial a}$$
(4)

where P is applied load .

b_n is crack width

c is specimen compliance

a is crack length

Specimen compliance was measured experimentally and results are reported in \dot{A}

2.3.4 Comments on Procedures

A considerable amount of experience was obtained in applying the DCB specimen testing procedures used in this program. In light of this experience, the following evaluation of the procedures is made.

The data resulting from the DCB specimen tests was very consistent and repeatable. Hence, it is believed that the procedures were more than adequate for generating the type of corrosion fatigue data contained in this report. Some of the key features of the procedures were: (1) no periodic visual measurements of crack length were made; (2) the load was incrementally increased throughout each test; (3) side grooves were used to restrict the growing crack to its original plane.

The need for intermittent visual measurements of crack length was circumvented by periodically increasing the applied load after predetermined increments of crack growth. This procedure left marks on the fracture surface which periodically established the location of the crack front. Hence, a recurrent check of instrumentation output was available throughout each test. Comparisons between actual and calculated crack length based on the intial compliance tests never yielded differences greater than 0.03 inch. However, since each specimen was individually calibrated the actual location of the crack front was always known with accuracy much greater than 0.03 inch. Total crack length was used only to calculate stress intensity factor and was not used in crack growth rate calculations. Since total crack lengths varied from 1 to 3 inches, the accuracy of crack length determinations in these tests was more than adequate.

The amount of crack growth generated under constant test conditions influences the accuracy of crack growth rate calculations. In these tests, cracks were grown in 0.30 inch increments under constant test conditions. Increments of this size were required to yield readily interpretable test records, i.e. records having sufficient change in compliance to establish the proper curvature of the crack deflection versus cycles record. Smaller increments of crack growth would have required increased sensitivity for the strip chart recorders and would have taxed the accuracy of normal recording equipment. Hence, the size of increments in which the crack is grown has to be tailored to the available test equipment.

The use of side grooves to restrict the growing cracks to the original crack plane is believed to be an acceptable procedure as long as the groove depth is not an excessively large percentage of the specimen thickness. In these tests, groove depth was 10% of the specimen thickness. The resulting crack growth rates compared very well with large DCB specimens in which side grooves were not used and so it was concluded that 10 per cent deep grooves did not have a significant effect on crack growth rate behavior. The authors are not vare of any systematic study of the effects of side grooves on crack growth rate e-havior.

Side grooving of DCB specimens has both advantages and disadvantages. The main advantage is that smaller specimens can be tested without encountering crack

rotation problems. Without grooves, the height of the specimen arms must be increased until the ratio of bending stress to applied load is sufficiently low to preclude crack rotation. This approach leads to larger specimens and test load capacities. One disadvantage of side grooves is that they made visual measurements of crack length very difficult. A second disadvantage is that systematic studies of the effects of side groove on fatigue crack growth rates are lacking. If side grooves deeper than about 10 per cent of the specimen thickness are required, the grooves could have influences on crack growth rate that cannot be accounted for using existing knowledge.

3.0 RESULTS AND DISCUSSION

Results of stress corrosion cracking and corrosion fatigue tests for each of the four major alloys are presented and discussed in separate sections. The effects of test environment, cyclin frequency, and specimen type on results are treated individually for each major. A combined presentation of overload and stress ratio effects is individed in the last two subsections. Test results for the 7475-T651 aluminum alloy are included in Section 4.1 along with the 7075-T651 aluminum alloy results. Results for the super ELI Ti-6A1-4V beta annealed plate are included in Section 4.2 along with results for the standard ELI Ti-6A1-4V beta annealed plate. Results of the thermal processing effect tests on Ti-6A1-4V recrystallize annealed alloy are included in Section 4.3.2.4.

3.1 Aluminum Alloy Test Results

The test program for 7075-T651 aluminum alloy plate is summarized in Table 10. Mechanical property and fracture toughness tests were conducted for both the longitudinal (RW) and long transverse (WR) directions. Stress corrosion cracking tests were conducted for the short transverse (TR), RW and WR crack propagation directions. Corrosion fatigue and overload tests were conducted for only the WR crack propagation direction. Results of mechanical property and fracture toughness tests were previously described in Section 2.1. Results of the stress corrosion cracking and corrosion fatigue tests are described in the following subsections 3.1.1 through 3.1.3

Two stress corrosion cracking (SCC) and four corrosion fatigue (CF) tests were conducted for 7475-T651 aluminum alloy plate. One SCC test was conducted in each of two environments of 3.5% NaCl solution and desiccated air; CF tests were performed in both 3.5% NaCl solution and desiccated air. Results are described and compared to comparable 7075-T651 results in Section 3.1.4.

3.1.1 Stress Corrosion Cracking Tests

Stress corrosion cracking tests were conducted in distilled water, 3.5% NaCl solution, and water-saturated JP-4 fuel. Three series of tests were undertaken.

57

Table 10: Test Program for 7075-T651 Aluminum

		٨٥	J								انتا	ENVIRONMENT	S.	AEN.								
E	E SIWEN	ONENC IC		₹	AIR	03	DISTILLED Water	LED R		3.5% Naci Solution	Q O	•	1P.4		Si T	SUMP TANK		4	JP-4+H20		DYE PEN	PEN
TEST IAYT	SPEC	CACI	BRT2 ITAR	±99-	72F	136F -66F	72F	194t	4 9 9-	72F	4941	-65F	72F	1941	-62F	12F	3871	-65F	72F	136r	199-	125 176F
MECHANICAL PROPERTY	TENS.			4	4:	4	-	_		. '						†		-	-	<u> </u>	-	}
FRACT JRE	כנ			2	4	2											-		ŀ	-		
GHINESS	ن ا ا			7	8	7							•									
STRESS CORROSION CRACKING	DCB SF			·	1 2		4		·	4 -			4						. *		4 -	
	80G	8	0.1 0.5 0.8	7	775	2	1 2			- 2 -	-		- 2	4		2 2			. 8			
CORROSION FATIGUE	BC8	မွ	0.1		- 2		1 2			- ~			- 2						7		7	
	SF	09	0.5		2					7										ļ		
OVERLOAD	TDCB	69	0.5		2		!			2												

The first series involved tests for the RW, WR, and TR crack propagation directions using wedge loaded double cantilever beam specimens. For each of the RW and WR directions, two specimens were tested; one specimen was loaded with the crack tip submerged in the test medium, and the second specimen was loaded in laboratory air. For the TR direction, all specimens were loaded with the crack tip submerged in the test medium. No SCC was observed for either of the RW or WR directions. In the TR (short transverse) direction, SCC was observed in all three test media. Periodic measurements of crack length were used to obtain the SCC velocity vs. stress intensity factor (v-K) data plotted in Figure 23. The trend of the v-K data indicate the existence of a threshold stress intensity factor below which SCC would not occur. The authors are not aware of any data verifying the existence of a threshold stress intensity factor in aluminum alloys. Crack growth rates become very slow at K levels approaching the apparent threshold value and tests of very long duration would be required to explore crack growth behavior at very low K values. In this program, tests were terminated after nine months when the surface of the specimens became too corroded to permit further crack length readings.

A considerable amount of corrosion product buildup between the crack faces of the TR/3.5% NaCl DCB specimen was observed. After the surface of the specimen became too corroded to allow further crack length measurements, the wedge used to load the specimen was removed and the opening mode deflection at the end of the specimen was measured both before and after the removal of the wedge. The removal of the wedge results in only a slight relaxation of the crack surface displacement. This result indicates that the corrosion products were exerting a wedging action between the crack surfaces after the removal of the wedge. It is not possible to quantitively assess the effect of corrosion product buildup on stress intensity factors at the crack tip during the nine month test duration. The possibility exists that actual stress intensity factors during the latter stages of the tests were higher than the calculated values due to corrosion product wedging action. Effects of corrosion product buildup have been previously observed during tests of aluminum alloy DCB specimens in 3.5% NaCl solution. The effect of wedging action on crack displacement at the ends of 7075-T651 aluminum alloy DCB specimens has been investigated (5) by measuring the deflections on a number of specimens that were tested for up to a year. The




Figure 23: Stress Corrosion Cracking Velocity Data for 7075-T651 Aluminum Alloy

changes in deflection ranged from zero to +0.006 in. In one specimen tested for more than a year, the deflection increased by 0.015 inch. Hence, corrosion products do result in a wedging action that can increase crack opening displacement, hence, stress intensity factor.

A second series of tests was conducted for the TR crack propagation direction after the DCB specimens were wedge loaded with the crack tip submerged in the corrosion inhibitive compound LPS-3, then immediately placed in the test medium. Results are plotted in terms of crack length versus test duration in Figure 24. After a modest initial delay in SCC growth rate, cracking proceeded at rates comparable to those obtained from the initial series of test where LPS-3 was not used.

A third series of tests was conducted for the TR crack propagation direction after specimens were loaded with the crack tip submerged in LPS-3, dried for three hours, then immersed in the test medium. Increases in crack length versus test duration are plotted in Figure 25. In distilled water, crack growth initiated immediately upon contact with the test medium and proceeded at rates that were slightly less than the plateau velocity for distilled water in Figure 23. In 3.5% NaCl solution, 40 hours elapsed between immersion of the specimen and initiation of crack growth; cracking then proceeded at rates slightly less than the plateau velocity for 3.5% NaCl solution in Figure 23.

A sustained load test of a surface-flawed specimen was discontinued after 1100 hours of exposure to a 3.5% NaCl solution. The semi-minor axis of the flaw coincided with the WT crack propagation direction. The specimen was loaded in the test environment to generate a stress intensity factor at the crack tip of 28 ksi $\sqrt{\text{in}}$ (about 90% of K_{IC}). As illustrated in Figure 26, the fracture surface revealed that considerable splitting had taken place in the short transverse planes all around the periphery of the flaw. It appeared that SCC occurred in the WR direction along the individual laminates formed by the splitting. The corresponding average growth rate is 5 x 10 $^{-5}$ inches/hour. Depthwise growth was prevented by splits. A second essentially identical specimen was loaded to the same peak stress level as used in the SCC test and was then immediately unloaded, fatigue marked, and failed. The loading process induced about 0.005




Figure 24: SCC Test Results for 7075-T651 Aluminum Alloy, Crack Surface Wet With LPS-3 Prior to Immersion in Test Medium





Figure 25: SCC Test Results for 7075-T651 Aluminum Alloy, Crack Surface Sprayed With LPS-3 and Dried for 3.0 Hours Prior to Immersion in Test Medium



APPLIED STRESS = 60 KSI TEST DURATION = 1103 HRS

Figure 26: Illustration of Fracture Face From 7075-T651 Aluminum Alloy Surface Flaw Specimen SCC Test in 3.5% NaCl Solution

inches of growth observed in the SCC test was due to SCC rather than pop-in or stable tear that occurred during the loading process.

The foregoing results indicate a difference between SCC test results obtained from DCB and SF specimens. In the DCB specimen tests, no SCC was observed for the WR direction at stress intensity factor values as high as $25 \text{ ksi}\sqrt{\text{in}}$. In the SF tests, SCC occurred in the WR direction at an estimated stress intensity factor of $16 \text{ ksi}\sqrt{\text{in}}$.

3.1.2 Corrosion Fatigue Tests

Variables involved in the corrosion fatigue tests were environment, cyclic frequency, specimen type, and stress ratio. The effects of environment, frequency, and specimen type on fatigue crack propagation behavior are described below. Stress ratio effects are described in Section 4.6.

All data collected from corrosion fatigue tests of the 7075-T651 aluminum alloy are included in Figures Al through Al5 in Appendix A. Only a limited amount of actual data are used in the body of the report. Rather, the effects of test variables are illustrated using average curves drawn through the data.

3.1.2.1 Effect of Test Environment

Test Media

Average crack growth rate curves for the five principal test media at 72F are summarized in Figures 27, 28 and 29. For all conditions tested, desiccated air and/or water saturated JP-4 fuel yielded the slowest crack growth rates at any given ΔK value; 3.5% NaCl solution and/or sump tanks water yielded the highest crack growth rates; distilled water yielded intermediate crack growth rates. At both 6 and 60 cpm, the maximum difference between the slowest and fastest crack growth rates at given ΔK values was about a factor of four. Hence, the effect of test media on fatigue crack growth behavior of 7075-T651 aluminum allow plate was significant, but not sufficiently large to create unmanageable problems in the operation of airframe components manufactured therefrom.




Figure 27: Effect of Environment on Fatigue Crack Growth Rates at R = 0.1 in 7075-T651
Aluminum Alloy (60 CPM)




Figure 28: Effect of Environment on Fatigue Crack Growth Rates at R=0.5 in 7075-T651 Aluminum Alloy (60 CPM)




Figure 29: Effect of Environment on Fatigue Crack Growth Rates at 6 CPM in 7075-T651
Aluminum Alloy

Test media affected crack growth rates over the entire range of ΔK values from the threshold to critical values. The effects were most easily noticed at intermediate ΔK was decreased, the slopes of the crack growth rate curves continuously increased and it became more and more difficult to distinguish differences in crack growth rate values. When the slopes became large, very small changes in the location of a data point can create an apparent large change in crack growth rates at a constant ΔK value. Hence, conclusions about low ΔK crack growth rate behaviors must be qualified by stating that such behaviors are difficult to ascertain. Notwithstanding the difficult. Figure 27 shows that the most aggressive test media consistently lowered the apparent threshold stress intensity values and increased crack growth rates at very low ΔK values.

Three tests were conducted in the alternating JP-4 fuel and distilled water environment using a stress ratio of 0.1 and cyclic frequeucy of 60 cpm; two tests were conducted using a stress ratio of 0.5 and cyclic frequencies of either 6 or 60 cpm. Each test was conducted by growing the crack in increments of 0.15 inch with the specimen alternately submerged in JP-4 fuel and distilled water. The resultant crack growth rate measurements are plotted in Figure 30 and 31. Individual da a points for the alternating environment are compared to average crack growth rate curves for both distilled water and JP-4 fuel. The 60 cpm data in Figures 30 and 31 fall either between or close to the average crack growth rate curves for the individual components of the environments. Hence, no unusual effects were generated by alternating the two environments. Some of the 6 cpm data, however, fell considerably above the crack growth rate curves for the components of the alternating environment as shown in Figure 31b. Since other similar tests in this program showed no accelerative effect on crack growth rates due to the alternating of JP-4 fuel and distilled water media, the apparent accelerative effect in Figure 31b is probably due to data scatter.

A single test was conducted on a 7075-T651 aluminum alloy specimen after the crack surfaces had been sprayed with the corrosion inhibitor LSP-3 and allowed to dry for 3 hours. The specimen was tested in distilled water using a stress ratio of 0.5 and cyclic frequency of 60 cpm. The resultant crack growth rate




Figure 30: Fatigue Crack Growth Rates for 7075-7651 Aluminum Alloy in Alternating JP-4 Fuel and Distilled Water (60 CPM)




Figure 31: Crack Growth Rates for 7075-T651 Aluminum Alloy Plate in Alternating JP-4
Fuel and Distilled Water (60 and 6 CPM)

data are plotted in Figure 32 along with the average crack growth rate curve for distilled water and untreated crack surfaces. The data show that the LPS-3 had little or no effect on fatigue crack growth rate behavior.

Three tests were conducted in dye penetrant (ZL-2A) using cyclic frequencies of both 6 and 60 cpm and stress ratios of both 0.1 and 0.5. The 60 cpm data are plotted in Figure 33 along with average crack growth rate curves for desiccated air. Since desiccated air was one of the least aggressive media used in this program, it is evident that the dye penetrant used in these tests is not detrimental to fatigue crack growth resistance of 7075-T651 aluminum alloy plate. The 6 cpm data are plotted in Figure 34 along with average crack growth rate curves for salt water and desiccated air. The dye penetrant data fall between or below the curves for the 3.5% NaCl solution and desiccated air environments over the range of ΔK values tested.

Temperature

Fatigue crack growth rate tests were conducted on 7075-T651 aluminum alloy specimens at 175F in four media. The resulting crack growth rate data for desiccated air and 3.5% NaCl solution are plotted in Figure 35; data for JP-4 fuel and distilled water are plotted in Figure 36. Average crack growth rate curves obtained at 72F in the same media are also included in Figures 35 and 36. It is evident that an increase in temperature from 72 to 175F had no significant effect on crack growth rate behavior in the four test media.

Tests were also conducted at -65F in air and the resulting crack growth rate data are plotted in Figure 35. It appears that variations in temperature within the range of -65F to +175F have little or no effect on fatigue crack growth rates for the 7075-T651 alloy.

3.1.2.2 Effect of Cyclic Frequency

A reduction in cyclic frequency from 60 to 6 cpm had little or no effect on fatigue crack growth rates of 7075-T651 aluminum alloy plate in any of the environments tested in this program. The result is substantiated by Figures 37 through 41 where 6 cpm crack growth rate data are plotted and compared to corresponding 60 cpm crack growth rate curves for the five principal test




Figure 32: Fetigue Crack Growth Rates for 7075 T851 Aluminum Alloy in Distilled Water, Crack Surface Sprayed With LPS-3 and Oried for 3.0 Hours Prior to Immersion in Test Medie (80 CPM)




Figure 33: Fatigue Crack Growth Rates for 7075-T651 Aluminum Alloy in Dya Penetrant (Type ZL-2A, 60 CPM)




Figure 34: Fatigue Creck Growth Rates for 7075-T651 Aluminum Alloy in Dye Penetrant (Type ZL-2A, 6 CPM)




Figure 35: Fatigue Creck Growth Rates for 7075-T651 Aluminum Alloy at -65F and +175F in Desiccated Air and 3.5% NaCl Solution (60-EPM)




Figure 36: Fatigue Crack Growth Rates for 7075-T651 Aluminum Alloy at +175 in Distilled Water and Water Saturated JP-4 Fuel (60 CPM)




Figure 37: Fatigue Crack Growth Rates for 7075-T651 Aluminum Alloy in Desiccated Air (6 CPM)




Figure 38: Fatigue Crack Growth Rates for 7075-T651 Aluminum Alloy in Distilled Water (6 CPM)




Figure 39: Fatigue Creck Growth Rates for 7075-T651 Aluminum Alloy in 3.5% NaCl Solution (6 CPM)




Figure 40: Fatigue Crack Growth Rates for 7075-T651 Aluminum Alloy in Water Saturated JP-4 Fuel (6 CPM)




Figure 41: Fatigue Crack Growth Rates for 3075-T651 Aluminum Alloy in Sump Tank Water (6 CPM)

media. The 6 cpm data fell both above and below the 60 cpm curves and only in sump tank water was there any consistent difference between 60 and 6 cpm crack growth rates. In sump tank water, 6 cpm crack growth rates were consistently 1.5 to 2 times the 60 cpm rates. Since this discrepancy is within normal data scatter for crack growth rate tests, it cannot be concluded that it was due solely to a frequency effect.

3.1.2.3 Effect of Specimen Type

Four surface-flawed (SF) specimens were tested so that crack growth rate data obtained from both DCB and SF specimens could be directly compared. Two tests were conducted in each of the 72F test media of desiccated air and 3.5% NaCl solutions. Peak cycle stress levels were varied by a factor of two to determine if stress level had any effect on crack growth rates other than through its contribution to the stress intensity factor. The resulting crack growth rate data are plotted in Figure 42 along with average crack growth rate curves obtained from tests DCB specimens. In air, crack growth rates obtained from SF specimens were slower than corresponding rates obtained from DCB specimens. Although these differences could be due to data scatter, it is believed to be due to the difference in crack propagation directions for the two specimens, namely, WT direction in the SF specimens and WR direction in the DCB specimens. Aluminum alloy hot rolled plate tends to be anisotropic with respect to fatigue crack growth rate resistance with the WT direction having the highest resistance. In contrast, the 3.5% NaCl solution, SF specimen tests yielded higher crack growth rates than did the DCB specimens. Past experience (2) has shown that SF specimens tend to lead to maximum susceptibility to SCC in agressive environments. In these tests, SF specimens yielded a greater impact of test environment on fatigue crack growth resistance. For example, at a AK of 5 ksivin, the 3.5% NaCl solution resulted in a twofold increase in crack growth rates in DCB specimens and a tenfold increase in crack growth rates in SF specimens.

Peak cyclic stress level did not appear to have a significant effect on crack growth rates for constant ΔK values. Data for the two peak cyclic stress levels




Figure 42: Fatigue Crack Growth Rates Data for 7075-T651 Aluminum Alloy Surface Flawed Specimens (60 CPM)

overlapped only for the 3.5% NaCl solutions and showed no effect of peak cyclic stress level.

3.1.3 Aluminum Alloy 7475-T651 Results

The aluminum alloy 7475 was tested as a high purity form of the 7075 alloy to compare SCC and corrosion fatigue behavior of the two alloys. Six tests were conducted for the 7475 alloy including two corrosion fatigue tests in low humidity air, one stress corrosion cracking test in distilled water, and one stress corrosion cracking and two corrosion fatigue tests in 3.5% NaCl solution.

The chemical content of the 7075 and 7475 alloys was essentially the same except for Fe and Mn contents which were lower in the 7475 alloy than in the 7075 alloy (see Table 2). The 7475 alloy contained significantly less impurities than did the 7075 alloy (see Figures 1 and 4).

3.1.3.1 Stress Corrosion Cracking Tests

One test was conducted in each of 3.5% NaCl solutions and distilled water test media for three months. The resulting crack growth rate data are plotted as a function of stress intensity factor in Figure 43. Average curves drawn through comparable 7075-T651 aluminum alloy SCC data are included in Figure 43 for comparison. For stress intensity factor above 12.5 ksivin, SCC rates in the 7475 alloy were faster than in the 7075 alloy. Below 12.5 ksivin, there was not much difference in SCC behavior between the two alloys in 3.5% NaCl solution. Hence, the 7475 alloy did not show any improvement over the 7075 alloy in resistance to SCC in the short transverse crack propagation direction.

3.1.3.2 Corrosion Fatigue Tests

Two corrosion fatigue tests were conducted at 60 cpm in each of the 3.5% NaCl solution and low humidity air test media. The resulting crack growth rate data are plotted in Figure 44 along with average crack growth rate curves drawn through comparable 7075-T651 aluminum alloy corrosion fatigue data. For crack growth rates above 5×10^{-7} inches/cycle, the agreement between data for the two alloys is within normal limits of data scatter. However, the trend




Figure 43: Stress Corrosion Cracking Velocity Data for 7475-T651 Aluminum Alloy




Figure 44: Fatigue Crack Growth Rates for 7475-T651 Aluminum Alloy in Desiccated Air and 3.5% NaCl Solution (60 CPM)

of the data indicates that the 7475 alloy might have a higher threshold stress intensity factor range than does the 7075 alloy. Unfortunately, there were insufficient data to verify this trend.

The work of other investigators has shown that low purity 7000 series aluminum alloys yield crack growth rates at low ΔK values that are equal to or slower than crack growth rates for comparable high purity alloys. Glassman and McEvily (6) have shown that a reduction in particle content may have detrimental effects on fatigue crack growth resistance; they found that crack growth rates in a 7075-T6 aluminum alloy were slower than in a lower particles content X7275-T6 aluminum alloy. Pelloux (7) found that reducing particle content in the 7178 aluminum alloy did not retard crack growth. In more recent work, Pelloux and McClintoch have found that particles (dirt) are beneficial and that low purity alloys outperform high purity alloys at low ΔK values. In the present investigation, insufficient crack growth rate data were generated at low ΔK values to provide a good comparison between the higher purity 7475 and lower purity 7075 aluminum alloys.

3.2 Titanium Alloy 6A1-4V Beta Annealed Results

The test program for the Ti-6Al-4V beta annealed alloy is summarized in Table 11. Mechanical property and fracture toughness data are reported in Section 2.1 Results of the stress corrosion cracking and corrosion fatigue tests are described in this section.

3.2.1 Stress Corrosion Cracking Tests

Two preliminary stress corrosion cracking tests were conducted to measure the relative susceptibility to SCC of the RW and WR crack propagation directions in the 6A1-4V beta mill annealed (β A) titanium alloy plate. Two DCB specimens (Figure B7) were wedge loaded and tested in 3.5% NaCl solutions for 120 hours. For the WR direction, the crack grew 0.47 inch while the stress intensity factor decreased from the initial value of 78 ksi $\sqrt{\text{in}}$; for the

Table 11: Test Program for Ti-6AI-4V Beta Annealed

1 " " 1 "

		٨:									É	ENVIRONMENT	Ž	Ē	_		1			ł			
	E SIWEN	ONENC IC		4	AIR	ο ¾	DISTILI	DISTILLED WATER		3.5% NaCI SOLUTION	Ç Ö		4		10 F	SUMP		4	JP-4+H20	Q	6	DYE PEN	Z
TEST	SPEC	CYCI	IRTS TAR	-92E	72F	196F 176F	725	196F	-65F	72F	136F	-65F	72F	136F	-65F	72F	196F	499-	12F	1961	199-	72F	1361
MECHANICAL TENT	TENS.			- 🙀	- #	4	_	_				<u> </u>						t	t		t	T	
FRACTURE	CT			2 ,	,,	2													i	 -			
TOUGHNESS	ry.			~	7	7								~									
STRESS	BCB				2	-	4			2			4			7			4		·	4	
CRACKING	SF				_					-												***	
			0.1		2		-			9			-			7				┢			
	820	8	0.5	7	2		7	~		7	•		7	-		7	-		2			8	
			0.8		_					-													
CORROSION	a C	u	0.1		-		-			-			-										
	}	,	0.5	-	Ç4		7			7			7						7			7	
	SF	09	0.5		2					2													
OVERLOAD T	тосв	60	9.0		2					2							<u> </u>						

RW direction, the crack grew 0.46 inch and the stress intensity factor decreased from 85 ksi \sqrt{in} to 77 ksi \sqrt{in} . It was concluded that the resistance to SCC of the titanium alloy plate was not very sensitive to test direction and it was decided to test the WR direction in the ensuing tests.

Four subsequent stress corrosion cracking tests were conducted including one test in each of the environments of water saturated JP-4 fuel, distilled water, sump tank water, and 3.5% NaCl solution. Specimen configuration is illustrated in Figure B7. The specimens were pin loaded in a test machine with the crack tip submerged in the test medium and a clip gage was used to monitor maximum crack surface displacement during the loading process. After the desired crack displacement was attained, a pair of circular wedges were inserted in the central hole to wedge open the crack. The specimens were then transferred to test chambers filled with the proper medium and were left there for a period of 506 hours. Periodic observations of crack length showed that no crack growth occurred in any of the test media except 3.5% NaCl solution where a trace of growth was observed. Test results are summarized in Table 12. The result for the 3.5% NaCl solution is in good agreement with the preliminary tests where an apparent K_{ISCC} of 70 ksi \sqrt{in} was measured for the WR direction of the Ti-6Al-4V beta annealed plate.

3.2.2 Corrosion Fatigue Tests

Test variables included environment, cyclic frequency, specimen type and stress ratio. The effects of environment, frequency, and specimen type on fatigue crack propagation behavior are described in this section. Stress ratio effects are described in Section 4.6.

All data collected from corrosion fatigue tests of the Ti-6Al-4V beta annealed alloy are included in Figure Al7 through A32 in Appendix A. In the body of the report, only a limited amount of actual data are shown. For the most part, effects of test variables are illustrated using average curves drawn through the data.

Table 12: SCC Test Results for Ti-6AI-4V Beta Annealed Plate (WR Direction)

SPECIMEN	TEST ENVIRO	NMENT	INITIAL APPLIED K	INITIAL CRACK	FINAL CRACK	COMMENTS
SPECIMEN	MEDIUM	TEMP (°F)	(KSI √IN.)	LENGTH (IN.)	LENGTH (IN.)	COMMENTS
TS-2	JP-4 FUEL	72	79.6	1.96	1.96	NO GROWTH
TS-1	DISTILLED WATER	72	82.5	1.98	1.98	NO GROWTH
TS-3	SUMP TANK WATER	72	81.2	1.97	1.97	NO GROWTH
TS-4	3.5% NaCl SOLUTION	72	69.2	2.02	2.02 ⁺	TRACE OF GROWTH

NOTE: ALL TEST DURATIONS WERE 500 HOURS

3.2.2.1 Effect of Test Environment

Test Media

The effects of the five primary test media on fatigue crack growth rate behavior of the Ti-6Al-4V beta annealed plate are shown in Figures 45 through 49. Average crack growth rate curves in Figure 45 show a consistent effect over the entire range of ΔK values tested. The least aggressive media were desiccated air and water saturated JP-4 fuel and the most aggressive medium was 3.5% NaCl solution. The ratio of maximum to minimum crack growth rates at a given value of ΔK increased from 1.6 to 100 as ΔK decreased from 60 ksi $\sqrt{\text{in}}$ to 14 ksi $\sqrt{\text{in}}$. This ratio is difficult to evaluate at the low ΔK values due to the steepness of the crack growth rate curves. Nevertheless, these data show a large effect cf test media or crack growth rates at the low ΔK values. Current calculations indicate that crack growth rates in the range of 10^{-7} to 10^{-5} inch/cycle are of prime interest in calculating crack propagation lives for military aircraft components. Hence, the media with which the components come in contact could have a serious effect on crack growth behavior and some serious thought must be given to potential problems due to environmental exposure.

Since 3.5% NaCl solution is a severe representation of the "worst" corrosive operating environment for airframe components, sump tank water is currently being used in some aircraft development programs as being representative of the "worst" environment. The crack growth rate curves in Figure 45 show that sump tank water is indeed less aggressive than 3.5% NaCl solution, particularly at the low ΔK values. For example, at $\Delta K = 12$ ksi \sqrt{in} , these tests yielded a ratio of crack growth rate in 3.5% NaCl solution to crack growth rate in sump tank water of five. This ratio gradually decreased to 1.4 at $\Delta K = 40$ ksi \sqrt{in} . Previous work (8) has shown that the chloride ion content of the test medium is a key factor in determining the crack growth resistance of titanium alloys. This observation is substantiated by the result that the 3.5% NaCl solution was more aggressive than sump tank water. Hence, some thought should be given as to how concentrated chloride ions can become in potential crack locations.

Two tests were conducted in an alternating distilled water and JP-4 fuel environment at 72F. The resulting data are plotted in Figures 50 and 51 along with comparable average crack growth rate curves for both distilled water and




Figure 45: Effect of Environment on Fatigue Crack Growth Rates at R=0.1 in 6Al-4V Standard ELI Beta Annealed Titanium Alloy (60 CPM)




Figure 46: Effect of Environment on Fatigue Crack Growth Rates at R=0.50 in 6AI-4V Standard ELI Beta Annexied Titanium Alloy (60 CPM)




Figure 47: Effect of Environment on Fatigue Crack Growth Rates at R=0.80 in 6Al-4V Standard ELI Bata Annealed Titanium Alloy (60 CPM)




Figure 48: Effect of Environment on Fatigue Crack Growth Rates at R=0.10 in 6Al-4V Standard ELI Beta Annealed Titanium Alloy (6 CPM)




Figure 49: Effect of Environment on Fatigue Crack Growth Rates at R = 0.50 in 6Al-4V Standard ELI Beta Annealed Titanium Alloy (6 CPM)




Figure 50: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in Alternating JP-4 Fuel and Distilled Water (60 CPM)




Figure 51: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Bata Annealed Titanium at R = 0.1 in Alternating JP-4 Fuel and Distilled Water (60 CPM)

water saturated JP-4 fuel. All of the data for the alternating environment fall between or very close to the average crack growth rate curves for the individual components of the environment. Hence, alternating the test media had no effect on crack growth rate behavior of the Ti-6A1-4V beta annealed alloy.

A single 72F test was conducted in dye penetrant using a stress ratio of 0.5 and cyclic frequency of 6 cpm. The resulting data in Figure 52 show that type ZL-2A dye penetrant is equivalent to desiccated air in its effect on crack growth rate behavior.

A single 72F test was conducted in distilled water after the crack surfaces had been sprayed with the corrosion inhibitive compound LPS-3 and dried for 3 hours. The test involved a stress ratio of 0.5 and cyclic frequency of 60 cpm. The resulting data are plotted in Figure 53 where it is evident that the data fall close to the average crack growth rate curve for distilled water with no corrosion inhibitor. However, distilled water had only a very mild accelerative effect on fatigue crack growth rates relative to desiccated air and so the corrosion inhibitor would not be expected to have a large effect on crack growth rate behavior in distilled water.

Temperature

Corrosion fatigue tests were conducted at 175F in four environments to evaluate the effects of elevated temperatures on fatigue crack growth behavior of the Ti-6Al-4V beta annealed alloy. The crack growth rate data for all four test media are plotted in Figure 54. Average crack growth rate curves for both 3.5% NaCl solution and desiccated air at 72F are included for comparison. The comparison shows that an increase in temperature from 72F to 175F had little or no effect on crack propagation rates over the range of ΔK values tested. Since increase in temperature usually accelerates chemical reactions and decreases yield strength, it was anticipated that if a temperature increase from 72F to 175F had any effect on corrosion fatigue behavior, it would accelerate crack growth rates. However, data for the 3.5% NaCl solution indicates a decelerative effect of the temperature increase on crack growth rates. However, the apparent deceleration is probably due to data scatter since the magnitude of the effect is less than normal data scatter.




Figure 52: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in Dye Penetrant (Type ZL-2A, 60 CPM)





Figure 53: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in Distilled Water, Crack Surface Sprayed With LPS-3 and Dried for 3.0 Hours Prior to Immersion in Test Media (60 CPM)



"(i).

Figure 54: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Beta Annealed Titanium Alloy at -65F and +175F (60 CPM)

Two tests were conducted at -65F in air to explore the effects of colder temperatures on fatigue crack growth rate behavior in the Ti-6Al-4V beta annealed alloy. The resulting crack growth rate data are plotted in Figure 54 along with the +175F data and average 72F crack growth rate curves for desiccated air and 3.5% NaCl solution. The decrease in temperature from +175 to -65F resulted in a modest deceleration in crack growth rates over the entire range of ΔK values tested. However, the differences between the +175 and -65F crack growth rates are less than those arising from normal data scatter.

3.2.2.2 Effect of Cyclic Frequency

A reduction in cyclic frequency from 60 to 6 cpm had little or no effect on fatigue crack growth rate behavior in three of the four media in which tests were conducted. Data for 6 cpm in desiccated air, distilled water, and JP-4 fuel are plotted in Figures 55, 56 and 57, respectively. Average crack growth rate curves drawn through the corresponding 60 cpm data are shown on the same figures for comparison. Close correspondence between the 6 and 60 cpm data was obtained in all three media. In 3.5% NaCl solution, cyclic frequency had a noticeable effect on fatigue crack growth rate behavior. The 6 cpm salt solution data are plotted in Figure 58 along with average crack growth rate curves for the 60 cpm data. There is a crossover between the 6 and 60 cpm crack growth rate curves at a crack growth rate of about 10-4 inches/cycle. For crack growth rates in excess of 10⁻⁴ inches/cycle, tests at 6 cpm yielded faster crack growth rates than did tests at 60 cpm. For lower crack growth rates, the opposite effect occurred. Reasons for the crossover in crack growth rates curves for 6 and 60 cpm are not immediately obvious. The data indicate that for crack growth rates in the range of primary interest, i.e., from 10⁻⁷ to 10⁻⁵ inches/cycle, cyclic frequencies within the range of interest for airframe components will not significantly influence corrosion fatigue crack growth behavior in Ti-6Al-4V beta annealed.

3.2.2.3 Effect of Specimen Type

Surface-flawed (SF) specimens were tested in both desiccated air and 3.5% NaCl solution using two different peak cyclic stress levels. The resulting crack growth rate data for the WT direction are plotted in Figure 59 along with




Figure 55: Fatigue Crack Growth Astes for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in Desiccated Air (6 CPM)




Figure 56: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in Distilled Water (6 CPM)




Figure 57: Fatigue Crack Growth Rates for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in Water Saturated JP-4 Fuel (6 CPM)




Figure 58: Fatigue Crack Growth Rutes for 6Al-4V Standard ELI Beta Annealed Titanium Alloy in 3.5% NaCl Solution (6 CPM)




Figure 59: Fatigue Crack Growth Rates for "Super EL1" 6AI-4V Beta Annealed Titanium Alloy in 3.5% NaCl Solution (60 CPM)

average crack growth rate curves for the WR direction obtained from tests of DCB specimens. There is excellent agreement between all data for a given environment regardless of crack propagation directions or peak cyclic stress level.

3.2.2.4 Tests of Low O2 (Super ELI) Material

Two corrosion fatigue tests were conducted in 3.5% NaCl solution using DCB specimens cut from the "super ELI" Ti-6Al-4V β A plate described in Section 2.1.3. Oxygen content of the "super ELI" plate was 0.06% as compared to 0.13% for the standard ELI Ti-6Al-4V β A plate tested in this program, and K_{ISCC} values for the super and standard ELI plates were 87 and 69 ksi $\sqrt{\text{in}}$, respectively. The intent of the tests was to measure the effect of 0₂ content on fatigue crack growth rates in an agressive environment.

Crack growth rate data for the super ELI plate are plotted in Figure 60. The scatterband of comparable data for the standard ELI plate are also shown in the same figure. Any differences between crack growth rate data for the two materials were sufficiently small to be considered insignificant.

It had been hoped that the mechanism lending to increased SCC resistance with decreased oxygen content would also lead to similar increases in corrosion fatigue crack growth resistance. However, even though the apparent $K_{\mbox{ISCC}}$ value was higher for the super ELI plate, the corrosion fatigue resistance for both the super and standard ELI grade plates was essentially identical.

The results described above need to be verified before any conclusions with regard to the effect of oxygen content on corrosion fatigue crack growth resistance can be drawn. Chemistry and K_{ISCC} measurements for the super ELI specimens tested in this program were made at locations in the parent plate different from the area from which the test specimens were cut. Hence, chemistry variations within the parent plate could have led to less favorable chemistry in the test samples than was thought to exist.




Figure 60: Fatigue Crack Growth Rate Data for 6AI-4V Standard ELI Bata Annealed Titenium Alloy Surface Flawed Specimens (60 CPM)

3.3 Titanium Alloy 6Al-4V Recrystallize Annealed

The test program for the Ti-6Al-4V RA alloy is summarized in Table 13. Mechanical property and fracture toughness data are reported in Section 2.1 Results of the stress corrosion cracking, corrosion fatigue and thermal processing effect tests are described in this section.

3.3.1 Stress Corrosion Cracking Tests

Five stress corrosion cracking tests were conducted including one test in each of the 72F environments of low humidity air, distilled water, water saturated JP-4 fuel, sump tank water, and 3.5% NaCl solution. Double cantilever beam specimens (Figure B7) were used to conduct the tests. Specimens were loaded to a constant deflection with the crack tip submerged in the test media, and were then placed in the required test media within enclosed chambers. Test results are summarized in Table 14. Periodic observations of crack length over a period of 325 hours showed that no SCC occurred in low humidity air, distilled water or water saturated JP-4 fuel. In both the sump tank water and 3.5% NaCl solutions, stress corrosion cracking intitated at the outset of the test and proceeded at a uniform rate of about one inch per hour until crack growth abruptly stopped. The amounts of SCC observed in the sump tank water and 3.5% NaCl solutions were 0.69 and 0.78 inches, respectively. The calculated $K_{\mbox{TSCC}}$ values were 45 and 61 ksivin for the 3.5% NaCl solution and sump tank water media, respectively. The K_{TSCC} values are 48 and 65 percent of the 72F fracture toughness, respectively.

3.3.2 Corrosion Fatigue Tests

Major test variables included environment, cyclic frequency, thermal processing, and stress rates. A limited number of tests were conducted to evaluate the effects of specimen configuration on crack growth rates. The effects of environment, cyclic frequency, thermal processing, and specimen type on corrosion fatigue crack growth rates are described and discussed in this section. Results of a limited number of crack closure measurements are also included in this section. Stress ratio effects are described in Section 4.6.

Table 13: Test Program for Ti-6AI-4V Recrystallize Annealed

		٨									<u> </u>	Ž	NO.	ENVIRONMENT	5								Γ
	E IMEN	וכ טובעכ		. 4	AJR	0 5	DISTILLED WATER	# E		3.5% Naci SCLUTION			4	_	8 -	SUMP		6 2	JP-4+H20	02	۵	DYE PEN	Z
rest Iqyt	SPEC TYPE	CACL	BAT2 ITAR	-82F	12F	135F	-39- -30-	72F	4871 486	12F	1961	199-	72F	136F	-65F	72F	1361	199-	72F	136F	199-	725	136F
MECHANICAL PROPERTY	TENS.			4	14	4	-	-		-	 -		L					Γ	ľ		T	Ī	
FRACTURE TOUGHNESS	CT SF			2 2	4 2	7 7		·								Ì							
STRESS CORROSION CRACKING	DCB SF				7 -					5 -		<u> </u>	4			7			4			4 **	
	800	99	0.1 0.5 0.8	7	4 7 -			2 1		L 2 L	_		- ~	-		22			7			2	
CORROSION FATIGUE	DCB	9	0.1 0.5		- 2			- 2	<u> </u>	1 2			1 2						7			7	
	SF	60	0.5		2					2											İ		
OVERLOAD	ТБСВ	60	0.5	·	2					2									İ				

Table 14: SCC Test Results for Ti-6Al-4V Recrystallize Annealed Plate (WR Direction)

SPECIMEN	TEST ENVIRO	NMENT	INITIAL APPLIED K	INITIAL CRACK	FINAL CRACK	FINAL K
SPECIMEN	MEDIUM	TEMP (°F)	KSI √IN.	LENGTH (IN.)	LENGTH (IN.)	KSI √TN.
NTSC-4	AIR	72	88.9	2.00	2.00	88.9
NTSC-8	DISTILLED WATER	72	85.9	2.00	2.00	85.9
NTSC-5	JP-4 FUEL	72	84.8	2.00	2.00	84.8
NTSC-6	SUMP TANK WATER	72	85.5	2.00	2.69	60.6
NTSC-7	3.5% NaCi SOLUTION	72	66.0	2.00	2.78	45.0

NOTE: ALL TEST DURATIONS WERE 325 HOURS

All data collected from corrosion fatigue tests of the Ti-6A1-4V RA alloy are included in Figures A33 through A49 in Appendix A. In the body of this report all of the data are not shown. In some cases, average crack growth rate curves are used to represent the data and to illustrate specific effects.

3.3.2.1 Effect of Test Environment

Test Media

The effect of the five primary test media on fatigue crack growth rate behavior is illustrated in Figures 61 through 65. The least aggressive test media were desiccated air and water saturated JP-4 fuel, both of which yielded identical results. The most aggressive media were 3.5% NaCl solution and sump tank water, both of which yielded identical curves up to ΔK values of 24 ksi \sqrt{in} ; at higher ΔK values, the 3.5% NaCl solution resulted in larger crack growth rates than did the sump tank water. Distilled water resulted in a modest acceleration in crack growth rates relative to the air and fuel media. This ratio of maximum to minimum crack growth rates for given ΔK values was relatively constant over the entire range of ΔK values tested and ranged from about 2 at the highest ΔK values to 3 at the lowest ΔK values.

The two potential models of the "worst" environments for airframe components, namely sump tank water and 3.5% NaCl solution, yielded essentially identical crack growth rates over the range of rates believed to be of primary importance to crack propagation life calculations for airframe components, i.e., 10^{-7} to 10^{-5} inches/cycle. The deviation between crack growth rates in the two media occurred when peak stress intensity factors during the loading cycles reached a value of 24 ksi $\sqrt{\text{in}}$. This value of stress intensity factor is about one-half the K_{ISCC} value measured in 3.5% NaCl solution. The relative behavior of the RA processed alloy in the sump tank and salt water media was different from that for the beta processed alloy in that the latter alloy yielded faster crack growth in 3.5% NaCl solution over the entire range of ΔK values tested. This behavioral difference could not be predicted on the basis of the SCC test results.

Five tests were conducted in an alternating distilled water and JP-4 fuel environment at 72F. The resulting data are plotted in Figure 66 along with comparable average crack growth rate curves for both distilled water and water saturated JP-4




Figure 61: Effect of Environment on Fatigue Crack Growth Rates at R=0.1 in 6Al-4V Recrystallize Annealed Titanium Alloy (60 CPM)




Figure 62: Effect of Environment on Fatigue Crack Growth Rates at R = 0.50 in 6Al-4V Recrystallize Annealed Titanium Alloy (60 CPM)




Figure 63: Effect of Environment on Fatigue Crack Growth Rates at R = 0.50 for 6AI-4V Recrystallize Annealed Titanium Alloy (60 CPM)




Figure 64: Effect of Environment on Fatigue Crack Growth Rates at R = 0.10 in 6Al-4V Recrystallize Annealed Titanium Alloy (6 CPM)




Figure 65: Effect of Environment on Fatigue Crack Growth Rates at R = 0.50 in 6Al-4V Recrystellize Annealed Titanium Alloy (6 CPM)




Figure 66: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy in Alternating JP-4 Distilled Water (60 CPM)

fuel. All of the data for the alternating environment fall on or between the average crack growth rate curves for the individual components of the alternating environment. This result is identical to that obtained from tests of the other primary alloys in the alternating environment.

Three 72F tests were conducted in type ZL-2A dye penetrant using a stress ratio of 0.5 and cyclic frequencies of both 6 and 60 cpm. The resulting data are plotted in Figure 67 where it can be seen that cyclic frequency had no effect on crack growth rates and that the dye penetrant was equivalent to the least aggressive environments tested in this program (desiccated air and JP-4 fuel) in its effect on fatigue crack growth rates.

Two tests were conducted in distilled water after the crack surfaces had been sprayed with the corrosion inhibitive compound LPS-3 and dried for 3.0 hours. Tests were conducted at 72F using stress ratios of both 0.1 and 0.5. The resulting crack growth rate data are plotted in Figure 68 along with corresponding average crack growth rate curves for distilled water with no corrosion inhibitor. The data for specimens that were treated with the corrosion inhibitor fall below the average curves and are equivalent to the crack growth rate data obtained from tests in desiccated air. This result is indicative of a beneficial effect on crack growth rates of the corrosion inhibitor. However, previously discussed results for the 7075-T651 aluminum and Ti-6Al-4V beta annealed alloys showed no effect of the corrosion inhibitor or crack growth rate behavior in distilled water. This knowledge combined with the fact that the apparent effect of LPS-3 in Figure 68 is small leads to the speculation that the apparent effect may be due to data scatter rather than the LPS-3.

Temperature

Corrosion fatigue tests were conducted at 175F in four media to evaluate the effects of elevated temperatures on fatigue crack growth behavior of the Ti-6Al-4V RA alloy. The resulting crack growth rate data for all four media are plotted in Figure 69 along with average crack growth rate curves resulting from comparable tests at 72F. In all but the 3.5% NaCl solution, the data for 175F tests fall on or below the 72F crack growth rate curves. In the 3.5% NaCl solution, there was considerable scatter in the data, but the majority of data points fell significantly above the 72F crack growth rate curve; the trend of the




Figure 67: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy in Dye Penetrant (Type ZL-2A, 60 CPM)




Figure 68: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy in Distilled Water, Crack Surfaces Sprayed With LPS-3 and Dried for 3.0 Hours (60 CPM)




Figure 69: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy at -65F and +175F (60 CPM)

data indicates that over the range of crack growth rates of prime importance to airframe life problems, $(da/dN less than <math>10^{-4} inches/cycle)$ an increase in temperature from 72 to 175F would not have any detrimental effect on crack growth rates.

Two tests were conducted at -65F to evaluate this effect of colder temperatures on crack growth rates in the Ti-6Al- 4 V RA alloy. The resulting crack growth rate data are plotted in Figure 69 along with the +175F data. The decreases in temperature from +175 to -65F had no significant effect on crack growth rate behavior over the range of Δ K values tested.

3.3.2.2 Effect of Cyclic Frequency

Tests to evaluate the effect of a reduction in cyclic frequency from 60 to 6 cpm were conducted in the five prime test media at 72F. The crack growth rate data resulting from the 6 cpm tests are plotted in Figures 70 through 74 along with average crack growth rate curves drawn through the 60 cpm data. The effect of a reduction in cyclic frequency from 60 to 6 cpm on crack growth rate behavior was dependent on the test media. In the non-aggressive media of desiccated air and JP-4 fuel, the reduction in cyclic frequency had no detectable effect on crack growth rate behavior as shown in Figure 70 and 71. In the mildly agressive medium of distilled water, cyclic frequency appeared to have a modest effect on crack growth rate behavior. For ∆K values above 30 ksi√in, the 6 cpm crack growth rates tended to be faster than comparable 60 cpm rates; below 30 ksivin, the 6 cpm rates for R=0.5 tended to be slower than comparable 60 cpm rates. However, none of the difference were larger than one normally expects from data scatter. In the more aggressive media of 3.5% NaCl solution and sump tank water, the effect of a decrease in cyclic frequency was to accelerate crack growth rates at ∆K values above about 20 ksi√in by approximately an order of magnititude, and to decelerate crack growth rates below 20 ksivin. This result is an amplification of the trend noted in the distilled water data.

3.3.2.3 Specimen Configuration Effect

Three corrosion fatigue tests were conducted using large "compact" tension specimens having overall dimensions of 1.0 inch thick by 7.2 inch high by




Figure 70: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy in Desiccated Air (6 CPM)




Figure 71: Fatigue Crack Growth Rates for 6Ai-4V Recrystallize Annealed Titanium Alloy in Water Saturated JP-4 Fuel (6 CPM)




Figure 72: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Allay in Distilled Water (6 CPM)




Figure 73: Fatigue Crack Growth Rates for 6AI-4V Recrystallize Annealed Titanium Alloy in 3.5% NaCl Solution (6 CPM)




Figure 74: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy in Sump Tank Water (6 CPM)

8.9 inch long (Figure B12). The specimen arms were sufficiently high that side grooves were not required to restrict the growing crack to its original plane. The resulting crack growth data obtained in low humidity air and 3.5% NaCl solution are plotted in Figure 75 along with average crack growth rate curves obtained in the present investigation. The agreement between the data obtained using large compact tension specimens and the average crack growth rate curves resulting from tests in this program is good.

Two surface-flawed specimens were tested in both desiccated air and 3.5% NaCl solution using two different peak cyclic stress levels. The resulting WT direction crack growth rate data are plotted in Figure 76 along with average crack growth rate curves for the WR direction obtained from tests of DCB specimens. All data for a given environment agree regardless of specimen type and peak cyclic stress level.

3.3.2.4 Crack Closure Measurements

A series of crack closure measurements were made on titanium alloy CT specimens to investigate the crack closure behavior of the CT specimen configuration. These measurements were undertaken as an aid to future investigations concerned with developing fatigue crack growth models, and with the application of laboratory crack growth rate data to the prediction of minimum crack propagation life for full scale components.

Procedures

The crack closure behavior of Ti-6Al-4V RA compact tension specimens was investigated by periodically measuring crack opening displacements near the crack tip in specimens subjected to programmed loads. Specimen configuration is illustrated in Figure B12 in Appendix B.

Specimens were instrumented with clip gages spring loaded against knife edges spot welded to the specimen surface immediately above and below the crack as illustrated in Figure 77. The spot welds were located 0.05, 0.10 and 0.25 inches away from the tip of the crack, and 0.02 inches above the plane of the crack. Gages that were 0.05 and 0.25 inch from the crack tip were located on one side of the specimen with the middle gage on the other side of the specimen. Crack




Figure 75: Fatigue Crack Growth Rates for 6Al-4V Recrystallize Annealed Titanium Alloy (Obtained Using North American Rockwell Specimen Configuration)





Figure 76: Fatigue Creck Growth Rate Date for 6AI-4V Recrystellize Annealed Titanium Alloy Surface Flawed Specimens



Property of the second

Figure 77: Clip Gage Locations For Crack Closure Measurements

opening was recorded as a function of applied load using an X-Y plotter with crack displacement recorded on the abscissa and load recorded on the ordinate.

Specimens were cycled at 72F in air using the loading program illustrated in Figure 78. The loading program involved cycling at three different peak cyclic load levels in a low-high-low-high sequence using a stress ratio of 0.1. During each loading block, the crack was grown over an increment of about 0.2 to 0.3 inches as shown on the abscissa in Figure 78. At the locations in the loading program designated by the letter A, crack closure measurements were repeated three times during the last three cycles of the loading block. At locations designated by the letter B, crack closure measurements were made on the first and second, fifth and sixth, and ninth and tenth cycle of the loading block.

Results

Examples of the crack displacement versus load recordings obtained in these tests are shown in Figure 80. The three recordings were simultaneously obtained during a single loading of the test specimen. The sensitivity of the crack displacement scale was decreased as the gages became further away from the crack tip. This was done so that each recording filled the 11 x 17 inch graph paper. This change in recording sensitivity may have had come influence on the measured values of minimum loads at which the crack was entirely open. This will be discussed in the following evaluation of results.

The minimum value of load at which the crack was entirely open (P_0) was taken as the load corresponding to the point of tangency between the sloping straight line and curved portions of the test record, as shown in Figure 77. The value of P_0 was used to calculate the minimum stress intensity factors at which the crack was entirely open, K_{op} . In Figure 79, K_{op} is plotted as a function of distance from the crack tip at which the measurement was made (I_0) for each of the three load levels in the loading program. As the load level was increased, there was an increasing tendency for K_{op} to decrease with increase in I_0 . It is believed that this result was due, at least in part, to the intentional decrease in instrumentation sensitivity with increase in I_0 . The decrease in sensitivity led to lower and lower apparent tangency points between the sloping straight line and curved portions of the diagram and, hence, to lower values of K_{op} . Accordingly, the value of P_0 obtained from the clip gages located 0.05 inch away from the crack tip was used to calculate values of K_{op} .




Figure 78: Loading Program Used For Crack Closure Measurements




Figure 79: Effect of Measurement Location on Apparent Stress Intensity Factor at Onset of Crack Closure




Figure 80: Examples of Crack Displacement Vs. Load Recordings Obtained During Crack Closure Measurements

The values of K appeared to be a constant percentage of the peak stress intensity factor used to generate the crack growth. This is illustrated in Figure 81 where the three data points obtained in this investigation are included in a scatter hand having the bounds $K_{op} = 0.20 K_{max}$ and $K_{op} = 0.30 K_{max}$. Included in the same figure are comparable results reported by Elber (9), Shih and Wei (10), and Katcher and Kaplan (11). Both the Elber and Shih and Wei results differ considerably from those reported merein. Elber's data were obtained from thin aluminum specimens tested under conditions of net section yielding. Hence, the applicability of Elber's data is questionable. Shih and Wei's results were obtained from tests of 0.2 inch thick Ti-6A1-4V center-cracked panels, whereas the results herein were obtained from 1.0-inch-thick-specimens. The results that Katcher and Kaplan obtained from tests of 1.0-inch thick Ti-6Al-4V RA DCB specimens are in good agreement with the results obtained in this program. The effects of specimen thickness on crack closure behavior have yet to be investigated and it is not known whether or not difference in thicknesss contributed to the disagreements between Shih and Wei's results and those obtained in this program and in (10).

Stress intensity factors at the onset of crack tip closure (K_{op}) showed no tendency to vary with crack length, or during the first ten cycles of high load cycling following lower load cycling. This result is illustrated in Figure 82 where K_{op} is plotted as a function of crack length for the last cycle of the low stress cycling (point A) and the tenth cycle of the subsequent high stress cycling (point B). It is evident that crack length did not affect the value of K_{op} for a given (K_m) , and that K_{op} did not change significantly during the first ten cycles of the high stress cycling. This result is consistent with the transient acceleration in crack growth rates that is often observed immediately after an increase in peak cyclic load.

Discussion

All of the crack closure measurements of which the authors are aware have been made at the surface of test specimens. At the present time, the relationship between surface measurements and conditions at the interior of the specimen are unclear. This uncertainty needs to be resolved before the effects of crack closure on crack growth rate can be determined.




Figure 81: Effect of Peak Cyclic Stress Intensity Factor on Stress Intensity Factor at the Onset of Crack Closure




Figure 82: Effect on Crack Length and Load Increase on Stress Intensity Factor at Which Crack Closure Occurs

It appears that stress ratio effects on fatigue crack growth rate behavior do not result solely from crack closure effects. If surface measurements are accepted as being representative of average conditions throughout the thickness of the specimen, the crack would be expected to remain open at all times for stress ratios in excess of about 0.2 to 0.3, and stress ratio effects would not be observed for stress ratios above this range. However, the data in this report and in the literature demonstrate that stress ratios above 0.3 have a significant effect on fatigue crack growth rate behavior.

Summary

The crack closure measurements made in this program showed that:

- Crack closure at the specimen surface occurs during fatigue crack growth testing for R ratios below about 0.25 in Ti-6A1-4V RA compact tension specimens.
- After sufficient uniform stress cycling to stabilize conditions, the onset of crack closure occurs at a stress intensity factor value that is a reasonably constant percentage (about 25%) of the peak cyclic stress intensity factor.
- Crack closure behavior is independent of crack length for long cracks.
- After an increase in peak cyclic load, it takes more than ten uniform load cycles before the closure load starts to increase to the new value associated with the higher peak cyclic stress level.

3.3.2.5 Thermal Processing Effects

Tests were conducted to evaluate the effects of variations in metallurical characteristics imparted to the Ti-6Al-4V RA alloy by various thermal cycles. The original intent was to evaluate the effects of grain size and cooling rate on the fracture and crack growth resistance properties of this alloy. Small

plates were heated to temperatures near the beta transus and were slow cooled to grow the primary alpha grains. The plates were then reheated to 1400F and either air cooled or slow cooled at 50 F/hour to study effects of possible ordering of the alpha phase of the material. However, the thermal cycles used to cause grain growth also resulted in large variations in microstructure throughout each of the plates from which the test specimens were cut. The microstructural variations had a large influence on fracture and crack growth resistance as described in the following paragraphs.

Metallurgical Effects

Various thermal cycles were employed on $1 \times 10 \times 14$ inch plates of Ti-6Al-4V RA plate material to achieve alpha phase grain growth. Initial trials involved heating the material near the predicted beta transus and slow cooling the the alpha-beta temperature range. The beta transus of the material was predicted to be 1790F utilizing ingot composition and an empirical relationship. The following thermal cycle was employed:

1775F 1 hr Furnace Cool at 50F/Hr to 1400F. Air Cool from 1400F to Room Temperature.

Microstructural examination after heat treatment revealed that all samples had been heated above the beta transus. This was evidenced by a large grained basketweave structure, devoid of equiaxed primary alpha phase.

Next, the beta transus was determined experimentally by microstructural evaluation of samples heated to various temperatures and was found to be $1793 \pm 10F$.

A second set of plates were heat treated using the same thermal cycle except that a thermocouple was placed between the plates during heat treatment. Microstructural examination of samples cut from the corners of the plates after heat treatment indicated that two of the plates had been heated above the beta transus and the third plate had not. Grain size measurements indicated that the equiaxed slpha grain size had increased 50% in the third plate. Two of the

plates, designated 33 (alpha-beta) and 44 (basketweave) were then exposed to the following additional thermal cycle:

1400F 1 Hr Furnace Cool at 50F/Hr to 900F


This cycle was expected to result in higher stress corrosion susceptibility than observed in the as-received plate and to allow a comparison of results for both the basketweave morphology and the alpha-beta morphology.


A cyclic thermal treatment was employed on additional material in an attempt to grow the primary alpha grains by more than 50%. Metallurgical samples were exposed to the following cyclic thermal treatment:


1770F 45 minutes then cycled between 1600F and 1770F for 6 hours. 1700F for 16 hours (overnight) and heated to 1770F for 10 minutes and furnace cooled at 25F/hr to 1650F, then 100F/Hr to 1400F, then air cooled from 1400F to room temperature.

Grain size measurements on the metallurgical samples indicated an increase in alpha grain size of nearly 100%. Based on these results, two additional 1 x 10 x 14 inch plate samples were given the above cyclic thermal treatment to achieve large alpha grains. The plate samples, designated 55 and 66, were heat treated in a similar manner except that the increased sample size and larger furnace required slower heat-up and cool-down rates. To assure adequate temperature control, three thermocouples were used to monitor temperatures. The test plates were stacked in the furnace with an additional 1-inch thick plate on top to minimize furnace temperature variations. Subsequently, sample 55 was heated to 1400F-one hour and air cooled, and sample 66 was furnace cooled from 1400F at 50F/hr to 900F and then air cooled.

Subsequent metallurgical examination of samples cut from corners of the plates and examination of the fracture faces of various test specimens revealed that the microstructure varied throughout each plate as shown in Figure 83. Some regions in each plate had large transformed beta grains (basketweave morphology)







LEGEND:

MORPHOLOGY	SYMBOL
BASKETWEAVE	***
ALPHA-BETA	*******
BASKETWEAVE CENTER ALPHA-BETA EDGES	****

SPECIMEN TYPE	IDENTIFICATION
DCB (CORROSION FATIGUE)	A
DCB (STRESS CORROSION)	В
CT (FRACTURE TOUGHNESS)	С
TENSILE	D

Figure 83: Cutting Diagrams and Microstructural Variations for Thermally Cycled Ti-6Al-4V RA Plates

with the remaining regions composed of equiaxed alpha-beta morphology. Examples of alpha-beta microstructure and basketweave microstructure showing large primary alpha grains are shown in Figure 84 and 85, respectively. An example of variation in microstructure within a given plate is demonstrated in Figure 86 where both basketweave and equiaxed alpha-beta morphology in plate 66 are shown. Since the equiaxed alpha microstructure occurred in regions near the original plate surfaces, the difference in microstructure is most likely a result of compositional differences. Lower oxygen and aluminum content in the center of the plate would lower the beta transus temperature in that area. If microstructural variations had been caused by temperature variations within the plate during heat treatment, the surface microstructure would then have been the basketweave morphology. The microstructural variations within each plate sample necessitated an examination of the fracture face of each test specimen so that it could be categorized with respect to microstructure.

A dramatic change in crystallographic texture was observed with the change in microstructure. Basal plane pole figures were determined for specimens 44CF-1 (from plate 44). The texture for the equiaxed alpha microstructure of specimen 44CF-1 (Figure 87 and Table 15) compares favorably with that of the asreceived material. The majority of basal planes were oriented normal to the transverse direction. The texture for the basketweave microstructure of specimen 44CF-2 (Figure 88 and Table 15) was extremely different with about 60% of the basal planes oriented normal to the longitudinal direction. This was the most severe texture encountered to date at Boeing for a thermally produced basketweave microstructure.

Effects on Mechanical Properties

Mechanical properties for the four plates used to fabricate test specimens are listed in Table 16. The specimens used to measure longitudinal and transverse grain properties were cut from different locations within each plate and in three of the four plates, the specimen from a single plate exhibited markedly different microstructures. All transverse specimens had a basketweave microstructure with the majority of the basal planes oriented normal to the long-itudinal direction. Hence, ultimate and yield strengths for the transverse

Figure 85: Basketweave Microstructure of Tr-6AI-4V Specimen 44K-1 (200X)






Figure 84: Equiaxed Alpha-Beta Microstructure of Tr-6AI-4V, Specimen 55K-1 (200X)





CONTOUR LINES	1	2	3	4	5	6	7	8	9	0
TIMES RANDOM INTENSITY	0.5	1.0	1.5	2.0	4.0	8.0	14.0	20.0	25.0	30.0

Figure 87: Basal Plane Pole Figure for Equiaxed Alpha-Beta Microstructure Resulting from Cyclic Heat Treatment of Plate 44



CONTOUR LINES	1	2	3	4	5	6	7	8	9	0
TIMES RANDOM INTENSITY	0.5	1.0	1.5	2.0	4.0	8.0	14.0	20.0	25.0	30.0

Figure 88: Basal Plane Pola Figure for Basketweave Microstructure Resulting from Cyclic Heat Treatment of Plate 44

Table 15: Quantitative Texture Factors and Moduli for Ti-6Al-4V Alloy Subjected to Various Thermal Cycles

	HEAT	TEXT	JRE FAC	TORS*	MODU	LI (KSI X	10-3)**
MATERIAL	TREATMENT	%1L	%I _T	%I _{ST}	E _L	ET	EST
Ti-6AI-4V (PLATE 44) EQUIAXED ALPHA MICROSTRUCTURE	CYCLED FROM 1600F + 1700F FOR ~ 12 HRS AND FURNACE COOLED	29.6	44.1	26.3	15.8	17.0	15.6
Tigal-4V (Plate-44) Basketweave Microstructure	SAME AS ABOVE	59.5	16.7	23.8	18.2	15.1	15.5
Ti-6AI-4V RA EQUIAXED ALPHA-BETA MICROSTRUCTURE	AS RECEIVED	34.0	41.2	24.8	16.2	16.7	15.5

^{*}SEE TABLE 6

Table 16: Mechanical Property Test Results at 72F for Ti-6Al-4V Plate Subjected to Various Thermal Cycles

PLATE NO.*	MICROSTRUCTURE	GRAIN DIRECTION	ULTIMATE TENSILE STRENGTH (KSI)	YIELD STRENGTH 0.2% OFFSET (KSI)	ELONGATION IN 2.0 IN (%)	REDUCTION IN AREA (%)
33	ALPHA-BETA BASKETWEAVE	LONGITUDINAL TRANSVERSE	129.6 120.1	120.9 108.5	8 8	33 25
44	BASKETWEAVE BASKETWEAVE	LONGITUDINAL TRANSVERSE	133.3 121.8	125.2 110.4	8 5	25 17
55		LONGITUDINAL TRANSVERSE	138.1 133.3	127.6 117.8	7 4	24 12
66		LONGITUDINAL TRANSVERSE	136.3 126.2	125.0 115.0	8 7	25 22

^{*}SEE SECTION 3.3.2.4 FOR DETAILS OF THERMAL PROCESSING

^{**}CALCULATED FROM X-RAY POLE FIGURE INTENSITIES

direction tended to be lower than for the longitudinal direction. The anistropy in strength is best illustrated by the results for plate 44 that were obtained from specimens having similar microstructures. In plates 33, 55, and 66, the longitudinal specimens had an alpha-beta microstructure with little texturing.

The additional thermal processing of the as-received Ti-6Al-4V RA plate had no effect on the tensile strength values as long as the alpha-beta microstructure was retained. However, both elongation and reduction in area were reduced by the additional thermal processing regardless of microstructure. This reduction was greatest for the transverse direction of the transformed basketweave microstructure.

Results of static fracture toughness tests for the WR direction of the four test plates are included in Table 17. Again, the microstructure of test specimens varied. For specimens having an alpha-beta microstructure, fracture toughness values tended to be slightly higher than the values of 90.4 and 94.6 ksi\sqrt{in} measured for the as-received plate. For specimens having a basketweave microstructure, fracture toughness was noticeably greater than for the alpha-beta specimens. These results are typical since beta processed titanium alloys normally tend to have higher fracture toughness than comparable alpha-beta processed alloys, although the as-received materials for this program had comparable fracture toughness values.

Effects on Susceptibility to Stress Corrosions Cracking

Results of stress corrosion cracking tests of specimens taken from each of the four thermally cycled plates are listed in Table 18. Microstructural characteristics of the various specimens had a significant influence on test results. The specimen cut from plate 33 had the microstructure pictured in Figure 86; the central 0.5 inch thick band of the plate had a basketweave microstructure and the outer 0.15 each thick bands had an alpha-beta microstructure. The fracture surface of the test specimen is shown in Figure 89. In the WR direction, more SCC, occured in the outer alpha-beta regions of the plate than in the basketweave central zone. In the basketweave region, there was a tendency for

Table 17: Tracture Toughness Test Results for Ti-6Al-4V Subjected to Various (Trema Cycles (WR Direction and CT Specimens)

PLATE * NO.	MICROSTAUCTURE	AVERAGE CRACK LENGTH (IN)	PEAK LOAD (K)	PQ @ 5% OFFSET (K)	K _Q (a) (KSI√IN)
33	BASKETWEAVE	1,277	18.60	16.68	109.9
44	ALPHA-BETA	1,430	13,40	12.69	99.5
55	ALPHA-BETA	1.410	11.82	12.25	95.6
66	BASKETWEAVE + ALPHA-BETA	1.317	16.85	15,44	111.3

^{*}SEE SECTION 3.3.2.4 FOR DETAILS OF THERMAL PROCESSING
(a) SPECIMENS DID NOT MEET ASTM E399-70T THICKNESS REQ'MENTS.

Table 18: SCC Test Results in 72F/3.5% NaCl Solution for Ti-6Al-4V Subjected to Various Thermal Cycles

PLATE*	MICROSTRUCTURE	TEST DIRECTION	INITIAL CRACK LENGTH (IN)	FINAL CRACK LENGTH (IN)	FINAL STRESS INTENSITY FACTOR (KSI√IN)
33	BASKETWEAVE PLUS ALPHA BETA (FIGURE 86)	WR	1.375	1.470	68.3
44	BASKETWEAVE	WR	1.400	(a)	
55	BASKETWEAVE	WR	1.410	(a)	
66	ALPHA-BETA	WR	1.375	1.550	42.9
55	BASKETWEAVE	RW	0.980	1.12	46.3

^{*}SEE SECTION 3.3.2.4 FOR DETAILS OF THERMAL PROCESSING
(a) CRACK GREW PERPENDICULAR TO ORIGINAL PLANE (I.E., IN RW DIRECTION)




Figure 89: Fracture Surface of Stress Corrosion Specimen 33LT-1 (Plate 33)

SCC to occur in the RW directions, i.e., perpendicular to the original crack plane. This result was probably due to the severe texturing of the basketweave material as illustrated in Figure 88. Test specimens cut from plates 44 and 55 both had a basketweave microstructure. There was only a small amount of SCC in each specimen and the SCC that did occur propogated primarily perpendicular to the original crack plane i.e. in the RW direction. Since the majority of the basal planes were normal to the longitudinal direction in the basketweave material, it should be more susceptable to SCC in the RW than in the WR crack propogation direction. Finally the specimen taken from plate 66 had an alpha-beta microstructure with alpha grain size about double that of the as-received plate. This specimen underwent the most SCC of any of the four specimens tested and the apparent $K_{\rm ISCC}$ was 42.9 ksi $\sqrt{\rm in}$ as compared to the $K_{\rm ISCC}$ for the as-received material of 45 ksi $\sqrt{\rm in}$.

In summary only one of the four specimens tested had an alpha-beta microstructure similar to the as-received plate. The grain size in the specimen was about double that of the as-received plate and the specimen had been slow cooled at 50F/hour through the critical temperature range from 1400F to 900F. Neither this moderate increase in grain size or slow cooling had any significant effect on SCC susceptibility of the material. The other three specimens had either a basketweave or mixed basketweave/alph-beta microstructure and were not directly comparable to the as-received plate. The basketweave microstructure was severely textured with the majority of the basal planes oriented normal to the longitudinal direction and was most susceptible to SCC in the RW crack propogation direction.

Effects on Corrosion Fatigue Crack Growth Rates

Corrosion fatigue tests were conducted in 3.5% NaCl solution at 72F on two specimens from each of the four test plates. One of the two specimens was tested under constant peak cyclic load and the other under constant peak cyclic deflection conditions. Results are plotted on graphs of crack growth rate versus ΔK in Figure 90. Again, results were affected by differences in microstructure from specimen to specimen.

The most striking result of the corrosion fatigue test was the wide variation in crack growth rates. At ΔK of 20 ksi√in for instance, crack growth rates




Figure 90: Corrosion Fatigue Crack Growth Rates for Thermal Processing Effect
Tests (6Al-4V Annealed Titanium Alloy in 3.5% NaCl Solution)

varied over one and one-half orders of magnitude. The fastest crack growth rate occured in specimens having an alpha-beta microstructure and the slowest rates for the WR crack propogation direction in specimens having a basket-weave microstructure. However, the basketweave material was highly textured and crack propogation rates for the RW direction were about the same as the fastest rates measured for the WR direction of the specimens having an alphabeta microstructure.

All additional thermal treatments applied to the as-received material had either no effect or a decelerative effect on corrosion fatigue crack growth rate. The crack growth rate curve for the as-received material is included in Figure 90 for comparison and lies on or above all but three data points. Data points indicated by solid circles, open triangles, and open diamonds in Figure 90 were obtained from specimens having an alpha-beta microstructure with grain size about double that of the as-received material, and were slow cooled at 50F/hour through the critical temperature range. Neither the increased grain size nor slow cooling had a detremental effect on crack growth rate under the conditions existent in these tests. There is always the possibility that if cyclic speed had been slower, or if composition of the material had been different within specification limits, that an acceleration in crack growth rates due to increased grain size or slow cooling would have been observed. However, these tests indicate that for conditions representative of gust loadings in aircraft structure, the effects of overheating or slow cooling of Ti-6Ai-4VRA material will not be detrimental to crack propogation life of the components.

Summary

Specimens of Ti-6Al-4V RA material were heated near the beta transus and were slow cooled to: (1) grow the primary alpha grains and (2), result in ordering of the alpha phase. Mechanical property, fracture toughness, stress corrosion cracking, and corrosion fatigue tests were conducted to determine the effects of grain size and ordering an fracture and crack growth resistance. After testing was underway, it was discovered that the thermal processing had resulted in wide variations in microstructure within each test plate. Both Alphabeta and basketweave microstructures were observed throughout each test plate.

Both alpha-beta and basketweave microstructures were observed throughout each test plate. Alpha grain size varied from 1.5 to 2 times that of the as-received material but no ordering was detected by thin foil electron diffraction microscopy. The basketweave material was extremely textured with about 60% of the basal planes oriented perpendicular to the longitudinal direction.

Differences in microstructure had the largest effect on fracture and crack growth resistance. In the WR crack propagation direction, the textured basketweave material had superior fracture toughness, SCC resistance, and corrosion fatigue resistance. For the RW direction, the SCC and corrosion fatigue resistance of the basketweave material was nearly the same as for the as-received Ti-6Al-4V RA plate. A significant result was that none of the potentially detrimental thermal processing applied to the Ti-6Al-4V RA material degraded the fracture and crack growth resistance properties of the as-received material which is believed to be representative of high quality Ti-6Al-4V RA alloy plate.

3.4 Steel Alloy Test Results

The test program for 9Ni-4Co-0.3C (240 ksi) steel alloy plate is summarized in Table 19. Mechanical property and fracture toughness tests were conducted for both the longitudinal (RW) and long transverse (WR) directions. Stress corrosion cracking tests were conducted for the short transverse (TR) and WR crack propagation directions. Corrosion fatigue tests were conducted for only the WR direction. Results of mechanical property and fracture toughness tests are reported in Section 2.1. Results of the stress corrosion cracking and corrosion fatigue tests are described in the following sections 3.4.1 and 3.4.2.

3.4.1 Stress Corrosion Cracking Tests

Six stress corrosion cracking (SCC) tests were conducted including five in distilled water and one in water saturated JP-4 fuel. The distilled water tests included four tests for the WR crack propagation direction and one test for the TR crack propagation direction.

Results of tests conducted in distilled water are plotted in Figure 91. The specimen was wedge loaded to generate a stress intensity factor of 80 ksi $\sqrt{\text{in}}$.

Table 19: Test Program for 9Ni-4Co-0.3C (240 KSI) Steel Alloy Plate

		٨									E	ĬŽ	ENVIRONMENT	Ē								
	E	JUENC IC		₹	AIR	ο ¾	DISTILLED WATER	LED.		3.5% NaCI SOLUTION	υδ	-7	4 4		ਲ ≥	SUMP	-	P-4+H20	1 H 2		DYE PEN	<u>a</u>
TEST	SPEC Iqyt	CACE	BAT2 ITAR	-66F	326	1921 1981	72F	135F	199-	72F	136F	199-	72F	136F	499-	72F	78F1	-65F	72F	136F	488-	72F
MECHANICAL	TENS.			- 8	- 8	8	_	_							 	t		F	F		-	†
FRACTURE	CT			2	2	2								_						 	}	ĺ
TOUGHNESS	፠			~	2 2				·										•	~		
STRESS	820					 -	2						-	 		1	-			+		
CRACKING	쌇										····											٠.
			0.1	'	2	-	~	l		7			7	<u> </u>		-	 -		-	\vdash	ľ	1
	BCB	8	0.5		-		y-			-			***			***	-,					
			0.8		***	-					-				-							
CORROSION	370	9	0.1				-			-			-	 		_	-			-	l	
	3	ò	0.5	•	_		***				····		-			1		•				
	ઝ	89	0.5	-							·										ļ	
OVERLOAD	TDCB	. 09	0.5								,											




Figure 91: Stress Corrosion Cracking Velocity Data for 9Ni-4Co-0.3C Steel Alloy in Distilled Water

Crack growth initiated immediately but the crack deviated from its original plane and grew into the specimen arms. It was estimated that the initial crack velocity was about 2 x 10⁻⁴ inches/second as shown by the bar in the upper right of Figure 91. After the initial test, all other specimens were tested without side grooves. A second specimen was wedge loaded in distilled water to generate a stress intensity factor of 32 ksi\sqrt{in} at the crack tip. After an incubation period of about 24 hours, the crack began to grow and the velocity data indicated by the oran circles in the lower part of Figure 91 were taken. The stress intensity factor was then increased to 47 ksi\sqrt{in} after which the rate of crack propagation increased dramatically; the crack propagated in its original plane for only a short distance at a rate of about 2 x 10⁻⁴ inches/second, then rotated into the specimen arm. A third specimen was wedge loaded to generate a stress intensity factor of 40 ksi\sqrt{in} and the crack growth rate data indicated by the open circles in the upper part of Figure 91 were taken.

A single SCC test was conducted for the TR crack propagation direction after considerable short transverse splitting was observed on the fracture faces of corrosion fatigue specimens tested in distilled water. The specimen (Figure B5) was wedge-loaded in distilled water to generate a stress intensity factor of 25 ksi $\sqrt{\text{in}}$. Crack propagation initiated immediately and continued in the original crack plane for a distance of 1.8 inches before the test was discontinued. Periodic measurements of crack length were used to calculate the SCC velocities plotted as solid triangles in Figure 91. It is evident that the TR direction was extremely prone to SCC in distilled water with the apparent K_{TSCC} value being less than 14 ksi $\sqrt{\text{in}}$ or about 13 percent of the fracture tougliness for the WR crack propagation direction.

A single SCC test was conducted in JP-4 fuel. The specimen was initially wedge loaded to generate a stress intensity factor of $47.5 \text{ ksi}\sqrt{\text{in}}$ and tested for five days without any indication of SCC; the stress intensity factor was subsequently increased to 60, 73.2 and 83 ksi $\sqrt{\text{in}}$ for seven, three and 345 days, respectively, without undergoing SCC. It is evident that the JP-4 fuel is a very mild environment for the 9Ni-4Co-0.3C steel alloy.

It had been hoped at the outset of this program that the 9Ni-4Co alloy would yield higher $K_{\rm IC}$ and $K_{\rm ISCC}$ values than comparable strength 4330 alloys. The resulting fracture toughness values were better than those normally obtained from the 4330 alloy at the 220-240 strength level, i.e., $100 + \text{ksi}\sqrt{\text{in}}$ versus 70-80 ksi $\sqrt{\text{in}}$. However, the aqueous environment $K_{\rm ISCC}$ for the WR direction showed no improvement over typical values for 4330 steel. In addition, a particularly severe susceptibility to SCC in the TR direction was observed. However, the latter result was probably influenced by the banding in the particular batch of 9Ni-4Co-0.3C steel alloy plate tested in the program.

3.4.2 Corrosion Fatigue Tests

The program of corrosion fatigue tests for the 9Ni-4Co-0.3C steel alloy plate is summarized in Table 19. Tests were conducted in seven different test media at 72F using three different stress ratios (0.1, 0.5 and 0.8) and two cyclic frequencies (6 and 60 cpm). The effects of these variables on fatigue crack propagation are described in this section.

All crack growth rate data collected for the 9Ni-4Co-0.3C steel alloy is included in Figures A50 through A62 in Appendix A. All data are not shown in the body of the report. Rather, average crack growth rate curves drawn through the data are used to illustrate specific effects.

3.4.2.1 Effect of Test Media and Cyclic Frequency

The effect of test media on fatigue crack growth rates was highly dependent on cyclic frequency. At 60 cpm, tests in seven different media yielded very little variation in crack growth rates as illustrated in Figure 92. The scatter bands in Figure 92 encompass all the crack growth rate data obtained in the seven test media for stress ratios of 0.1 and 0.5. For given AK, the largest ratio of maximum to minimum crack growth ratio was 3 for a stress ratio of 0.5 and crack growth rates near 10⁻⁵ inches/cycle. At 6 cpm, there was a marked effect of cyclic frequency on crack growth rate behavior as shown in Figures 93 and 94. Testing was discontinued before crack growth rates at low AK values were evaluated and the effects of the decrease in test frequency




Figure 92: Envelopes of Average Fatigue Crack Growth Rates for 9Ni-4Co-0.3C Cteel Alloy in Seven (7) Environments (60 CPM)




Figure 93: Effect of Environment on Fatigue Crack Growth Rates at R=0.1 in 9Ni-4Co-0.3C Steel Alloy (6 CPM)




Figure 94: Effect of Environment on Fatigue Crack Rates at R=0.5 in 9Ni-4Co-0.3C Steel Alloy (6 CPM)

were not fully characterized. However, it does appear the the marked acceleration in crack growth rates due to the decrease in cyclic frequency began at K_{max} levels near the apparent K_{ISCC} value of about 26 ksi $\sqrt{\text{in}}$. Below $K_{\text{max}} = .26$ ksi $\sqrt{\text{in}}$, the effect of cyclic frequency on crack growth rates is probably less drastic than the effects shown in Figures 93 and 94.

3.5 • Overload Effect Tests

Thirty overload effect tests were conducted to evaluate the effect of single overloads on subsequent fatigue crack growth rate behavior. Ten tests were conducted for each of three alloys including 7075-T651 aluminum, Ti-6A1-4V beta annealed, and Ti-6A1-4V recrystallize annealed, as summarized in Table 20. Three different peak overload stress intensity factors (K_0) were tested to represent overloads early $(K_0 = 62.5\% \ K_{cr})$, midway $(K_0 = 75\% \ K_{cr})$, and late $(K_0 = 90\% \ K_{cr})$ in the life of an airframe component. The subsequent peak cyclic stress intensity factors (K_{max}) were chosen to yield overload ratios (K_0/K_{max}) of 1.5 and 1.8. Parallel test programs were conducted in desiccated air and 5.5% NaCl solution to evaluate overload effects in both mild and agressive media.


3.5.1 Test Procedures

Overload effect tests were conducted by subjecting tapered double cantilever beam specimens (Figure B13) to loading profiles consisting of two block of uniform load cycles separated by a single overload. All tests were conducted using a cyclic frequency of 60 cpm and stress ratio of 0.5. Specimens were instrumented with clip gages spring loaded against knife edges integrally muchined at the mouth of the crack as shown in Figure B13. The clip gages were used to continuously record crack displacement as a function of loading cycles.

Tests were conducted in both desicnated air and 3.5% NaCl solution. Tescs in desiccated air were performed with the specimen surrounded by a sealed plastic bag containing sufficient desiccant to reduce the relative humidity to about 10%. Tests in 3.5 solution were conducted with the crack tip continuously submerged in the solution.

Table 20: Overload Effects Test Program

ALLOYS	TEST MEDIA	KOVERLOAD (% KQ)	K _{MAX} (% K _{cr})	R	NUMBER OF TESTS
		90	60 50	0.6	12
AI - 7075-T651 Ti - 6AI-4V βA Ti - 6AI-4V HA	DESICCATED AIR 3.5% NaCI SOLUTION	75	{50 41.7}	0.5	12
		62.5	41.7	0.5	6



Multiple tests were conducted on each specimen. Five tests were conducted on each aluminum alloy specimen and either two or three tests were conducted on each titanium alloy specimen. Individual tests included the application of two blocks of uniform load cycles separated by an overload. During the application of each block of uniform load cycles, the crack was grown a distance approximately equal to the value of $(K_0/\sigma_{ys})^2$ where K_0 is the value of peak stress intensity factor during the overload cycle, and σ_{ys} is the yield strength of the material. Different stress levels were used for each successive test and the crack growth that occurred during each block of cycles was identifiable on the fracture surfaces of the test specimens.

3.5.2 Methods for Evaluating Results

Results for overload effect tests were determined both by evaluation of test records of crack displacement versus cycles, and observation of the fracture faces of test specimens. An example of a crack displacement versus cycles record is shown in Figure 95. The initial straight line portion of the record (AB) was obtained during uniform stress cycling prior to application of the overload. An overload was applied at point B and the crack displacement increased to point C during the overload. Uniform stress cycling was then resumed and the curved portion (CD) of the record was obtained. At point D, the test record returned to the straight line DE which was parallel to the initial straight line portion AB. Test records were used to determine: (1) the number of delay cycles caused by the application of the overload, AN, and (2) the crack length over which the effects of the overloads were observed, Δa_d . The value of Δa_d was proportional to $\Delta \delta_d$ which was measured from the test record as shown in Figure 95. The relationship between crack growth that occurred during the overload (Δa) was measured directly from the fracture face of the test specimen. The number of baseline loading cycles that would have been required to growth the crack the same distance that it grew during the overload (ΔN_{Δ}) was calculated by dividing Δa_{Δ} by the average rate at which the crack was growing prior to application of the overload. The relationship of both Δa_{Ω} and ΔN_{Ω} to the test record is shown in Figure 95.




Figure 95: Example of Test Records Obtained From Overload Tests

3.5.3 Results and Discussion

Test parameters and results for each of the Ti-6Al-4V beta annealed, Ti-6Al-4V recrystallize annealed, and 7075-T651 aluminum alloy tests are listed in Tables 21, 22 and 23, respectively. Results obtained from tests in desiccated air are listed in the upper parts of the tables; comparable results from tests in 3.5% NaCl solution are listed in the lower parts of the tables. Individual values of delay cycles (ΔN_d), crack growth caused by the overload (Δa_0), number of baseline cycles that would have been required to grow the crack a distance equal to Δa_0 (ΔN_0), and length of crack over which the overload effect was observed (Δa_d) are listed in the tables.

All tests did not yield results of equal consistency and so the consistency of each set of data have been indicated in the tables of results. Where the consistency was very good, the data were very easy to evaluate and no subjective interpretations were required. When the consistency of the data was poor, subjective interpretations of the data were required and the accuracy with which the values of ΔN_A and Δa_A could be evaluated deteriorated. The majority of the data obtained from titanium alloy tests exhibited good consistency. On the other hand, the aluminum alloy tests yielded fairly inconsistent data. The reason for the inconsistent aluminum alloy data was that only very small changes in crack deflection occurred between the application of the overload and the time at which the crack grew out of the influence of the overload. The plastic zone size for the 7075-T651 alloy was on the order of 0.01 inch as compared to total crack lengths in excess of 2.5 inches. Hence, the change in crack length and crack deflection over which the overload effects occurred were too small to be reliably detected by the instrumentation used in those tests. The plastic zone size for the titanium alloys was on the order of 0.1 inch and the instrumentation was sufficiently sensitive to detect changes in crack growth behavior as the crack traversed the plastic zone formed by the overload. Consequently, most of the following discussion will be directed to titanium alloy data.

In the titanium alloys, environment had a strong effect on the number of delay cycles resulting from the application of an overload. This is illustrated in Figure 96 where delay cycles (AN,) are plotted as a function of overload ratio (K_0/K_{max}) for both titanium alloys. For the Ti-6A1-4V RA alloy, a substantial

Table 21: Results of Overload Effect Tests on 6AI-4V Standard ELI Beta Annealed Titanium Alloy Plate (TDCB Specimens—WR Orientation)

						i	-	-		
ENVIRONMENT	AK KMAX (KSI √IN) (KSI √IN)	KMAX (KSI √IN)	KOVERLOAD (KSI VIN)	K _o	∆N d (~)	ΔN _o (~)	P _P Q	Δ ₂ 0 (IN)	Δa _d 0.2 (K _o /σ _{ys}) ²	CONSISTENCY OF DATA
	19.5	38.9	58.3	1.50	2,600	150	0.067	0.002	1.6	VERY GOOD
	19.5	38.9	6.99	1.80	10,000	770	0.084	0.010	1,4	VERY GOOD
DESSICATED	19.5	38.9	69.3	1.80	11,400	1,900	0.078	0.025	1.3	VERY GOOD
€72F	23.3	46.6	6.63	1.50	2,930	2,380	950'0	0.005	1.0	VERY GOOD
·	23.3	46.6	83.9	1.80	5,050	4,760	0.066	0.010	6.7	VERY GOOD
	28.0	55.9	83:6	1.50	64	290	0.020	ი.01ი	0.2	G000
	19.5	38.9	58.3	1.50	0	110	0	0.003	0	FAIR
	19.5	38.9	69.9	1.80	6,400	110	0.039	0.003	0.7	0000
SOLUTION 6 72F	23.3	46.5	6.69	1.50	1,400	6	0.139	0.005	2.3	VERY GOOD
	23.3	46.6	83.9	1.0	2,840	370	0.056	0.020	0.6	VERY GOOD
	28.0	55.9	83.9	1.50	1,200	230	0.174	0.020	1.9	VERY GOOD

SEE FIGURE 95 FOR DEFINITION OF SYMBOLS

Results of Overload Effect Tests on 6AI-4V Recrystallize Annealed Titanium Alloy Plate (TDCB Specimens—WR Orientation) Table 22:

							1	ا		
ENVIRONMENT	ΔK (KSI √ĪÑ)	KMAX (KSI√ÍÑ)	KOVERLOAD (KSI VIN)	K _o KMAX	(~)	ΔN_o^* (\sim)	Δa _d *	Δ a _o *	Δa_{d} 0.2 (K _o / σ_{vs}^{2})	CONSISTENCY OF DATA
	19.3	38.6	6.72	1.50	3500	100	0.096	0.002	2.3	g009
DEGLOCATED	19.3	38.6	9:69	1.80	7300	400	0.094	0.008	1.5	FAIR
AIR © 72F	23.2	46.4	69.6	1.50	æ 1500	360	(a)	0.010	(e)	0009
	23.2	46.4	83.4	1.80	0029	1260	0.078	0.035	6.0	0009
	27.8	55.6	83.4	1.50	(a)	1100	(a)	0.055	(a)	ROOR
	19.3	38.6	67.3	1.50	450	20	0.124	0.002	3.0	VERY GOOD
3.5% NaC	19.3	38.6	69.6	1.80	299	100	0.042	0.010	0.7	VERY GOOD
SOLUTION @ 72F	23.2	46.¢	69.6	1.50	0 ≈	30	0 ≈	0.005	. 0 ≈	a009
	23.2	46.4	83.4	1.80	099	190	0.183	0.030	2.1	VERY GOOD
	27.8	55.6	83.4	1.50	0≈	450	0 ≈	0.100	0 ≈	FAIR

(a) NOT DETERMINED
(b) ESTIMATED


• SEE FIGURE OF EACH

SEE FIGURE 95 FOR DEFINITION OF SYMBOLS

Table 23: Results of Overload Effect Tests on 7075-T651 Aluminum Alloy Plate TDCB Specimen—WR Orientation

ENVIRONMENT	AK (KSI √ÍÑ)	KMAX V) (KSI √IN)	Koverload (Ksi vín)	K _o	(~)	∆N _o (~)	PPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPP	Δ ₈ ο (Ni)	$\Delta_{\rm sd}$ 0.2 (K _o / $\sigma_{\rm ys}$) ²	CONSISTENCY OF DATA
	4.60	9.20	13.80	1,50	40,000	833	0.035	0.002	5.8	FAIR
	4.60	9.20	16.50	1.80	QN	833	QN	0.002	QN	POOR
DESSICATED	5.50	11.00	16.50	1.50	~25,000	300	0:030	0.001	3.5	POOR
0.72F	5.50	11.00	19.80	1.80	∞4,000	600	€ 0.039	0.002	3.2	POOR
	6.60	13.20	19.80	1.50	•4,000	170	910"0≈	0.001	1.3	POOR
	9.30	13.80	16.60	1.20	3,600	150	0.042	(a) 0.001	4.9	0009
	4.60	9.20	13.80	1.50	8,850	370	906.0	0.002	1.0	POOR
34	4.60	9.20	16.50	1.80	000′8≈	370	≈ 0.024	0.002	3.0	FAIR
SOLUTION © 72F	5.50	11.00	16.50	1.50	3,890	260	0.030	0.002	3.8	FAIR
	5.50	11.00	19.80	1.80	4,800	260	0,040	0.002	3.3	GOOD
	6.60	13.20	19.80	1.50	4,300	140	0.022	0.002	1.8	POOR

(a) ESTIMATE
SEE FIGURE 95 FOR DEFINITION OF SYMBOLS






Figure 96: Effect of Overload Ratio on Delay Cycles for Titanium Alloy Overload Tosts

number of delay cycles were obtained from the tests in desiccated air. However, the presence of the 3.5% NaCl solution reduced the number of delay cycles to near zero. For the Ti-6Al-4V beta annealed alloy, the reduction in numbers of delay cycles due to the 3.5% NaCl solution was less marked than in the Ti-6Al-4V RA plate.

When the peak stress intensity fa tors during the overloads reached 90% of the corresponding critical stress intensity factor, the number of delay cycles for Ti-6Al-4V β A tests was reduced from values of delay cycles obtained from tests having lower peak stress entensity factors. In contrast, the Ti-6Al-4V RA tests did not yield such a trend. These trends are illustrated in Figure 96 where data for three different values of $K_{\rm o}/K_{\rm cr}$ ratios of 0.90 agree with data obtained from tests using $K_{\rm o}/K_{\rm cr}$ ratios of 0.75 and 0.63. For the Ti-6Al-4V β A alloy, the data for overload ratios of 0.9 fall considerably below the data for lesser overload ratios. This result was probably influenced by the ductile tear that occurs during overloads to high percentages of the ultimate load.

Overloads resulted in detrimental as well as beneficial effects. During the application of the overloads, the crack extended considerably more than would have been predicted using uniform stress crack growth rate data. For example, the overload cycle for the test listed on the top line of Table 21 resulted in 0.002 inches of crack growth. The overload cycle had a AK of 38.8 ksi\(\si\)in and stress ratio of 0.33. The uniform load crack growth rate data in Figure A17 yields a crack growth rate of about 10⁻⁴ inch for the overload cycle, i.e., an order of magnitude less than the actual growth. This result is typical of all overloads applied on these tests. An acceleration in crack growth rate during high stress cycles following low stress cycles has been previously observed by several investigators (12, 13).

The change in crack length required to eliminate the effects of the prior overloads (Δa_d) was compared to the size of the plastic zone formed by the overload to see if a consistent relationship between the two quantities existed. Plastic zone sizes were estimated to be 0.2 $(K_o/\sigma_{ys})^2$ (14). Ratios of $\Delta a_d/0.2$ $(K_o/\sigma_{ys})^2$ are listed in the next to last column in the tables. For titanium alloy tests in which a K_o/K_{max} ratio of 1.8 was used, the values of $\Delta a_d/0.2$ $(K_o/\sigma_{ys})^2$ varied

from 0.6 to 2.1 and average 1.1. When a $K_0/K_{\rm max}$ ratio of 1.5 was used, the values varied from 0 to 3 with an average of 1.2. Hence, it appears that on the average, the effects of overloads on subsequent crack propagation ratios are dissipated after the crack has grown approximately one plastic zone size or 0.2 $(K_0/\sigma_{vs})^2$ for plane strain conditions.

The total effect of the overloads on the number of cycles required to grow the crack a given distance is indicated by the quantity $(\Delta N_d - \Delta N_o)$, i.e., delay cycles less the equivalent cyclic damage caused by the overload; this quantity is plotted as a function of the ratio of K_{max}/K_o in Figure 97. It is evident that as K_o approaches K_{cr} , the beneficial effect of overloads decreases rapidly. There is insufficient data to allow easy quantification of the results, but it does appear that overloads do not have a detrimental effect on crack propagation life until the peak overload stress intensity factor (K_o) reaches 90% of the critical stress entensity factor. However, beneficial effects of overloads start to diminish when K_o exceeds about 60-70% of the critical stress intensity factor. More tests are required to firmly establish the aforementioned trends.

Results for the 7075-T651 aluminum alloy in Tablé 23 seem to show trends similar to those observed in the titanium alloy results. The effect of overloads on crack growth rate appeared to be less pronounced in 3.5% NaCl solution than in desiccated air. Also, the beneficial effect of overloads diminished as the peak overload stress intensity factor approached the corresponding critical value.

Several methods of calculating the effect of overloads on subsequent crack growth rate have been proposed (15, 16, 17). The methods due to Wheeler (15) and Willenborg (16) have received the most attention. Unfortunately, a considerable amount of effort would be required to evaluate the results in terms of these methods. A more simple but unpublished procedure for calculating delay cycles due to overloads has been in use at Boeing for some time. The Boeing method was based on data published by Porter (17) and calculates crack growth rate after the application of an overload using the equation

$$\frac{da}{dN} = \frac{da}{dN} = \frac{da}{dN} = \frac{da}{dN} = \frac{\left(\frac{K}{max}\right)^2}{uniform} = \frac{\left(\frac{K}{max}\right)^2}{K_o} = \frac{\left(\frac{K}{o}\right)^2}{for} = \frac{\left(\frac{K}{o}\right)^2}{\sqrt{g}} = \frac{\left(\frac{K}{o}\right)^2}$$




Figure 97: Effect of Peak Overload Stress Intensity Factor on Change in Cyclic Life

Equation 5 was used to calculate delay cycles for the titanium tests and results of the calculation are shown by the solid curves in Figure 96. The agreement between calculations and test data is quite good except for the Ti-6Al-4V β A alloy tests in which $K_o = 0.9 \ K_{cr}$.

Other investigators have reported that during the transient crack growth rate deceleration that occurs after overloads, the maximum deceleration does not occur immediately after the application of the overload; rather, crack growth rates decelerate to minimum values, then gradually accelerate back to the values that would have occurred in the absence of the overload. In the present tests it did appear that maximum crack growth rate deceleration occurred during the first low stress cycle after the overload. However, the instrumentation used was not sufficiently sensitive to accurately detect crack growth rate behavior during the initial cycles after the overload.

3.5.4 Summary

The following observations were made during evaluation of the overload test data:

- The application of overloads resulted in a transient retardation in crack growth rates following the overload. The increase in cyclic life caused by an overload varied with ratio of overload stress to cyclic stress, ratio of overload stress to fracture stress, and test medium.
- The amount of crack growth that occurred during the overloads was significantly greater than the corresponding uniform load crack growth rate for the overload cycle.
- Overloads increased cyclic life up to peak overload to fracture stress (σ_o/σ_c) ratio of 0.9. Extrapolation of the data to higher values of overload ratio led to predicted detrimental effects of overloads. For σ_o/σ_c > 0.9, the beneficial effect of crack growth rate retardation is more than offset by the detrimental effect of crack growth occurring during the overload. Maximum beneficial effects were not realized until (σ_o/σ_c) was decreased to less than about 0.6.

- The beneficial effects of overloads were much greater in desiccated air than in 3.5% NaCl solution. The differences between results for the two media was due to differences in uniform stress crack growth rates for the two media.
- The delay cycles caused by the overloads were predicted with acceptable accuracy by Equation 5.
- The presently available methods of calculating the effect of overloads on crack propagation life maybe unconservative, at least to the extent that accelerated crack growth that occurs during overload is not accounted for. For peak overload to critical stress ratios less than about 0.6, the errors resulting from the accelerated growth during the overload should be negligible.

3.6 Stress Ratio Effects

The effects of stress ratio on crack growth rates were evaluated by plotting ratios of crack growth rate at R=0.5 and 0.8 to crack growth rate a R=0.1 as a function of ΔK . The procedure was followed for each of the four prime alloys and five test media, namely, 7075-T651 aluminum, 9Ni-4Co-0.3C steel, 6A1-4V βA titanium and 6A1-4V RA titanium in desiccated air, water saturated JP-4 fuel, distilled water, 3.5% NaCl solution, and sump tank water. The majority of applicable data were generated at 60 cpm using stress ratios of R=0.1 and 0.5. The resulting stress ratio effects are shown in Figures 98 and 99. There was only a limited amount of data which could be used to evaluate stress ratio effects for R=0.8 and the results are shown in Figure 100. A summary of stress ratio effects for data generated using a cyclic frequency of 6 cpm is included in Table 24, and results are plotted in Figure 101.

The effect of stress ratio on crack growth rates was dependent on the value of ΔK at which crack growth was taking place. For low ΔK values, the rates of increase in crack growth rates with increase in stress ratio tended to large values. This trend was due to the existence of apparent threshold stress





Figure 98: Effect of Stress Ratio on Corrosion Fatigue Crack Growth Rate Behavior of Aluminum and Steel Alloys at 60 CPM







Figure 99: Effect of Stress Ratio on Corrosion Fatigue Crack Growth Rate Behaviors of Titanium Alloys at 60 CPM






Figure 100: Effect of Stress Ratio on Fatigue Crack Growth Rates for Steel and Titanium Alloys in Desiccated Air

Table 24: Summary of Stress Ratio Effects Resulting from 6 CPM Tests

ALLOY	TEST MEDIUM	COMMENTS
7075-T651	AIR JP-4 FUEL (WATER SATURATED) DISTILLED WATER	NOT ENOUGH DATA OVERLAP BETWEEN R = 0.1 AND R = 0.5 TO EVALUATE R EFFECTS
ALUMINUM	3.5% NaCI SOLUTION	SAME AS 60 CPM EFFECTS FOR $\Delta K > 7$ KSI $\sqrt{1N}$. NO DATA OVERLAP BELOW $\Delta =$ 7 KSI $\sqrt{1N}$.
9NL4Co 0 2C	AIR JP-4 FUEL (WATER SATURATED)	NOT ENOUGH DATA OVERLAP TO EVALUATE R EFFECTS. TRENDS INDICATE EFFECT SHOULD BE SAME AS 60 CPM EFFECTS.
9Ni-4Co-0.3C STEEL	3,5% NaCI SOLUTION	DATA FOR BOTH R = 0.1 AND R = 0.5 FALL IN ONE SCATTER BAND BETWEEN △K = 30 AND 45 KSI √IN
	DISTILLED WATER	SEE FIGURE 101
·	AIR	NO DATA FOR R = 0.1
6Al-4V βA TITANIUM	JP-4 FUEL (WATER SATURATED) DISTILLED WATER	SAME AS 60 CPM EFFECTS (FIGURE 99) FOR ∆K ≥ 25 KSI √IN
	3.5% NeCI SOLUTION	SEE FIGURE 101
6Al-4V HA	AIR JP-4 FUEL (WATER SATURATED)	SAME AS 60 CPM EFFECTS FOR ΔK > 25 KSI √IN
TITANIUM	DISTILLED WATER	SEE FIGURE 101
	3.5% NeCI SOLUTION	INSUFFICIENT DATA

Figure 101: Effect of Cyclic Frequency on Stress Ratio Effects in Titanium and Steel Alloys

intensity ranges (ΔK_{th}) near which crack growth rates asymptotically approached very small values. Since ΔK_{th} for R=0.1 was greater than ΔK_{th} for R=0.5, the ratio of crack growth rates at R=0.5 to those at R=0.1 tended to large values when ΔK approached the ΔK_{th} for R=0.1. As ΔK values increased, the effect of stress ratio on crack growth rate decreased to a minimum and then once again tended to large values as ΔK approached K_{cr} (1-R) where: K_{cr} is the appropriate critical stress intensity factor and R is the higher of the two stress ratios for which data is being compared. As ΔK approaches K_{cr} (1-R), crack growth rate are accelerated rapidly due to the onset of ductile tear and, hence, the ratio of crack growth rates at the two different R value increases rapidly.

Test media influenced the effects of stress ratio on crack growth rates in three of the four alloys tested. For the 6Al-4V RA titanium alloy, the effects of stress ratio increased with increasing susceptibility to SCC in the test medium. For the 7075-T651 aluminum alloy, distilled water tests yielded higher stress ratio effects than did the 3.5% NaCl solutions even though the apparent K_I values and stress ratio effects between the two media was not large. In the 9Ni-4Co-0.3C steel alloy, stress ratio effects at a cyclic frequency of 60 cpm in air, JP-4 fuel, 3.5% NaCl solution, and sump tank water were different from these in the other media. For the 6Al-4V β A titanium alloy, test medium had only a small effect on stress ratio effects. In general, the results indicate that stress ratio effects are more severe in aggressive environments than in benign environments. This result is probably due in part to the detrimental effects of aggressive media on both ΔK_{th} and on corrosion fatigue crack growth rates.

Cyclic frequency influenced stress ratio effects for some material/environment combinations as summarized in Table 24 and Figure 102. As stated in the table, there was insufficient data overlap to evaluate R effect, at 6 cpm for several material/environment couples. For other couples, stress ration effects for both 6 and 60 cpm were identical over the range of AK values tested. For Ti-6Al-4V RA in distilled water, Ti-6Al-4V BA in 3.5% NaCl solutions, and 9Ni-4Co-0.3C steel in distilled water, stress ratio effects were larger at 6 cpm than 60 cpm as illustrated in Figure 101. For the titanium alloys, the effect of cyclic frequency on stress ratio effect increased with increasing AK. This result is consistent with SCC behavior where environmental effects

increase with increasing stress intensity factors. On the other hand, the effect of cyclic frequency on stress ratio effects for the steel alloy decreased with increasing stress intensity factor over the range of ΔK values tested.

In summary, stress ratio effects on corrosion fatigue crack growth rates varied considerably from one material/environment couple to another. In general, stress ratio effects were largest for material/environment combinations that were susceptible to SCC. The higher the susceptiblity of the alloy to SCC in the test medium, the greater the stress ratio effects. Environment influenced stress ratio effects by changin values of both apparent ΔK_{th} and crack growth rates. The material/environment couple which exhibited unique behavior was the steel alloy in distilled water. The presence of distilled water resulted in a marked increase in the effect of stress ratio on crack growth rates at low ΔK values and a decrease in stress ratio effect on crack growth rates for moderate ΔK values.

4.0 OBSERVATIONS AND CONCLUSIONS

The following observations and conclusions are based on the results of this program.

4.1 Observations

Alloy

- 1. For the Ti-6Al-4V alloy, beta annealing led to superior stress corrosion cracking and corrosion fatigue crack growth resistance than did recrystal-lize annealing. The beta annealed alloy yielded slower crack growth rates for the WR direction under all test conditions. Both annealing treatments led to similar fracture toughness values for each of the WR and WT directions.
- 2. The 7475-T651 alloy plate had fracture toughness superior to the 7075-T651 alloy plate for the WR crack propagation direction (other directions were not tested). Fatigue crack growth rates for the two alloys in 3.5% NaC1 solution did not differ greatly. There was an indication that the 7475 alloy might have had a higher threshold stress intensity factor in fatigue than the 7075 alloy. However, there were insufficient data to substantiate this indication.
- of suspected improper hot rolling practice and was not considered to be typical of the 9Ni alloy by the producer (Republic Steel). The effect of the banding on test results is unknown. When heat treated to the 240 ksi strength level, the alloy was found to be very susceptible to stress corrosion cracking in aqueous environments. The apparent K_{ISCC} values for the WR and TR crack propagation direction were about 27 and 13 ksi/in, respectively. Aqueous environments also markedly accelerated corrosion fatigue crack growth rates for fatigue cycles having peak stress intensity factors above about 26 ksi/in and cyclic frequencies less than 60 cpm.

Environment

- 4. Of the seven test media (desiccated air, water saturated JP-4 fuel, disstilled water, 3.5% NaCl solution, sump tank water, alternating JP-4 fuel/distilled water, and dye penetrant type ZL-2A), desiccated air and JP-4 fuel were the least detrimental to SCC and corrosion fatigue crack growth resistance; 3.5% NaCl solution and sump tank water were the most detrimental. Fatigue crack growth rates for the alternating JP-4 fuel/distilled water media fell between rates for the individual components of the alternating media. Finally, the effect of dye penetrant on corrosion fatigue cracking was equivalent to that of desiccated air.
- 5. The relative effects of potential models of the "worst" normal operaing environment for airframe components, namely, 3.5% NaCl solution and sump tank water, was dependent on alloy. For the 7075-T651 aluminum and Ti-6Al-4V RA alloys, the effects of the two media were equally detrimental. For Ti-6Al-4V beta annealed, the 3.5% NaCl solution was more detrimental than the sump tank water. For 9Ni-4Co-0.3C steel, the sump tank water was more detrimental than the 3.5% NaCl solution.
- 6. Spraying the crack surfaces of test specimens with the corrosion inhibitive compound LPS-3 prior to test had no significant effect on SCC and corrosion fatigue crack growth resistance.
- 7. Changes in test temperature from -65F to +175F had little or no effect on corrosion fatigue crack g. with rates.

Cyclic Frequency

8. The effect of change in cyclic frequency from 60 to 6 cpm was dependent on alloy/environment couple. Both accelerations and decelerations in crack growth rate at given ΔK values occurred with decrease in cyclic frequency. It is not possible to generalize the frequency effects noted in this program.

Stress Ratio

9. The magnitude of stress ratio effects on corrosion fatigue crack growth rates varied considerably from one material/environment couple to another. In general, increases in crack growth rate with increase in stress ratio were largest for material/environment combinations that were susceptible to SCC. The higher the susceptiblity of the alloy to SCC in the test medium, the greater the stress ratio effects. Environment influenced stress ratio effects by changing values of both apparent ΔK_{th} and crack growth rates. The material/environment couple that exhibited unique behavior was the steel alloy in distilled water. The presence of distilled water resulted in a marked increase in the effect of stress ratio on crack growth rates at low ΔK values, and a decrease in stress ratio effect on crack growth rates for moderate ΔK values.

Crack Propagation Direction

10. Crack growth rates for the WT direction (obtained from tests of surface flawed specimens) and for the WR direction (obtained from tests of double cantilever beam specimens) were in excellent agreement for the two titanium alloys in both desiccated air and 3.5% NaCl solution. In the 7075-T651 aluminum alloy, crack growth rates were slower in air and faster in 3.5% NaCl solution than corresponding rates for the WR direction.

Overload Effects

- 11. The application of overloads resulted in transient retardation in crack growth rates following the overload. The increase in cyclic life caused by an overload varied with ratio of overload stress to cyclic stress, ratio of overload stress to fracture stress, and test medium.
- 12. The amount of crack growth that occurred during the overloads was significantly greater than the corresponding uniform load crack growth rate for the overload cycle.
- 13. Overloads increased cyclic life up to peak overload to fracture stress $(\sigma_0/\sigma_{\rm cr})$ ratios of 0.9. Extrapolation of the data to higher values of overload ratio led to predicted detrimental effects of overloads. For

- $\sigma_{\rm o}/\sigma_{\rm cr}$ >0.9, the beneficial effect of crack growth rate retardation is more than offset by the detrimental effect of crack growth occurring during the overload. Maximum beneficial effects were not realized until ($\sigma_{\rm o}/\sigma_{\rm cr}$) was decreased to about 0.6 or less.
- 14. The benefical effects of overloads were much greater in desiccated air than in 3.5% NaCl solution. The differences between results for the two media were due to differences in uniform load crack growth rates for the two media.
- 15. The delay cycles caused by the overloads were predicted with acceptable accuracy by Equation 5.

Thermal Processing Effects

16. Thermal cycles used to induce grain growth and ordering in the Ti-6A1-4V RA alloy did not degrade either the SCC or corrosion fatigue crack growth resistance of the plate. Some of the thermal cycles resulted in a highly textured basket-weave structure that was most susceptible to SCC in the RW direction. The K_{ISCC} and crack growth rate values for the RW direction were the same as for the as-received material.

4.2 Conclusions

- 1. Testing of double cantilever beam specimens is a very good method of generating fatigue crack growth rate data. However, the resulting data are not always applicable to many practical cracking situations in airframe components. This is particularly true for plate materials that exhibit anisotropy in SCC and corrosion fatigue resistance. In such cases, surface flawed specimen tests must be conducted to evaluate crack growth resistance for the thickness direction.
- 2. Due to the steepness of the crack growth rate versus ΔK correlations at low ΔK values, calculations of crack propagation life for airframe components in which most of the life is consumed by cycling at low ΔK values will be very sensitive to applied stress level.

- 3. For the Ti-6Al-4V alloy, beta processing is superior to alpha-beta processing from the standpoint of fracture and crack growth resistance.
- 4. The use of corrosion inhibitive compounds such as LPS-3 will not necessarily decrease crack propagation rates of cracked airframe components.
- 5. Type ZL-2A dye penetrant is compatible with all alloys tested in this program.
- 6. Service temperatures within the range of +175F to -65F will not have any significant effect on the crack propagation rates in airframe components fabricated from the aluminum and titanium alloys tested on this program. Service temperatures could have some influence on crack propagation life by changing fracture toughness of the component materials.

REFERENCES

- 1. C. F. Tiffany, "Fracture Control of Metallic Pressure Vessels", NASA Space Vehicle Design Criteria (Structures) NASA SP-8040, May 1970.
- L. R. Hall and R. W. Finger, "Stress Corrosion Cracking and Fatigue Crack Growth Studies Pertinent to Spacecraft and Booster Pressure Vessels", NASA CR-120823, National Aeronautics and Space Administration, December 1972.
- 3. S. Mostovoy, P. B. Crosley and E. J. Ripling, "Use of Crack-Line-Loaded Specimens for Measuring Plane Strain Fracture Toughness", Journal of Materials, Vol. 2, No. 3, September 1967.
- 4. R. C. Shah and A. S. Kobayashi, "On the Surface Flaw Problem", The Surface Crack: Physical Problems and Computational Solutions, edited by J. L. Swedlow, ASME, November 1972.
- 5. M. V. Hyatt and M. O. Speidel, "Stress Corrosion Cracking of High Strength Aluminum Alioys", Advances in Corrosion Science and Technology, Vol. 2, edited by M. G. Fontana and R. W. Staehle, Plenum Press 1972.
- 6. L. H. Glassman and A. J. McEvily, Jr., "Effects of Constituent Particles on the Notch Sensitivity and Fatigue Crack Propagation Characteristics of Aluminum-Zinc-Magnesium Alloys", NASA TN D928, National Aeronatuics and Space Administration, April 1962.
- 7. R. M. N. Pelloux, "Fractographic Analysis of the Influence of Constituent Particles on Fatigue Crack Propagation in Aluminum Alloys", Transactions ASM, Vol. 57, 1964.
- 8. M. J. Blackburn, J. A. Feeney, and T. R. Beck, "Stress Corrosion Cracking of Titanium Alloy", Advances in Corrosion Science and Technology, Vol. 2, edited by M. G. Fontana and R. W. Staehle, Plenum Press, 1972.

- 9. W. Elber, "The Significance of Fatigue Crack Closure", ASTM Special Technical Publication 486, 1971.
- 10. T. T. Shih and R. P. Wei, "A Study of Crack Closure in Fatigue", Lehigh University Report No.
- 11. M. Katcher and M. Kaplan, "Effect of R Factor and Crack Closure on Aluminum and Titanium Alloys", presented at Sixth Annual Fracture Mechanics Symposium, Philadelphia, August 1972.
- 12. O. Jonds and R. P. Wei, "An Exploratory Study of Delay in Fatigue Crack Growth", International Journal of Fracture Mechanics, Vol. 7, 1971.
- 13. J. C. McMillan and R. N. M. Pelloux, "Fatigue Crack Propagation Under Program and Random Loads", ASTM Special Technical Publication 415, 1966.
- 14. J. R. Rice, "Mechanics of Crack Tip Deformation and Extension by Fatigue", ASTM Special Technical Publication 415, 1966.
- 15. O. E. Wheeler, "Crack Growth Under Spectrum Loading", Report No. FZM-5602, General Dynamics Corp., Fort Worth Division, June 1970.
- 16. J. Willenborg, R. M. Engle and H. A. Wood, "A crack Growth Retardation Model Using an Effective Stress Concept", Technical Memorandum 71-1FBR, Air Force Flight Dynamics Library, WPAFB, January 1971.
- 17. T. R. Porter, "Method of Analysis and Prediction for Variable Amplitude Fatigue Crack Growth", Eng. Fracture Mech., Vol. 4, No. 4, December 1972.

APPENDIX A TEST DATA

This appendix contains all the detailed test data generated during this program. Included are mechanical property, static fracture toughness and corrosion fatigue data for aluminum alloy 7075-T651 and 7475-T651, titanium alloys 6A1-4V beta annealed and 6A1-4V recrystallize annealed, and steel alloy 9Ni-4Co-0.3C. The location of the various types of data within this appendix is identified in Table A1.

Table A1: Index of Test Data

ALLOY	TYPE OF DATA	LOCATION
ALUMINUM 7075-T651	Mechanical Property Fracture Toughness Corrosion Fatigue	Table A2 Tables A3, A4 Figures A1 Through A15
ALUMINUM 7475-T651	Corrosion Fatigue	Figure A16
TITANIUM 6AI-4V BETA ANNEALED	Mechanical Property Fracture Toughness Corrosion Fatigue	Table A5 Tables A6, A7 Figures A17 Through A32
TITANIUM 6AI-4V RA	Mechanical Property Fracture Toughness Corrosion Fatigue	Table A8 Tables A9, A10 Figures A33 Through A49
STEEL 9Ni-4Co-0.3C	Mechanical Property Fracture Toughness Corrosion Fatigue	Table A11 Tables A12, A13 Figures A50 Through A62

Table A2: Mechanical Property Data for 7075-T651 Aluminum Alloy Plate

GRAIN DIRECTION	TEMPERATURE (°F)	SP⊏CIMEN NUMBER	ULTIMATE TENSILE STRENGTH (KSI)	0.2% OFFSET YIELD STRENGTH (KSI)	ELONGATION IN 2.0 INCH GAGE LENGTH (%)
	72	AL-1 AL-2	86.7 88.1	79.0 81.2	9.9 13.7
LONG.	-65	AL-3 AL-4	93.9 94.2	86.2 86.4	11.6 10.9
	+175	AL-5 AL-6	81.5 81.7	74.2 75.4	14.5 10.6
	72	AT-5 AT-6	89.9 86.8	82.4 78.9	10.6 10.5
TRANS.	-65	AT-3 AT-4	90.2 89.9	80.8 80.9	10.3 10.6
	+175	AT-1 AT-2	80.5 83.0	73.8 75.8	9.2 9.0

Table A3: Fracture Toughness (K_{IC}) Data for 7075-T651 Aluminum Alloy Plate

SPECIMEN TYPE	ORIENTATION	TEMP (°F)	K _{Ic} (KSI √IN.)
COMPACT TENSION	WR	-65	21.0 21.8
COMPACT TENSION	WR	+72	23.1 22.4
COMPACT TENSION	WR	+175	24.0 24.4
DCB (FIG. 1)	WR	+72	22.8 22.4 21.9 21.8 22.2
DCB (FIG. 1)	RW	+72	31.5 32.0

Table A4: Static Fracture Data for 7075-T651 Aluminum Alloy SF Specimens

SPECIME	N GAGE	FL	ΑW		LOA	D AT	APPROX
WIDTH (IN.)	THICKNESS (IN.)	DEPTH, a (IN.)	WIETH, 2c (IN.)	TEST TEMP (°F)	POPIN (K)	FAILURE (K)	WT FRACTURE TOUGHNESS* (KSI √IN.)
3.00	0.404	0.170	0.708	+72	53.7	56.0	31.7
3.00	0.402	0.172	0.717	+72	56.3	58.6	33.6
3.00	0.405	0.172	0.720	-65	50.1	52.8	29.9
3.00	0.401	0.174	0.718	-65	49.6	55.0	31.6
3.00	0.404	0.177	0.715	+175	58.3	60.2	34.8
3.00	0.403	0.176	0.715	+175	58.2	59.8	34.7

^{*}FRACTURE TOUGHNESS = $1.1\sigma\sqrt{\pi a/Q}$

Table A5: Tensile Properties of 6AI-4V Beta Annealed Titanium Alloy Plate

SPECIMEN NUMBER	DIA (IN.)	AREA (IN.2)	TEST ENVIRONMENT	TEST TEMPERATURE(^{OF)}	ULTIMATE STRENGTH (KSI)	0.2% OFFSET YIELD STRENGTH (KSI)	ELONGATION (% PER 2.0 INCHES)	REDUCTION IN AREA (%)
TBL-1	0.2479	0.0483		72	133.6	124.2	10	20
TBL-2	0.2496	0.0489		72	133.5	123.3	10	22
TBL-3	0.2501	0.0491	AIR	-65	152.4	145.8	7	18
TBL-4	0.2506	0.0493		-65	152.4	143.9	8	19
TBL-5	0.2499	0.0490		175	121.7	108.5	10	27
TBL-6	0.2501	0.0491		175	121.4	108.3	10	26
TBT-1	0.2498	0.0490		72	133.8	123.8	10	24
TBT-2	0.2494	0.0489		72	133.8	121.6	10	24
TBT-3	0.2499	0.0490	AIR	-65	152.3	144.6	8	22
TBT-4	0.2497	0.0490		-65	152.3	143.2	8	20
TBT-5	0.2489	0.0487		175	121.6	107.5	12	27
TBT-6	0.2498	0.0490		175	122.1	109.1	12	27

Table A6: Static Fracture Toughness Data for 6AI-4V Beta Annealed Titanium (CT Specimens)

SPECIMEN NO.	TEST TEMP (^O F)	AVERAGE CRACK LENGTH (IN.)	PEAK LOAD (K)	PQ 5% OFFSET (K)	K _Q KSI √IÑ.
T5	65	1.290	15.12	14.62	93.0
T6	65	1.327	14.12	13.68	92.0
T1	72	1.385	13.07	12.55	91.0
T2	72	1.272	16.02	15.34	95.5
T3	+175	1.288	17.36	15.95	101.4
T4	+175	1.267	17.15	15.53	95.8

Table A7: Static Fracture Data for GAI-4V Beta Annealed Titanium Surface-Flawed Specimens

	SPECIME	N GAGE	FL	AW			
SPECIMEN NUMBER	WIDTH (INCH)	THICKNESS (INCH)	DEPTH, a (INCH)	WIDTH, 2c (INCH)	TEST TEMP (°F)	FAILURE LOAD (KIPS)	APPROXIMATE WT FRACTURE TOUGHNESS (KSI √IN.)
TBS-5	3.4995	0.3238	0.210	0.885	-65	140.4	103.6
TBS-4	3.5008	0.3196	0,210	0.885	-65	140.4	106.0
TBS-1	3.4975	0.3332	0.213	0.905	+72	121.8*	>87.5
TBS-2	3.4994	0.3272	0.206	0.885	+72	129.6	95.2
TBS-3	3.4992	0.3253	0.208	0.890	+175	119.7	89.3
TBS-6	3,4980	0.3304	0.216	0.890	+175	117.3	86.5

^{*}SPECIMEN FAILED AT GRIP

Table A8: Mechanical Property Measurements for 6AI-4V Recrystallize Annealed Titanium 1.0-Inch Thick Plate

GRAIN DIRECTION	TEMP (^o F)	ULTIMATE STRENGTH (KSI)	YIELD STRENGTH (KSI)	ELONGATION IN 2.0 IN. (%)	REDUCTION IN AREA (%)
	175	128.1 128.1	112.5 113.0	12 13	33 37
TRANS.	72	137.0 137.2	125.1 125.8	12 12	39 37
	-65	154.6 154.0	145.1 143.8	10 10	28 29
LONG.	175	128.0		12	28
	72	138.4 137.5	126.2 124.5	13 12	39 37
	-65	153.7 150.7	143.2 141.0	10 10	30 27

Table A9: Static Fracture Toughness Data for 6AI-4V Recrystallize Annealed Titanium Alloy 1.0-Inch Thick Plate (CT Specimens—WR Direction)

SPECIMEN NUMBER	TEST TEMP (°F)	AVERAGE CRACK LENGTH (INCH)	PEAK LOAD (KIPS)	P _Q 5% OFFSET (KIPS)	κ _α (KSI √1 N .)
NTS-1	72	1.333	13.42	12.91	94.6
NTS-2	72	1.333	13.12	12.32	90.4
NTS-3	-65	1.355	11.60	11.20	84.8
NTS-4	-65	1.317	12.00	11.53	83.0
NTS-5	+175	1.327	15.20	13.56	103.7
NTS-6	+175	1.345	14.70	13.88	101.3

Table A10: Static Fracture Data for 6Al-4V Recrystallize Annealed Titanium Alloy Surface-Flawed Specimens

	SPECIMEN GAGE		FLAW				
SPECIMEN NUMBER	WIDTH (INCH)	THICKNESS (INCH)	DEPTH, a (INCH)	WIDTH, 2c (INCH)	TEST TEMP (°F)	FAILURE LOAD (KIPS)	APPROXIMATE WT FRACTURE TOUGHNESS (KSI √IN.)
NTSS-1	3.5023	0.3268	0.217	0.897	-65	138.4	103 [>>
NTSS-2	3.5021	0.3223	0.215	0.890	-65	138.0	103
NTSS-3	3.5022	0.3252	0.215	0.890	+72	126.5	94
NTSS-4	3.5022	0.3262	0.212	0.895	+72	123.8	92
NTSS-5	3.5020	0.3252	0.212	0.890	+175	121.0	91
NTSS-6	3.5017	0.3279	0.210	0.890	+175	120.0	88

SPECIMEN WAS INITIALLY LOADED TO K_{IE} = 106.7 KSI $\sqrt{1N}$. (LOAD = 127.0 KIPS) WITH a = 0.210 INCH, 2c = 0.897 INCH, LOAD DROPPED TO ZERO DUE TO TEST MACHINE FAILURE; SPECIMEN WAS THEN RELOADED.

Table A11: Tensile Properties of Heat Treated 9Ni-4Co-0.3C Steel Alloy

GRAIN	TEMP (°F)	ULTIMATE STRENGTH (KSI)	YIELD STRENGTH (KSI)	ELONGATION IN 2.0 IV. (%)	REDUCTION IN AREA (%)
	175	235.6 235.1	201.2 203.5	8 8	57 57
LONG.	72	244.7 243.2	207.1 209.1	1 1	1 1
·	-65	255.6 256.0	222.5 221.8	7 7	51 46
	175	235.0 235.1	203.2 202.7	8 7	56 51
TRANS	72	239.8 240.1	204.0 203.7	-	_
	-65	254.4 254.7	211.4 215.7	7 7	46 47

Table A12: Fracture Toughness Data for 9Ni-4Co-0.3C Steel Alloy

SPECIMEN TYPE	CRACK TEST PROPAGATION TEMPERATU (°F)		PLANE STRAIN FRACTURE TOUGHNESS (K _{Ic}) (KSI √IN.)	FRACTURE TOUGHNESS (KSI √IN.)
COMPACT TENSION	WR	-65	88.1 86.1	
DOUBLE CANTILEVER BEAM	WR	72	<u>-</u>	107.5 104.5
COMPACT TENSION	WR	175	104.6 105.5	_

Table A13: Static Fracture Data for 9Ni-4Co-0.3C Steel Alloy Surface-Flawed Specimens

	SPECIMEN GAGE		FLAW				
SPECIMEN NUMBER	WIDTH (INCH)	THICKNESS (INCH)	DEPTH, a (INCH)	WIDTH, 2c (INCH)	TEST TEMP (°F)	FAILURE LOAD (KIPS)	APPROX!MATE WT FRACTURE TOUGHNESS (KSI √IÑ.)
SS-3	2.2532	0.3968	0.140	0.565	-65	132.9	91,9
SS-4	2.2618	0.3962	0.138	0.555	-65	140.4	96.0
SS-1	2.2578	0.4000	0.138	0.560	+72	156.9	106.7
SS-2	2.2553	0.4065	0.137	0.560	+72	159.0	106.4
SS-5	2.2564	0.4032	0.138	0.550	+175	160.8	108.7
SS-6	2.2542	0.3967	0.137	0.550	+175	156.9	107.8





Figure A1: Fatigue Crack Growth Rates For 7075-T651 Aluminum Alloy in Desiccated Air







Figure A2: Fatigue Crack Growth Rates For 7075-T651 Aluminum Alloy in Distilled Water







Figure A3: Fatigue Crack Growth Rates For 7075-T651 Aluminum Alloy in 3.5% NaCl Solution







Figure A4: Fatigue Crack Growth Rates For 7075-7651 Aluminum Alloy in Water Saturated JP-4 Fuel






Figure A5: Fatigue Crack Growth Rates For 7075-T651 Aluminum Alloy in Sump Tank Water




Figure A6: Fatigue Crack Crowth Rates For 7075-T651 Aluminum Alloy in Altornating JP-4 Fuel and Distilled Water




Figure A7: Fatigue Crack Growth Rates For 7075-T65! Aluminum Alloy in Dye Penetrant (Type ZL-2A)




Figure A3: Fatigue Crack Growth Rates For 7075-T651 Aluminum Alloy in Distilled Water, Crack Surface Sprayed With LPS-3 and Dried For 3.0 Hours Prior to Immersion in Test Litedia




Figure A9: Fatigue Crack Growth Rates For 7075-T651 Aluminum Alloy in Various Environments at +175F and -65F





Figure: A10: Fatigue Crack Growth Rates For 7475-T651 Aluminum Alloy in 3.5% NaCl Solution and Desiccated Air







Figure A11: Fatigue Crack Growth Rates For 6Ai-4V Standard ELI Beta Annealed Titanium Alloy in Desiccated Air







Figure A12: Fatigue Crack Growth Rates For 6A!-4V Standard ELI Beta Annealed Titanium Alloy in Distilled Water






Figure A13: Fatigue Crack Growth Fiates For 6AI-4V Standard ELI Beta Annealed Titanium Alloy in 3.5% NaCl Solution





Figure A14: Fatigue Crack Growth Rates F v. 6A1-4V Standard EL1 Beta Annealed Titanium Alloy in Water Saturated JP-4 Fuel






Figure A15: Fatigue Crack Growth Rates For 6AL-4V Standard ELI Beta Annealed Titanium Alloy in Sump Tank Water






Figure A16: Fatigue Crack Growth Rates For &AI-4V Standard ELI Beta Annealed Titanium Alloy in Alternating J.9-4 Fuel and Distilled Water










Figure A18: Fatigue Crack Growth Rates For 6AI-4V Standard ELI Beta Annealed Titanium Alloy in Distilled Vlater, Crack Surface Sprayed With LPS-3 and Dried For 3.0 Hours Prior to Immersion in Test Isledia




Figure A19: Fatigue Crack Growth Rates For 6AL-4V Standard ELI Beta Annealed Titanium Alloy in Various Environments at +175F and -65F





Figure A.20: Fatigue Crack Growth Rates For 6AI-4V "Super ELI" (0.06 02 Content) Beta Annealed Titanium Alloy in 3.5% NaCl Solution






Figure A21: Fatigue Grack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in Desiccated Air





Figure A22: Fatigue Crack Growth Hales For 6A!-4V Recrystallize Annealed Titanium Alloy in Distilled Water







Figure A23: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in 3.5% NaCl Solution







Figure A24: Fatigue Crack Growth Rates For 6Ai-4V Recrystallize Annealed Titanium Alloy in Water Saturated JP-4 Fuel






Figure A25: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in Sump Tank Water





Figure A26: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in Alternating JP-4 Fuel and Distilled Water






Figure A27: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in Dye Penetrant (Type ZL-2A)




Figure A28: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in Distilled Water, Crack Surface Sprayed With LPS-3 and Dried For 3.0 Hours Prior to Immersion in Test Media




Figure A.29: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annealed Titanium Alloy in Various Environments at +175F and -65F

CHACK GROWTH RATE, de/dn (INCH/CYCLE)




Figure A31: Fatigue Crack Growth Rates For 6AI-4V (Fast Cooled)
Recrystallize Annealed Titanium Alloy in 3.5% NaCl
Solution and Desiccated Air





Figure A.30: Fatigue Crack Growth Rates For 6AI-4V Recrystallize Annoded Titonium Alloy in 3.5% NaCl Solution and Desiccated Air







Figure A32: Fatigue Crack Growth Fates For 9Ni-4Co-0.3C Steel Alloy in Desiccated Air







Figure A33: Fatigue Crack Growth Rates For 9Ni-4Co-0.3C Steel Alloy in Distilled Water







Figure A34: Fatigue Crack Growth Rates For 9Ni-4Co-0.3C Steel Alloy in 3.5% NaCl Solution






Figure A35: Fatigue Crack Growth Rates For 9Ni 4Co-0.3C Steel Alloy in Water Saturated JP-4 Fuel




Figure A36: Fatigue Crack Growth Rates For 9Ni-4Co-0.3C Steel Alloy in Sump Tank Water




Figure A37: Fatigue Crack Growth Rates For 9Ni-4Co-0.3C Steel Alloy in Alternating JP-4 Fuel and Distilled Water

CHACK GROWTH RATE, dAM (INCH/CYCLE)




Figure A38: Fatigue Crack Growth Rates For 9Ni-4Co-0.3C Steel Alloy in Distilled Water, Crack Surface Sprayed With LPS-3 and Dried For 3.0 Hours Prior to Immersion in Test Media

京美工工 本解學 经加

APPENDIX B TEST SPECIMENS

Thirteen different specimen configurations were used to conduct the tests described in the body of this report. The thirteen configurations are detailed in Figures Bl through Bl3. A summary identifying the particular specimen configuration used for each alloy and test type is presented in Table Bl.



Table B1: Summary of Specimen Configurations Used For Each Type of Test

TEST TYPE	ALLOY	CYCLIC FREQUENCY	SPECIMEN TYPE	CONFIGURATION (Figure No.)	
Mechanical Property	All Alloys	_	Tensile	В1	
Fracture Toughness	All Alloys Aluminum Steel Titanium		CT SF SF	B2 B3 B4	
Stress Corrosion Cracking	All Alloys TR Direction		DCB	B 5	
	Aluminum } Steel		DCB	B 6	
	Titanium		DCB	B7	
	Aluminum Titanium		SF SF	B8 B4	
Corrosion Fatigue Tests	All Alloys All Alloys Aluminum Titanium Titanium	6, 60 900 60 60 60	DCB DCB SF SF CT	89 B10 B8 B11 B12	
Overload	Aluminum Titanium	60	TDCB	B 13	




Figure B1: Tensile Specimen For Mechanical Property Measurements




Figure B2: Compact Tension Specimen Configuration Used For Static Fracture Testing





Figure B3: Surface Flawed Specimen Configuration For 7075-T651
Aluminum Alloy Plate Static Fracture Testing



MATERIAL	W ₁	W ₂	t
9NI-4Co-0.3C STEEL ALLOY	3.00	2.25	0,400
MAI-4V TITANIUM ALLOYS	3.50	3.50	0.325

Figure B4: Surface-Flawed Specimen Configuration




Figure B5: Short Transverse DCB Specimen Configuration Used For Stress Corrosion Testing




Figure 86: DCB Specimen Configuration Used For Stress Corrosion Testing (7075-T651 Aluminum and 9Ni - 4Co - 0.3C Steel Alloys)




Figure B7: DCB Specimen Configuration Used For Stress Corrosion Testing (Titanium Alloys)




Figure B8: Surface-Flawed Specimen Configuratio or 7075-T651
Aluminum Alloy K_{ISCC} and da/dN T. .ing




Figure 89: DCB Specimen Conviguration Used For da/dN and Compliance Yesting




Figure B10: Specimen Configuration Used for da/dN Testing (900 CPM)




Figure B11: Surface Flawed Specimen Configuration Used For Titanium Alloys da/dN Testing




Figure B12: NAR Compact Tension Specimen Configuration




Figure 813: TDCB Specimen Configuration Used For Overload Testing

APPENDIX C COMPLIANCE MEASUREMENTS FOR DOUBLE CANTILEVER BEAM SPECIMENS

Results of tests undertaken to measure specimen compliance as a function of crack length for the 7075-T651 aluminum, 9Ni-4Co-0.3C steel and 6A1-4V beta annealed and recrystallize annealed titanium alloys are described in this appendix. Values of specimen compliance were determined for both the uniform height Double Cantilever Beam (DCB) and Tapered Double Cantilever Beam (TDCB) specimens for the aluminum and titanium alloys, and for DCB specimens for the steel alloy. Values of specimen compliance were used in crack length calculations for the DCB corrosion fatigue tests, and stress intensity factor calculations for the TDCB specimen tests.

Procedures

Compliance values were determined using the slopes of load displacement plots obtained when specimens were loaded in tensile test machines. Displacements were measured using clip gages spring loaded against integrally machined knife edges. Both clip gage and load cell were connected to an X-Y recorder to obtain the load-displacement graphs. For the 7075-T651 aluminum and 6A1-4V β A alloy DCB specimens, knife edges were located both at the end of the specimen and at the load line as shown in Figure B10. For all other specimens, knife edges were located only at the end of the specimens. When knife edges were located at the end of the specimen, load line displacements were calculated by multiplying end displacements by the ratio a/(a+1) where "a" is crack length and "1" is the distance from the load line to the end of the specimen. Load line displacements were divided by the corresponding load to calculate compliance values. Crack lengths were visually measured.

Results

Compliance measurements for the uniform height DCB specimens are plotted in Figures Cl and C2, and for the TDCB specimens in Figure C3. For the DCB specimens compliance values determined using deflections measured at the end of the specimen and the load line agreed very well. Furthermore, compliance values for the crack lengths less than 3.5 inches agreed with values calculated using




Figure C1: Compliance Values for 7075-7651 Aluminum and 9Ni-4Co-0.3C Steel Alloy Double Cantilever Beam Specimens




Figure C2: Compliance Values for 6AI-4V Standard ELI Beta Annealed and Recrystallize Annealed Titanium Alloys, Double Cantilever Beam Specimens




Figure C3: Compliance Values for 7075-T651 Aluminum, 6Al-4V Standard ELI Beta Annealed and Recrystallize Annealed Titanium Alloys, Taper Double Cantilever Beam Specimens

the semi-empirical relationship (1)*

$$C = \frac{2}{3E1} \left[(a + 0.6h)^3 + h^2 a \right]$$
 (C1)

where: C is specimen compliance, E is modulus of elasticity, 1 is moment of inertia of one of the specimen arms, a is crack length, and h is one half the specimen height. For crack lengths in excess of 3.5 inches, specimen compliance increased over those given by Equation C1 due to interaction effects between the crack and back specimen face.

Reference

1. S. Mostovoy, P. B. Crosley, and E. J. Ripling, "Use of Crack-Line-Loaded Specimens for Measuring Plane Strain Fracture Toughness", Journal of Materials, Vol. 2, No. 3, September 1967.

^{*} Numbers in parentheses refer to references at end of Appendix.

APPENDIX D CRYSTALLOGRAPHIC TEXTURE MEASURED BY X-RAY POLE FIGURES

Background

Each grain in a polycrystalline aggregate normally has a crystallographic orientation different from that of its neighbors (1)*. The orientations of all the grains may be randomly distributed in relation to some selected frame of reference, or they may tend to cluster, about some particular orientation or orientations. Any aggregate characterized by the latter condition is said to have a preferred orientation, or texture. Since most single cyrstals are anisotropic, i.e., have different properties in different directions, it follows that an aggregate of crystals having preferred orientation must also have directional properties.

Preferred orientation is best described by means of a pole figure. This is a sterographic projection which shows the variations in pole intensity with pole orientation for a selected set of crystal planes. Poles are the projection points onto a sphere of the normal to the crystallographic plane. The pole figure is a contour map of pole intensities plotted on polar coordinates showing the alignment of the selected set of planes as schematically shown in Figure D1.

A significant metallurgical technique developed for titanium characterization by Boeing was a quantitative, computerized pole figure analysis for determining the preferred orientation in titanium alloys. The technique was developed and modified over 4 years by Olsen (Ref. 2), and the following provides a brief description of the procedure. X-ray diffraction data are obtained using a modified Siemens texture geniometer, which is precisely aligned. Approximately 700 data points are taken. A computer program analyzes the data, subtracting for background and correcting for defocusing, and then plots a pole figure. The pole figure gives the isointensity lines of poles for a given crystallographic plane in terms of "times random intensity". This random intensity can be likened to taking all the data from a preferred titanium sample and spreading the data evenly over the entire pole figure, resulting in an average or a

^{*} Numbers in parenthese refere to references at end of Appendix.




Figure D1: Relationship of Basal Plane Poles in Titanium Plate and Resulting Pole Figure

"random" intensity. Most of the data obtained were for the basal (0002) plane, although some data were also obtained for the prismatic (1010) plane for the alpha phase in Ti-6Al-4V. Some data were also obtained for the (110) plane of the retained beta phase in Ti-6Al-4V.

Procedure

Using the complex 45° cut to form the specimen, data points are taken on a spiral with \emptyset changing 5° for every 360° change in α (See Figure D2). A total of 698 data points are recorded for each pole figure. Loss in intensity due to defocusing and absorption during tilting of the specimen is corrected by use of a random standard specimen.

After correction for absorption and defocusing, each data point is ratioed to the reading from a random sample. A code is then given to different intensity values in "times random" intensity (i.e., 1 = 0.5 times random, 2 = 1.0 times random, etc.). This code is reported immediately below the pole figure. Identical consecutive numbers are then connected to form contour lines on the pole figure via a plot program and an SC 4020 plotter. A typical pole figure is shown in Figure D3 with the polar coordinates superimposed over the pole figure.

The X-ray data used to plot the pole figure is also used to calculate elastic modulus for various directions and the percentage of plane intensity oriented in the longitudinal, transverse and short transverse directions. The percentages ($\%1_L$, $\%1_T$ & $\%1_{ST}$). These percentages provide quantitative values for the differences in plane orientation as related to the three primary directions.

References

- 1. Cullity, 3. D., Elements of X-Ray Diffraction, Addison-Wesley Publishing Company, Inc. (1957)
- 2. Olson, R. H. "Computer Plotting Pole Figure", Metallography 5, 369-371 (1972)




Figure D2: Method of Collecting Pole Figure Data




Figure D3: Example of a Bosal Plane Pole Figure for Titanium With Polar Coordinates
Superimposed